PANG SCOOTER SERVICE

Blk 1006 Bukit Merah Lane 2 #01-06, S'PORE 159763 Tel: (65) 62714618 Fax: (65) 62732632 Business Regn. No.10115500W (ESTAB. SINCE 1975)

Attn; Motor Claim Department							
Dear Si	Dear Sir/Madam						
ACCIDENT INVOLVING VEHICLE NO FBJ 4109T AND SMJ 6421Y ON 23/09/2021							
We ref	fer to the above matter as Direct S	Settlement					
1.	Cost Of Repair (LUMP SUM))	S\$	7,850.00			
2.	Loss Of Use (4 days x \$50.00)		S\$	200.00			
		TOTAL	S <u>\$</u>	8,050.00			
Please let us have your reply soonest possible.							
Thank	You.						
Your I	Faithfully						

PANG SCOOTER SERVICE

PANG SCOOTER SERVICE

Blk 1006 Bukit Merah Lane 2, #01-06, Singapore 159762

Tel: (65) 6271 4618

Fax: (65) 62732632

Business Regn. No. 10115500W

E-mail: pang s s m@singnet.com.sg

LETTER OF AUTHORISATION

Re: M	otor Cycle No:_	FDJ41091				
I,	SEET TAI HU	AT	(N	RIC NO	SXXXX 807	E) confirm
arrang payme	e costs of repairs gement was that the ent and I therefore ensation monies	he workshore e authorise	p was to con you to forwa	nplete repaird paymen	irs to my motor t, when you re	ceive the
						E INSURANCE OUCHER TO US.
I hav	e read and u	nderstood	the conte	nts of thi	s letter and	declare that
I kno	ow and am ful	lly aware	of the natu	ire and c	onsequence	of this letter.
	Dated this	3 OTH	day of	SEPT	202 \	
Signat Name	: Be	A Tai H	Tre t		Witnessed By Name	: Jason Chiany



INDIA INTERNATIONAL INSURANCE PTE LTD

Co. Reg. No. 198703792k | GST. Reg. No. M2-0078806-X 64 | Cecil Street | #04 | #05 | #06-02 | IOB Building | Singapore 04 Office (65) 63476100 Email insure@iii.com.sg Fax (65) 62244174 Website www.lii.com.sg

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref: MPC2021D0004157 Claimant Ref: FBJ 4109T

Well, PAN	G SCOOTER SERVICE ("the worksho	p") hereby confirm that	we/I have reached an agreement
with the appoint	ed Surveyor of India International Insurance Pte Lt	LKK AUTO CON	SULTANTS PTE LTD_(name
	h respect to the amount claimed for S\$ $\frac{7.8}{}$, and the same of
	- (search fee), vehicle noFBJ 4109T that		
on 23/09/202	1 (date) atTAMPINES EXPRESSWA	Y (location) invol	ving vehicle no. SMJ 6421(insured
vehicle). This is p	oursuant to the inspection conducted on 19/11/2021	_ (date) at "the workshop	o".
	at we/l are/am authorized by the owner		("the third party
	hicle no FBJ 4109 To make the claim as set out in		
the matter on h	is/her behalf in a manner that we/I deem fit. We/	l enclose herein the le	etter of authority given by "the third
party claimant".			
We/I further cor	nfirm that we/l will indemnify India International Ins	surance Pte Ltd for all	damages, loss and/or expense that
	ve already incurred in the event that "the third p		
	gainst the former for any loss and expenses suffe	-	of repairs and/or rental and/or loss
of use pursuant	to the damage to FBJ 4109T(vehicle no.) as a r	esult of the accident.	
We/I confirm th	at the agreement reached above is in full and f	inal settlement of all of	claims of "the third party claimant"
	accident and that further this settlement is reache		
basis.			
This agreement	is subject to the application of Singapore law and	the Singapore Courts h	nave exclusive jurisdiction over any
dispute arising o	ut of the same.		
Mall and and	you to pay the total amount of S\$ 7,970.00 to	PANG SCOOT	ER SERVICE
we/i authorize	to paythe total amount or \$\$to		
Dated this 18	day of		
	(5/0:10)		
CLAIMANT:	1 1 (2(5 孝 5) 5)	WITNESS:	((LKK))
0:	A MOSITION	,	MTH
Signature:	Signed by "the workshop" (with chop)	Signature:	Signed by appointed Surveyor
Name:	Jason Chiang	Name:	LKK AUTO CONSULTANTS PTE LTD
NRIC:	SXXXXONE	NRIC:	199607198R
Address:	BIK 1006 Bukit Merah Lane 2	Address:	51 UBI AVE 1 #01-25 PAYA LEBAR IND'
	*#01-06 s(159762)		SINGAPORE 408933
Nationality:	S'porean	Nationality:	
Occupation:	Admin.	Occupation:	

PANG SCOOTER SERVICE

Blk 1006 Bukit Merah Lane 2 #01-06 Singapore 159762

Tel: 6271 4618 Fax: 6273 2632

Business Regn. No. 10115500W

		INVOICE NO.	0005/2022
	FBJ 4109T		
Messer	INDIA INTERNATIONAL INSURANCE PL	Date	18/3/2022
		D.O.A.	23/9/2021
		MAKE/MODEL :	YAMAHA / R6
	Attached to LKK		

S/N	Description	Qty	Unit Price (S\$)	Total Price (S\$)	
	LUMP SUM COST OF REPAIR			\$	7,850.00
			TOTAL	\$	7,850.00

4/12/22, 4:12 PM Merimen e-Claims

Print Received Message

This mail is associated with:

*FBJ4109T (MPC2021D0004157) [SMJ6421Y]

KENNETH SEET JUN KIAT Sep 23 2021 8:00PM

[-] Pang Scooter Service

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 11/04/2022 17:29 PM.

То

Alert - Adj Mandate Approved (S\$8050.00) - FBJ4109T - Claim Handler: Zuhaidah Bte Samsuri Subject

Approved:8050.00.			