## PANG SCOOTER SERVICE

Blk 1006 Bukit Merah Lane 2 #01-06, S'PORE 159763 Tel: (65) 62714618 Fax: (65) 62732632 Business Regn. No.10115500W (ESTAB. SINCE 1975)

Attn; Motor Claim Department					
Dear Si	r/Madam				
ACCIDENT INVOLVING VEHICLE NO FBJ 4109T AND SMJ 6421Y ON 23/09/2021					
We refer to the above matter as Direct Settlement					
1.	Cost Of Repair (LUMP SUM)		S\$	7,850.00	
2.	Loss Of Use (4 days x \$50.00)		S\$	200.00	
		TOTAL	S <u>\$</u>	8,050.00	
Please let us have your reply soonest possible.					
Thank	You.				
Your F	aithfully				

PANG SCOOTER SERVICE

## PANG SCOOTER SERVICE

Blk 1006 Bukit Merah Lane 2, #01-06, Singapore 159762

Tel: (65) 6271 4618

Fax: (65) 62732632

Business Regn. No. 10115500W

E-mail: pang s s m@singnet.com.sg

## LETTER OF AUTHORISATION

Re: Motor Cycle No: FBJ 4104 T				
I, KENNETH SEET JUN KIRT that the costs of repairs have not been paid arrangement was that the workshop was to	by me to PA	NG SCOOTER SE	RVICE. The	
payment and I therefore authorise you to forward payment, when you receive the compensation monies from third party insurers, to PANG SCOOTER SERVICE.				

NOTE: WE WILL ONLY RELEASE THE MOTOR CYCLE ONCE INSURANCE COMPANY HAS FINALISE/RELEASE THEIR DISCHARGE VOUCHER TO US.

I have read and understood the contents of this letter and declare that I know and am fully aware of the nature and consequence of this letter.

Dated this 30Tm day of SEPT 2021

Signature Name

NRIC No

- V 1

807E

Witnessed By

Name

NRIC No

Jason Chiany

## **PANG SCOOTER SERVICE**

Blk 1006 Bukit Merah Lane 2 #01-06 Singapore 159762

Tel: 6271 4618 Fax: 6273 2632

Business Regn. No. 10115500W

		INVOICE NO.	0005/2022
	FBJ 4109T		
Messer	INDIA INTERNATIONAL INSURANCE PL	Date	18/3/2022
		D.O.A.	23/9/2021
		MAKE/MODEL :	YAMAHA / R6
	Attached to LKK	•	

S/N	Description	Qty	Unit Price (S\$)	Total Price (S\$)
	LUMP SUM COST OF REPAIR			\$ 7,850.00
			TOTAL	\$ 7,850.00