BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company Co. Reg. No. 197401559W GST Reg. No M2-0020081-x Toll-Free Number (1800-2255269)

303, Alexandra Road Sime Darby Performance Centre Singapore 159941 Fax. 64747770

- ESTIMATE REPAIR FOR -

280, Kampong Arang Road East Coast Centre

Singapore 438180 Fax. 63449773

315, Alexandra Road Sime Darby Business Centre Singapore 159944 Fax. 64796601 (AfterSal 64796624 (Motorrad

(AfterSales) (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No.

: b1 60051

: 18/11/2021

Date Estimated Prepared By

Tok Hock Seng

5001 Beach Rd

: Inthiran A/L Thurasamy

- ACCOUNT -66

MSIG Insurance (S) Pte Ltd

4 Shenton Way

#21-01 SGX Centre 2 Singapore 068807

Singapore 199588

REGN. NO.

#12-35

CHASSIS NO.

To remove and install IU unit bracket.

with BMW specification.

To mount accident vehicle on celette bench or Car-O-liner

to facilitate re-alignment of body / chassis accordance

REGN. DATE

MODEL

MILEAGE

31.00

2,950.00

Page No. : 1 of 7

SDV1235U	WBAXG12050DX48911 30/08/2012 520iA	112872
	DESCRIPTION	VALUE
	To replace front bumper,both fender, bonnet,wheel house strut left,knocking pulling both chassis.	14,450.00
	To painting front bumper, bonnet, both fender, both wheel house and front left door.	6,348.00
	To tow accident vehicle to PML workshop.	150.00
	To supply front emboss number plate.	83.00
	To remove and install engine and auto transmission to facilitate jacking of chassis and mounting of car on celette bench including to replace damaged parts.	1,652.00
	To replace radiator assembly, fan housing with fan including pressure test, bleed cooling system and conduct check for leak. (All models except 7 series).	826.00
	To replace charge air cooler including conduct check for leak and proper function.	531.00
	To check steering geometry and conduct wheel alignment in accordance with BMW specifications. (1x).	531.00
	To replace front windscreen glass.	574.00
	To conduct water leak tests.	75.00
	To supply and install front or rear windscreen solar film.	531.00

Performance Motors Limited

A Sime Darby Motors Company Co. Reg. No. 197401559W GST Reg. No M2-0020081-x Toll-Free Number (1800-2255269)

303, Alexandra Road Sime Darby Performance Centre Singapore 159941 Fax. 64747770 280, Kampong Arang Road East Coast Centre Singapore 438180 Fax. 63449773

315, Alexandra Road Sime Darby Business Centre Singapore 159944 Fax. 64796601 (AfterSal 64796624 (Motorrad

(AfterSales) (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. Page No. : 2 of 7 : b1 60051

Date Estimated : 18/11/2021

Prepared By : Inthiran A/L Thurasamy

I	REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
I	SDV1235U	WBAXG12050DX48911	30/08/2012	520iA	112872

SDV1235U	WBAXG12050DX48911 30/08/2012 520iA	112872
	DESCRIPTION	VALUE
	To replace front dashboard panel and conduct check for proper function.	797.00
	To remove and install battery cables including perform high current test and charge up battery.	531.00
	To remove and install fuse box at the front section to facilitate repair.	531.00
	To check electrical wiring system at the front section for proper function including adjustment of headlights.	177.00
· · · · · · · · · · · · · · · · · · ·	To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.	177.00
	To replace air con condenser and air con hose including vacuum system, top up freon gas and conduct check for leak. (For all models except for 7 series).	1,003.00
	To replace front or rear PDC sensor wire harness including reset and conduct check for proper function.	266.00
	To replace both front seat belts and tensioners including reset and conduct check for proper function.	531.00
	To replace roof top headlining and ITS head air bag including reset and conduct check for proper function.	684.00
	To replace front left door air bag including reset and conduct check for proper function.	531.00
	To replace front right door air bag including reset and conduct check for proper function.	531.00
	To carry out body cavity preservation. (Per panel).	354.00
	To carry out body cavity preservation. (For cut panel).	531.00
	Sundries.	150.00
l		

Total Labour 1:

35,526.00

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company Co. Reg. No. 197401559W GST Reg. No M2-0020081-x Toll-Free Number (1800-2255269)

303, Alexandra Road Sime Darby Performance Centre Singapore 159941 Fax. 64747770

280, Kampong Arang Road East Coast Centre Singapore 438180 Fax. 63449773

315, Alexandra Road Sime Darby Business Centre Singapore 159944 Fax. 64796601 64796624

(AfterSales) (Motorrad)



Page No. : 3 of 7

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 60051

Date Estimated : 18/11/2021

Prepared By : Inthiran A/L Thurasamy

REGN. NO. CHASSIS NO. REGN. DATE MODEL MILEAGE

CDV122511 MD3VC12AEADV40A11 20/00/2012 EAALX 112872

RADIATOR EXPANSION TANK FAN HOUSING WITH FAN 600W FAN HOUSING WITH FAN 600W SPORT STEERING WHEEL LEATHER SHIFT LH ENGINE HOOD HINGE FAT LH WHEEL HOUSING STRUT 1 893.30 FRI LH FENDER 1 893.30 FRI LH TENDER 1 893.30 FRI LH 1 SIDE PANEL BRACKET 1 35.30 BONNET LH GRILLE AIR INLET PARTLY CLOSED RH GRILLE AIR INLET PARTLY CLOSED RH GRILLE AIR INLET PARTLY CLOSED TET BUMPER CARRIER TRI BUMPER CARRIER TRI BUMPER CARRIER TRI BUMPER CARRIER TRI BUMPER H SPACER FRI BUMPER H SPACER FRI BUMPER H SPACER FRI BUMPER H SPACER FRI BUMPER H SPACER TRI BUMPER H TIMSHER TOD TRI BUMPER TOD TR	SDV1235U	WBAXG12050DX48911 30/08/2012	520iA	.,	112872
CHARGE AIR COOLER COVER (Radiator) AUXILIARY RADIATOR AUXILIARY RADIATOR 1 69.15 AUXILIARY RADIATOR 1 1,103,70 1 RADIATOR EXPANSION TANK 1 199.60 FAN HOUSING WITH FAN 600W 1 1,347.85 1 SPORT STERRING WHEEL LEATHER SHIFT 1 1,422.45 1 LH ENGINE HOOD HINGE 1 99.55 FRI LH WHEEL HOUSING STRUT 1 800.35 FRI LH WHEEL HOUSING STRUT 1 800.35 FRI LH SIDE PANEL BRACKET 1 893.30 FRI TH I SIDE PANEL BRACKET 1 35.30 FRI TH 1 SIDE PANEL BRACKET 1 35.30 BONNET 1 35.30 BONNET 1 35.30 BONNET 1 79.60 RH GRILLE AIR INLET PARTLY CLOSED 1 79.60 RH GRILLE AIR INLET PARTLY CLOSED 1 79.60 RH GRILLE AIR INLET PARTLY CLOSED 1 79.60 FRI BUMPER CARRIER 1 721.25 FRI BUMPER OFD IMPACT ABSORBER 1 100.00 FRI BUMPER BOTTOM MOUNT 1 165.95 FRI BUMPER H SPACER 1 26.25 FRI BUMPER IH SPACER 1 26.25 FRI BUMPER H SPA		DESCRIPTION	QTY	PRIC	VALUE
COVER (Radiator) AUXILIARY RADIATOR AUXILIARY RADIATOR EXPANSION TANK 1 1,103,70 1 RADIATOR EXPANSION TANK 1 199,60 FAN HOUSING WITH FAN 600W SPORT STEERING WHEEL LEATHER SHIFT 1 1,422,45 1 LH ENGINE HOOD HINGE 1 99,55 FRT LH WHEEL HOUSING STRUT 1 800,35 FRT LH WHEEL HOUSING STRUT 1 800,35 FRT LH SHOER FRT RH FENDER 1 893,30 FRT RH 1 SIDE PANEL BRACKET 1 35,30 FRT RH 1 SIDE PANEL BRACKET 1 79,60 FR H GRILLE AIR INLET PARTLY CLOSED 1 79,60 FR BUMPER CARRIER 1 721,25 FR TEUMPER CARRIER 1 721,25 FR TEUMPER TOP IMPACT ABSORBER 1 100,00 FR TEUMPER TOP IMPACT ABSORBER 1 100,00 FR TEUMPER BOTTOM MOUNT 1 165,95 FR TEUMPER LH SPACER 1 26,25 FR TEUMPER LH SPACER 1 26,25 FR TEUMPER RH SPACER 1 26,25 FR TEUMPER LH FINISHER ROD 1 33,05 COVERING PRIMEND LH 1 48,10 COVERING PRIMEND CH 1 48,10 GRILLE AIR INLET MIDDLE 1 79,60 FR TEUMPER LH FINISHER ROD 1 33,05 COVERING PRIMEND CH 1 48,10 GRILLE AIR INLET MIDDLE 1 79,60 FR TEUMPER THIM PRIMED (PDC) 1 1,357,90 1 1 LH GRILLE CHROME 1 142,15 BMW EMBLEM BZMM 1 71,95 FR BUMPER TRIM PRIMED (PDC) 1 1,357,90 1 1 LH GRILLE CHROME 1 142,15 BMW EMBLEM BZMM 1 71,95 FR THUMPER TRIM PRIMED (PDC) 1 1,357,90 FR THUMPER TRIMP PRIMED (PD		CHARGE AIR COOLER			616.25
RADIATOR 1 1,103.70 1		COVER (Radiator)			69.15
RADIATOR EXPANSION TANK FAN HOUSING WITH FAN 800W FAN HOUSING WITH FAN 800W SPORT STEERING WHEEL LEATHER SHIFT 1,422.45 1 HENGINE HOOD HINGE FRI LH WHEEL HOUSING STRUT 1,899.55 FRI LH FWHEEL HOUSING STRUT 1,899.55 FRI LH FENDER 1,893.30 FRI HI SIDE PANEL BRACKET 1,835.30 FRI HI SIDE PANEL BRACKET 1,35.30 BONNET 1,2348.55 2 HGRILLE AIR INLET PARTLY CLOSED 1,79.60 RH GRILLE AIR INLET PARTLY CLOSED 1,79.60 FRI BUMPER CARRIER 1,79.60 FRI BUMPER TOP IMPACT ABSORBER 1,100.00 FRI BUMPER HINDER SHACKER 1,262.5 FRI BUMPER HINDER SHACER 1,262.5 FRI BUMPER SHACER		AUXILIARY RADIATOR		1 662.25	662.25
RADIATOR EXPANSION TANK	Į	RADIATOR		1 1,103.70	1,103.70
FAN HOUSING WITH FAN 800W 1 1,347.85 1 SPORT STEERING WHEEL LEATHER SHIFT 1 1,422.45 1 LH ENGINE HOOD HINGE 1 99.55 FRT LH WHEEL HOUSING STRUT 1 800.35 FRT LH FENDER 1 893.30 FRT RH FENDER 1 893.30 FRT RH FENDER 1 893.30 FRT RH FENDER 1 85.30 FRT RH FENDER 1 35.30 FRT RH 1 SIDE PANEL BRACKET 1 35.30 FRT RH 1 SIDE PANEL BRACKET 1 35.30 FRT RH 1 SIDE PANEL BRACKET 1 2,348.55 2		RADIATOR EXPANSION TANK			199.60
SPORT STEERING WHEEL LEATHER SHIFT		FAN HOUSING WITH FAN 600W			1,347.85
LH ENGINE HOOD HINGE FRT LH WHEEL HOUSING STRUT FRT LH FENDER 1 893.30 FRT RH FENDER 1 893.30 FRT RH FENDER 1 1 893.30 FRT RH FENDER 1 1 893.30 FRT RH 1 SIDE PANEL BRACKET 1 35.30 BONNET 1 1 2,348.55 LH GRILLE AIR INLET PARTLY CLOSED 1 79.60 RH GRILLE AIR INLET PARTLY CLOSED 1 79.60 RH GRILLE AIR INLET PARTLY CLOSED 1 79.60 FRT BUMPER TOP IMPACT ABSORBER 1 100.00 FRT BUMPER BOTTOM MOUNT 1 165.95 FRT BUMPER BOTTOM MOUNT 1 165.95 FRT BUMPER LH SPACER 1 26.25 FRT BUMPER LH SPACER 1 26.25 FRT BUMPER H SPACER 1 26.25 FRT BUMPER LH FINISHER ROD 1 33.05 COVERING PRIMEND LH COVERING PRIMEND LH COVERING PRIMEND RH 1 48.10 COVERING PRIMEND RH GRILLE CHROME 1 142.15 BM WEMPER THIS PRIMED (PDC) LH GRILLE CHROME 1 142.15 BM WEMBILEN BZMM 1 71.95 RH LOCK BONNET PASSIVE BONNET CATCH OPERATOR 1 38.25 FRT WISCREEN 1 190.50 BONNET CATCH OPERATOR 1 38.25 FRT WISCREEN 1 1,087.10 1 38.25 FRT WISCREEN 1 1,087.10 1 38.25 FRT WISCREEN 1 1,087.10 1 3.393.00 3 SOUNDI INSULATION WINDSCREEN 1 1,148.50 1 TRIM PANEL DASHBOARD (CYSTER) 1 1,57,70		SPORT STEERING WHEEL LEATHER SHIFT		1 1,422.45	1,422.45
FRT LH FENDER FRT RH FENDER FRT RH FENDER FRT RH FISIDE PANEL BRACKET FRT RH 1 SIDE PANEL BRACKET BONNET BONNET 1 2,348.55 2 LH GRILLE AIR INLET PARTLY CLOSED 1 79.60 RH GRILLE AIR INLET PARTLY CLOSED 1 79.60 FRT BUMPER CARRIER 1 721.25 FRT BUMPER CARRIER 1 100.00 FRT BUMPER TOP IMPACT ABSORBER 1 100.00 FRT BUMPER HOP IMPACT ABSORBER 1 26.25 FRT BUMPER H SPACER 1 26.25 FRT BUMPER H FINISHER ROD 1 33.05 FRT BUMPER LH FINISHER ROD 1 148.10 COVERING PRIMEND LH COVERING PRIMEND LH 1 48.10 COVERING PRIMEND LH 1 48.10 GRILLE AIR INLET MIDDLE 1 79.60 FRT BUMPER THIM PRIMED (PDC) 1 1,357.90 1 LH GRILLE CHROME 1 142.15 BM WEMBLEM 82MM 1 71.95 RH LOCK BONNET PASSIVE 1 190.50 BONNET CATCH OPERATOR 1 38.25 FRT WSCREEN MOULDING 1 49.30 FRT WSCREEN MOULDING 1 49.30 FRT WSCREEN MOULDING 1 1,48.50 1 1,148.5		LH ENGINE HOOD HINGE		1 99.55	99.55
FRT RH FENDER		FRT LH WHEEL HOUSING STRUT		1 800.35	800.35
FRT LH 1 SIDE PANEL BRACKET 1 35.30 FRT RH 1 SIDE PANEL BRACKET 1 35.30 BONNET 1 2,348.55 2 LH GRILLE AIR INLET PARTLY CLOSED 1 79.60 RH GRILLE AIR INLET PARTLY CLOSED 1 79.60 FRT BUMPER CARRIER 1 721.25 FRT BUMPER TOP IMPACT ABSORBER 1 100.00 FRT BUMPER BOTTOM MOUNT 1 165.95 FRT BUMPER LH SPACER 1 26.25 FRT BUMPER LH SPACER 1 26.25 FRT BUMPER RH SPACER 1 26.25 FRT BUMPER RH SPACER 1 26.25 FRT BUMPER RH SPACER 1 26.25 FRT BUMPER LH FINISHER ROD 1 33.05 FRT BUMPER LH FINISHER ROD 1 33.05 COVERING PRIMEND LH 48.10 COVERING PRIMEND RH 1 48.10 GRILLE AIR INLET MIDDLE 1 79.60 FRT BUMPER TRIM PRIMED (PDC) 1 1,357.90 1 LH GRILLE CHROME 1 142.15 BMW EMBLEM 82MM 1 77.95 RH LOCK BONNET PASSIVE 1 190.50 BONNET CATCH OPERATOR 1 53.40 BOWDEN CABLE FRONT 1 42.05 LH LOCK BONNET PASSIVE 1 190.50 BONNET GAS STRUT 2 131.25 LEVER 1 38.25 FRT WISCREEN MOULDING 1 49.30 FRT WISCREEN MOULDING 1 1,087.10 11 FINIM PANEL DASHBOARD (OYSTER) 1 1,148.50 1 FRIM PANEL DASHBOARD (OYSTER) 1 1,148.50 1 FRIM PANEL DASHBOARD (OYSTER) 1 75.70		FRT LH FENDER		1 893.30	893.30
FRT RH 1 SIDE PANEL BRACKET		FRT RH FENDER		1 893.30	893.30
BONNET	j	FRT LH 1 SIDE PANEL BRACKET		1 35.30	35.30
LH GRILLE AIR INLET PARTLY CLOSED RH GRILLE AIR INLET PARTLY CLOSED RH GRILLE AIR INLET PARTLY CLOSED RH GRILLE AIR INLET PARTLY CLOSED FRT BUMPER CARRIER 1 79.60 FRT BUMPER CARRIER 1 721.25 FRT BUMPER TOP IMPACT ABSORBER 1 100.00 FRT BUMPER BOTTOM MOUNT 1 165.95 FRT BUMPER LH SPACER 1 26.25 FRT BUMPER LH SPACER 1 26.25 FRT BUMPER RH SPACER 1 26.25 FRT BUMPER RH SPACER 1 26.25 FRT BUMPER RH SPACER 1 33.05 COVERING PRIMEND H 1 48.10 COVERING PRIMEND H 1 48.10 GRILLE AIR INLET MIDDLE 1 79.60 FRT BUMPER TRIM PRIMED (PDC) 1 1,357.90 1 142.15 RH GRILLE CHROME 1 142.15 RH GRILLE CHROME 1 142.15 BMW EMBLEM 82MM 1 71.95 RH LOCK BONNET PASSIVE BONNET CATCH OPERATOR 1 42.05 LH LOCK BONNET PASSIVE BONNET CAST OPERATOR 1 38.25 FRT WISCREEN BONNET GAS STRUT 2 131.25 LEVER FRT WISCREEN 1 1,087.10 1 1,48.50 1 TIM PANEL DASHBOARD (OYSTER) 1 3,393.00 3 30.00 SOUND INSULATION WINDSCREEN 1 1,148.50 1 1,14		FRT RH 1 SIDE PANEL BRACKET		1 35.30	35.30
LH GRILLE AIR INLET PARTLY CLOSED RH GRILLE AIR INLET PARTLY CLOSED RH GRILLE AIR INLET PARTLY CLOSED FRT BUMPER CARRIER 1 721.25 FRT BUMPER CARRIER 1 100.00 FRT BUMPER BOTTOM MOUNT 1 165.95 FRT BUMPER LH SPACER 1 26.25 FRT BUMPER LH SPACER 1 26.25 FRT BUMPER HS SPACER 1 26.25 FRT BUMPER RH SPACER 1 26.25 FRT BUMPER LH FINISHER ROD 1 33.05 FRT BUMPER LH FINISHER ROD 1 33.05 FRT BUMPER LH FINISHER ROD 1 33.05 COVERING PRIMEND LH COVERING PRIMEND LH GRILLE AIR INLET MIDDLE 1 79.60 FRT BUMPER TRIM PRIMED (PDC) 1 1,357.90 1 LH GRILLE CHROME 1 142.15 BMW EMBLEM B2MM 1 71.95 RH LOCK BONNET PASSIVE 1 190.50 BONNET CATCH OPERATOR 1 38.25 FRT WSCREEN MOULDING FRT WSCREEN 1 1,087.10 BUMP STOP MOLDED ROOF LINING (OYSTER) 1 1,087.10 1 3,393.00 3 393.00 3 393.00 3 393.00 3 393.00 3 393.00 3 393.00 3 393.00 3 393.00 3 393.00 3 393.00 3 393.00 3 393.00 3 393.00 3 393.00 3 3		BONNET		1 2,348.55	2,348.55
FRT BUMPER CARRIER FRT BUMPER TOP IMPACT ABSORBER FRT BUMPER TOP IMPACT ABSORBER FRT BUMPER BOTTOM MOUNT 1 165.95 FRT BUMPER LH SPACER 1 26.25 FRT BUMPER LH SPACER 1 26.25 FRT BUMPER RH SPACER 1 26.25 FRT BUMPER RH SPACER 1 26.25 FRT BUMPER RH SPACER 1 33.05 FRT BUMPER LH FINISHER ROD 1 33.05 FRT BUMPER LH FINISHER ROD 1 33.05 COVERING PRIMEND LH COVERING PRIMEND RH GRILLE AIR INLET MIDDLE 1 79.60 FRT BUMPER TRIM PRIMED (PDC) 1 1,357.90 1 LH GRILLE CHROME 1 142.15 BMW EMBLEM 82MM 1 71.95 RH GRILLE CHROME 1 190.50 BONNET CATCH OPERATOR 1 190.50 BONNET CATCH OPERATOR 1 190.50 BONNET GAS STRUT 2 131.25 LEVER FRT W/SCREEN MOULDING FRT W/SCREEN 1 1,087.10 1 1,48.50 FRT W/SCREEN 1 1,087.10 1 1,48.50 FRT W/SCREEN 1 1,087.10 1 1,48.50 1 1,148.50		LH GRILLE AIR INLET PARTLY CLOSED			79.60
FRT BUMPER TOP IMPACT ABSORBER FRT BUMPER BOTTOM MOUNT 1 165.95 FRT BUMPER LH SPACER 1 26.25 FRT BUMPER LH SPACER 1 26.25 FRT BUMPER H SPACER 1 26.25 FRT BUMPER RH FINISHER ROD 1 33.05 FRT BUMPER LH FINISHER ROD 1 33.05 COVERING PRIMEND LH 1 48.10 COVERING PRIMEND LH 1 48.10 GRILLE AIR INLET MIDDLE 1 79.60 FRT BUMPER TRIM PRIMED (PDC) 1 1,357.90 1 LH GRILLE CHROME 1 142.15 RH GRILLE CHROME 1 142.15 BMW EMBLEM 82MM 1 71.95 RH LOCK BONNET PASSIVE 1 190.50 BONNET CATCH OPERATOR 1 190.50 BONNET CATCH OPERATOR 1 190.50 BONNET GAS STRUT 2 131.25 LEVER FRT W/SCREEN MOULDING FRT W/SCREEN 1 1,087.10 BUMP STOP MOLDED ROOF LINING (OYSTER) 1 1,48.50 1 1,148.50 1 1,		RH GRILLE AIR INLET PARTLY CLOSED		1 79.60	79.60
FRT BUMPER BOTTOM MOUNT FRT BUMPER LH SPACER FRT BUMPER LH SPACER FRT BUMPER RH SPACER FRT BUMPER LH FINISHER ROD FRT BUMPER TRIMED LH FRT BUMPER TRIMED LH FRT BUMPER TRIMED RH FRT BU		FRT BUMPER CARRIER		1 721.25	721.25
FRT BUMPER LH SPACER		FRT BUMPER TOP IMPACT ABSORBER		1 100.00	100.00
FRT BUMPER LH SPACER		FRT BUMPER BOTTOM MOUNT			165.95
FRT BUMPER LH SPACER FRT BUMPER RH SPACER FRT BUMPER RH SPACER FRT BUMPER RH SPACER FRT BUMPER LH FINISHER ROD FRT BUMPER LH FINISHER ROD FRT BUMPER LH FINISHER ROD TOVERING PRIMEND LH TOVERING PRIMEND RH FRT BUMPER TRIM PRIMED (PDC) FRT BUMP STOP FRT W/SCREEN BOULDING FRT W/SCREEN FRT W/SCREEN BOULDING FRT W/SCREEN FRT W/S		FRT BUMPER LH SPACER		1 26.25	26.25
FRT BUMPER RH SPACER FRT BUMPER RH SPACER FRT BUMPER LH FINISHER ROD FRT BUMPER LH FINISHER ROD THE BUMPER THIM PRIMED LH TOVERING PRIMEND RH TOVER RH TOVERING PRIMEND RH TOVER		FRT BUMPER LH SPACER			26.25
FRT BUMPER RH SPACER FRT BUMPER LH FINISHER ROD COVERING PRIMEND LH FOWNER FRIMEND RH FRE BUMPER TRIMEND RE TRIMEND FRE TRIME		FRT BUMPER RH SPACER			26.25
FRT BUMPER LH FINISHER ROD 1 33.05 FRT BUMPER LH FINISHER ROD 1 33.05 COVERING PRIMEND LH 1 48.10 COVERING PRIMEND RH 1 48.10 GRILLE AIR INLET MIDDLE 1 79.60 FRT BUMPER TRIM PRIMED (PDC) 1 1,357.90 1 LH GRILLE CHROME 1 142.15 RH GRILLE CHROME 1 142.15 BMW EMBLEM 82MM 1 71.95 RH LOCK BONNET PASSIVE 1 190.50 BONNET CATCH OPERATOR 1 53.40 BOWDEN CABLE FRONT 1 42.05 LH LOCK BONNET PASSIVE 1 190.50 BONNET GAS STRUT 2 131.25 LEVER 1 38.25 FRT W/SCREEN MOULDING 1 49.30 FRT W/SCREEN MOULDING 1 1,087.10 BUMP STOP 10 3.20 MOLDED ROOF LINING (OYSTER) 1 1,148.50 1 TRIM PANEL DASHBOARD (OYSTER) 1 3,393.00 SOUND INSULATION WINDSCREEN 1 75.70		FRT BUMPER RH SPACER			26.25
FRT BUMPER LH FINISHER ROD COVERING PRIMEND LH COVERING PRIMEND RH GRILLE AIR INLET MIDDLE FRT BUMPER TRIM PRIMED (PDC) LH GRILLE CHROME 1 142.15 RH GRILLE CHROME 1 142.15 BMW EMBLEM 82MM 1 71.95 RH LOCK BONNET PASSIVE BONNET CATCH OPERATOR BOWDEN CABLE FRONT LH LOCK BONNET PASSIVE BONNET GAS STRUT LEVER FRT W/SCREEN MOULDING FRT W/SCREEN MOLDED ROOF LINING (OYSTER) TRIM PANEL DASHBOARD (OYSTER) TRIM PANEL DASHBOARD (OYSTER) 1 38.30.0 SOUND INSULATION WINDSCREEN 1 3,393.00 3		FRT BUMPER LH FINISHER ROD			33.05
COVERING PRIMEND LH COVERING PRIMEND RH GRILLE AIR INLET MIDDLE FRT BUMPER TRIM PRIMED (PDC) LH GRILLE CHROME 1 142.15 RH GRILLE CHROME 1 142.15 BMW EMBLEM 82MM 1 71.95 RH LOCK BONNET PASSIVE BONNET CATCH OPERATOR BOWDEN CABLE FRONT LH LOCK BONNET PASSIVE 1 190.50 BONNET GAS STRUT 2 131.25 LEVER FRT W/SCREEN MOULDING FRT W/SCREEN MOLDED ROOF LINING (OYSTER) TRIM PANEL DASHBOARD (OYSTER) TRIM PANEL DASHBOARD (OYSTER) SOUND INSULATION WINDSCREEN		FRT BUMPER LH FINISHER ROD			33.05
COVERING PRIMEND RH 1 48.10 GRILLE AIR INLET MIDDLE 1 79.60 FRT BUMPER TRIM PRIMED (PDC) 1 1,357.90 1 LH GRILLE CHROME 1 142.15 RH GRILLE CHROME 1 142.15 BMW EMBLEM 82MM 1 71.95 RH LOCK BONNET PASSIVE 1 190.50 BONNET CATCH OPERATOR 1 53.40 BOWDEN CABLE FRONT 1 42.05 LH LOCK BONNET PASSIVE 1 190.50 BONNET GAS STRUT 2 131.25 LEVER 1 38.25 FRT W/SCREEN MOULDING 1 49.30 FRT W/SCREEN MOULDING 1 1,087.10 1 BUMP STOP 10 3.20 MOLDED ROOF LINING (OYSTER) 1 1,148.50 1 TRIM PANEL DASHBOARD (OYSTER) 1 3,393.00 3		COVERING PRIMEND LH			48.10
GRILLE AIR INLET MIDDLE 1 79.60 FRT BUMPER TRIM PRIMED (PDC) 1 1,357.90 1 LH GRILLE CHROME 1 142.15 RH GRILLE CHROME 1 142.15 BMW EMBLEM 82MM 1 71.95 RH LOCK BONNET PASSIVE 1 190.50 BONNET CATCH OPERATOR 1 53.40 BOWDEN CABLE FRONT 1 42.05 LH LOCK BONNET PASSIVE 1 190.50 BONNET GAS STRUT 2 131.25 LEVER 1 38.25 FRT W/SCREEN MOULDING 1 49.30 FRT W/SCREEN MOULDING 1 49.30 FRT W/SCREEN 1 1,087.10 1 BUMP STOP 10 3.20 MOLDED ROOF LINING (OYSTER) 1 1,148.50 1 TRIM PANEL DASHBOARD (OYSTER) 1 3,393.00 3 SOUND INSULATION WINDSCREEN 1 75.70		COVERING PRIMEND RH			48.10
FRT BUMPER TRIM PRIMED (PDC) LH GRILLE CHROME RH GRILLE CHROME BMW EMBLEM 82MM T1 71.95 RH LOCK BONNET PASSIVE BONNET CATCH OPERATOR BOWDEN CABLE FRONT LH LOCK BONNET PASSIVE BONNET GAS STRUT LEVER FRT W/SCREEN MOULDING FRT W/SCREEN MOLDED ROOF LINING (OYSTER) TRIM PANEL DASHBOARD (OYSTER) SOUND INSULATION WINDSCREEN 1 1,357.90 1 142.15 1 142.15 1 190.50 1 190.50 1 190.50 1 38.25 FRT W/SCREEN 1 1,087.10 1 1,087.10 1 1,148.50 1 1,148.50 1 3,393.00 3 300 3 300 5 300 3 300 300 5 300 300 300 5 300 300 300 5 300 300 300 300 5 300 300 300 300 5 300 300 300 300 5 300 300 300 300 5 300 300 300 300 5 300 300 300 300 5 300 300 300 300 5 300 300 300 300 5 300 300 300 300 5 300 300 300 300 5 300 300 300 300 5 300 300 300 300 5 300 300 300 300 5 300 300 300 300 5 300 300 300 300 5 300 300 300 300 5 300 300 300 300 5 300 300 300 300 5 300 300 300 300 5 300 300 300 300 5 300 300 5 300 300 5 300 300 5 300 300 5 300 300 5		GRILLE AIR INLET MIDDLE			79.60
LH GRILLE CHROME 1 142.15 RH GRILLE CHROME 1 142.15 BMW EMBLEM 82MM 1 71.95 RH LOCK BONNET PASSIVE 1 190.50 BONNET CATCH OPERATOR 1 53.40 BOWDEN CABLE FRONT 1 42.05 LH LOCK BONNET PASSIVE 1 190.50 BONNET GAS STRUT 2 131.25 LEVER 1 38.25 FRT W/SCREEN MOULDING 1 49.30 FRT W/SCREEN 1 1,087.10 1 BUMP STOP 10 3.20 MOLDED ROOF LINING (OYSTER) 1 1,148.50 1 TRIM PANEL DASHBOARD (OYSTER) 1 3,393.00 3 SOUND INSULATION WINDSCREEN 1 75.70		FRT BUMPER TRIM PRIMED (PDC)			1,357.90
RH GRILLE CHROME 1 142.15 BMW EMBLEM 82MM 1 71.95 RH LOCK BONNET PASSIVE 1 190.50 BONDEN CABLE FRONT 1 42.05 LH LOCK BONNET PASSIVE 1 190.50 BONNET GAS STRUT 2 131.25 LEVER 1 38.25 FRT W/SCREEN MOULDING 1 49.30 FRT W/SCREEN 1 1,087.10 1 BUMP STOP 10 3.20 MOLDED ROOF LINING (OYSTER) 1 1,148.50 1 TRIM PANEL DASHBOARD (OYSTER) 1 3,393.00 3 SOUND INSULATION WINDSCREEN 1 75.70		LH GRILLE CHROME			142.15
RH LOCK BONNET PASSIVE 1 190.50 BONNET CATCH OPERATOR 1 53.40 BOWDEN CABLE FRONT 1 42.05 LH LOCK BONNET PASSIVE 1 190.50 BONNET GAS STRUT 2 131.25 LEVER 1 38.25 FRT W/SCREEN MOULDING 1 49.30 FRT W/SCREEN 1 1,087.10 1 BUMP STOP 10 3.20 MOLDED ROOF LINING (OYSTER) 1 1,148.50 1 TRIM PANEL DASHBOARD (OYSTER) 1 3,393.00 3 SOUND INSULATION WINDSCREEN 1 75.70	1	RH GRILLE CHROME			142.15
BONNET CATCH OPERATOR 1 53.40 BOWDEN CABLE FRONT 1 42.05 LH LOCK BONNET PASSIVE 1 190.50 BONNET GAS STRUT 2 131.25 LEVER 1 38.25 FRT W/SCREEN MOULDING 1 49.30 FRT W/SCREEN 1 1,087.10 1 BUMP STOP 10 3.20 MOLDED ROOF LINING (OYSTER) 1 1,148.50 1 TRIM PANEL DASHBOARD (OYSTER) 1 3,393.00 3 SOUND INSULATION WINDSCREEN 1 75.70		BMW EMBLEM 82MM		1 71.95	71.95
BOWDEN CABLE FRONT 1 42.05 LH LOCK BONNET PASSIVE 1 190.50 BONNET GAS STRUT 2 131.25 LEVER 1 38.25 FRT W/SCREEN MOULDING 1 49.30 FRT W/SCREEN 1 1,087.10 1 BUMP STOP 10 3.20 MOLDED ROOF LINING (OYSTER) 1 1,148.50 1 TRIM PANEL DASHBOARD (OYSTER) 1 3,393.00 3 SOUND INSULATION WINDSCREEN 1 75.70		RH LOCK BONNET PASSIVE		1 190.50	190.50
LH LOCK BONNET PASSIVE 1 190.50 BONNET GAS STRUT 2 131.25 LEVER 1 38.25 FRT W/SCREEN MOULDING 1 49.30 FRT W/SCREEN 1 1,087.10 1 BUMP STOP 10 3.20 MOLDED ROOF LINING (OYSTER) 1 1,148.50 1 TRIM PANEL DASHBOARD (OYSTER) 1 3,393.00 3 SOUND INSULATION WINDSCREEN 1 75.70		BONNET CATCH OPERATOR		1 53.40	53.40
LH LOCK BONNET PASSIVE 1 190.50 BONNET GAS STRUT 2 131.25 LEVER 1 38.25 FRT W/SCREEN MOULDING 1 49.30 FRT W/SCREEN 1 1,087.10 1 BUMP STOP 10 3.20 MOLDED ROOF LINING (OYSTER) 1 1,148.50 1 TRIM PANEL DASHBOARD (OYSTER) 1 3,393.00 3 SOUND INSULATION WINDSCREEN 1 75.70		BOWDEN CABLE FRONT			42.05
LEVER 1 38.25 FRT W/SCREEN MOULDING 1 49.30 FRT W/SCREEN 1 1,087.10 1 BUMP STOP 10 3.20 MOLDED ROOF LINING (OYSTER) 1 1,148.50 1 TRIM PANEL DASHBOARD (OYSTER) 1 3,393.00 3 SOUND INSULATION WINDSCREEN 1 75.70		LH LOCK BONNET PASSIVE			190.50
LEVER 1 38.25 FRT W/SCREEN MOULDING 1 49.30 FRT W/SCREEN 1 1,087.10 1 BUMP STOP 10 3.20 MOLDED ROOF LINING (OYSTER) 1 1,148.50 1 TRIM PANEL DASHBOARD (OYSTER) 1 3,393.00 3 SOUND INSULATION WINDSCREEN 1 75.70		BONNET GAS STRUT		2 131.25	262.50
FRT W/SCREEN MOULDING 1 49.30 FRT W/SCREEN 1 1,087.10 1 BUMP STOP 10 3.20 MOLDED ROOF LINING (OYSTER) 1 1,148.50 1 TRIM PANEL DASHBOARD (OYSTER) 1 3,393.00 3 SOUND INSULATION WINDSCREEN 1 75.70		LEVER			38.25
FRT W/SCREEN 1 1,087.10 1 BUMP STOP 10 3.20 MOLDED ROOF LINING (OYSTER) 1 1,148.50 1 TRIM PANEL DASHBOARD (OYSTER) 1 3,393.00 3 SOUND INSULATION WINDSCREEN 1 75.70		FRT W/SCREEN MOULDING			49.30
BUMP STOP 10 3.20 MOLDED ROOF LINING (OYSTER) 1 1,148.50 1 TRIM PANEL DASHBOARD (OYSTER) 1 3,393.00 3 SOUND INSULATION WINDSCREEN 1 75.70		FRT W/SCREEN			1,087.10
MOLDED ROOF LINING (OYSTER) 1 1,148.50 1 TRIM PANEL DASHBOARD (OYSTER) 1 3,393.00 3 SOUND INSULATION WINDSCREEN 1 75.70		BUMP STOP	1		32.00
TRIM PANEL DASHBOARD (OYSTER) 1 3,393.00 3 SOUND INSULATION WINDSCREEN 1 75.70		MOLDED ROOF LINING (OYSTER)			1,148.50
SOUND INSULATION WINDSCREEN 1 75.70		TRIM PANEL DASHBOARD (OYSTER)			3,393.00
		· · · · · · · · · · · · · · · · · · ·			75.70
LH SUPPORT 1 30.80		LH SUPPORT			30.80
RH SUPPORT 1 30.80					30.80
CONNECTION TOP FRT 1 196.65					196.65
CONNECTION TOP REAR 1 357.85					357.85
LH HEADLAMP SUPPORT 1 221.85					221.85

Performance Motors Limited

A Sime Darby Motors Company Co. Reg. No. 197401559W GST Reg. No M2-0020081-x Toll-Free Number (1800-2255269)

303, Alexandra Road Sime Darby Performance Centre Singapore 159941 Fax. 64747770 280, Kampong Arang Road East Coast Centre Singapore 438180

315, Alexandra Road Sime Darby Business Centre Singapore 159944 Fax. 64796601 (AfterSal 64796624 (Motorrad



Page No. : 4 of 7

GST REG. NO: M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 60051

Date Estimated : 18/11/2021

Prepared By : Inthiran A/L Thurasamy

REGN. NO. CHASSIS NO. REGN. DATE MODEL MILEAGE SDV1235U WBAXG12050DX48911 30/08/2012 520iA 112872

DESCRIPTION	QTY	PRIC	VALUE
RH HEADLAMP SUPPORT	1	221.85	221.85
CROSS BRACE FRT LH	1	37.85	37.85
CROSS BRACE FRT RH	1	37.85	37.85
COVER WINDSCREEN PANEL	1	147.15	147.15
AIR DUCT	1	587.15	587.15
FRT RH AIR DUCT ENGINE OIL COOLER	1	68.35	68.35
LH AIR DUCT BRAKE	1	65.10	65.10
RH AIR DUCT BRAKE	1	65.10	65.10
ENGINE COMP. SHIELD UNDERRIDE PROT.	1	185.80	185.80
FRT LH LOCATOR SEAL	1	228.60	228.60
FRT RH LOCATOR SEAL	1	228.60	228.60
SEAL ENGINE BONNET FRT	1	39.25	39.25
WIRING SET PDC FRONT	1	159.50	159.50
LH BI-XENON HEADLIGHT	1	2,662.90	2,662.90
LH BI-XENON HEADLIGHT	1	2,662.90	2,662.90
HEADLIGHT DRIVER MOD AHL XENON LIGH	2	844.25	1,688.50
CONTROL UNIT XENON LIGHT	2	872.20	1,744.40
LH FOG LIGHT GLASS LENS	1	284.70	284.70
RH FOG LIGHT GLASS LENS	1	284.70	284.70
CONDENSER AIR CONDITIONING	1	1,038.75	1,038.75
DECOUPLING RING PDC TORQUE CONVERTE	4	5.15	20.60
BUMPER PDC SENSOR (SCHWARZ)	4	239.25	957.00
(DG) LH LOWER BELT TENSIONER	1	327.60	327.60
(DG) LH LOWER BELT TENSIONER	1	327.60	327.60
FRT RH UPPER BELT (OYSTER 71)	1	407.10	407.10
(DG) HEAD AIRBAG RH	1	697.00	697.00
(DG) AIR BAG MODULE F/PASSENGER SI	1	1,394.00	1,394.00
(DG) CLEANER R1 (100ML)	1	26.15	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	2	131.55	263.10
(DG/SL)ADHESIVE PRIMER VP 206 (30ML	1	27.85	27.85
	To	tal Parts	: 38,022.10

Labour 1 35,526.00 Parts 38,022.10 Labour 2 0.00 Excess 0.00 Total GST @ 7% 5,148.37

Grand Total

78,696.47

^{**} THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

^{**} PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

SP0121BF0006 / Performance Motors Limited ENTRY DATE & TIME: 15/11/2021 17:35 (SGT) SUBMITTED BY: Chan Sook Ling VERSION: 1 (15/11/2021 17:35 (SGT))



IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 5. Any false reporting may be referred to the Police for investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 15/11/2021 17:35 (SGT) Date of Accident 14/11/2021 08:15 (SGT)

Exact Location of Accident Singapore

Additional Location Information JUNCTION BETWEEN NORTH BRIDGE ROAD AND

PARLIAMENT PLACE

Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Private use

Private car

Yes

Auto

1997

No

Vehicle Registration Number SDV1235U

INSURED/POLICYHOLDER

Is company? No

Name Of Registered Owner **TOK HOCK SENG**

NRIC No SXXXX354J

Email Address TOKSIMONE@YAHOO.COM Mobile Phone No (Phone) +65-96798381

Alternative Phone No (Home) +--

VEHICLE PARTICULARS

Manufacturer **BMW** Model 520i

Variant Exact purpose for which vehicle was being used at time of

accident

DRIVER

Are you claiming under your own insurance policy for repair to

your vehicle? Vehicle Category Transmission

CC

INSURANCE COMPANY

Name of Insurance Company MSIG Insurance (Singapore) Pte. Ltd.

Type of Coverage Comprehensive

Fleet Policy

Policy Number B300349440SMP2021RN Cover Note Number

Name of Driver **TOK HOCK SENG**

Accident report SP0121BF0006

Page 1 of 34

NRIC No Date Of Birth Occupation Date Of Driving Pass Driving experience Gender Mobile Number Alt. Phone Number Email Address Address Address complement Postcode Is the driver the policyholder? If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver

SXXXX354J 18/10/1962 Indoor 11/12/1989 31 YEARS AND 11 MONTHS Male (Phone) +65-96798381 (Home) +--TOKSIMONE@YAHOO.COM 5001 BEACH ROAD #12-35

199588 Yes -No

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Weather Conditions Road Surface

Road Surface

OTHER INFORMATION

Was any foreign vehicle involved in the accident?
Number of vehicles involved in the accident
Was anybody injured in the Accident?
Was any injured conveyed to hospital by ambulance?
Was any other vehicle or property damaged?
Number of Passengers (Including Driver)
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?

PASSENGER 1

Name Gender

PASSENGER 2

Name Gender

DETAILS OF POLICE ACTION

Was the accident reported to the police?
Police Station Name
Police Station Phone No
Alt. Police Station Phone No
Police Station Address
Was notice of intended Prosecution given?
If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

SEE ATTACHED SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment? Was there any video captured by Car Camera? Was there any audio recorded?

Collision - Cross Junction

Clear Dry

No 2 Yes Yes

Yes 3

No

LEE PHEK NGOH

Female

DARREN TOK WEILE

Male

Yes Traffic Police (Phone) +65-65470000

(Fax) +65-65474900

10 Ubi Avenue 3 Singapore 408865

No

Yes No No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number **SLV2057R** Vehicle Manufacturer Honda Vehicle Model Vezel Vehicle Variant Vehicle Colour Blue Vehicle Category Private hire Name of Driver Contact Number Address Address complement Postcode Insurance Company Name Nature Of Damage Details of property damaged in accident No. Of Passenger (Including Driver)

INJURED PERSONS DETAILS

INJURED 1

Name of injured person

Gender

Phone No

LEE PHEK NGOH
Female

Address 5001 BEACH ROAD

Address Complement #12-35 GOLDEN MILE COMPLEX

Post Code 199588 Approximate Age Years Old 61

Injuries Sustained HAIR LINE CRACK ON TOE AND WRIST

Injured person in which vehicle? SDV1235U Were seat belts worn? Yes

Were seat belts worn?

Yes
Was this injured conveyed to hospital by ambulance?

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: /5 NOV 202

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Inthiran A/LThurasamy

Herformance Hotors Limited 303 Alexandra Road

 Darby Performance Centre Singapore 159941

SMRMC Shoot Heart or or VS

DESCRIBE CIRCUMSTANCES O	OF THE ACCIDENT	en e
- Refer to g	odier report.	
DECLARATION /		
DECLARATION I/We declare the foregoing particu	ars are true in every respect.	

SJARMESI GENYAM CON VS





Police Station Of Origin:

Traffic Police

10 Ubi Avenue 3 SINGAPORE 408865

Tel No: 65470000

1 of 4 Report No. T/20211114/7008

REPORT OF A TRAFFIC ACCIDENT

Date/Time 14/11/2021	•	ade:	Vide Report No.: A/20211114/0036	Station Diary No.:	
Informant'	s Particu	ılars			
Name of Informant: TOK HOCK SENG			Address: 5001 BEACH ROAD #12-35 SINGAPORE 199588		
ID Type / ID No.: NRIC NO / S2593354J			Contact No.: Home/Office:	Mobile: 96798381	
Nationality: MALAYSIAN			Email: TOKSIMONE@YAHOO.COM		
Sex: Age: Date of Birth: Male 59 18/10/1962			Type of Informant: Driver		
Race: Chinese			Language: English	Institution / School Name:	
Occupation Business d		ent manager	Driving Licence Information: Class: 3	Date of Expiry: 30/06/2003	

General Infor	mation of the Accident			
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 14/11/2021 08:15	Type of Location: cross junction
Location:				
NORTH BRID	OGE ROAD			
Weather: Clear		Road Surface: Dry		Road Speed Limit: 60 Km/h
Traffic Flow: One Way		Traffic Control: Traffic Light - Wor	king	Traffic Volume: Light
Type of Collis Between Mov	sion: ring Vehicles - Head To Si	de		Anyone conveyed by ambulance: Yes

Vehicle No.	Type	Make	Model	Color	Conditio	No of
SDV1235U	Car	BMW	520I 2.0L AT D/AB 2WD 4DR GAS/D	Black	Seriously Damaged	2

Details of Vehicle Insurance	
Vehicle No. Insurance Company Insurance No Effective	Expiry Date





Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000 2 of 4 Report No. T/20211114/7008

CONTINUATION OF REPORT

Details of V	ehicle Insurance			
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SDV1235U	MSIG INSURANCE (SINGAPORE)	300349440	01/09/2021	31/08/2022
	PTE. LTD.			

Details of Perso	n Involved						
Any Pedestrian I	nvolved: No				April 12 12 12 12 12 12 12 12 12 12 12 12 12		
				Use of Pedestrian Crossing: NA			
Driver							
Name	TOK HOCK SENG			ID No.		S2593354J	
Related Vehicle	SDV1235U (Car)			Contact No.		96798381	
Hospital/Clinic	SINGAPORE GENERAL HOSPITAL			Class of Driving Licence & Expiry		Class: 3 Date of Expiry: 30/06/2003	
Date	14/11/2021		Date			/2021	
No. of Days gran				:	Slight		
Passenger							
Name	DARREN TOK WEILE			ID No.		S9302550D	
Related Vehicle	SDV1235U (Car)			Conta	ct No.	81337866	
Hospital/Clinic	SINGAPORE GENERAL HOSPITAL			Class of Driving Licence & Expiry		Class: 3 Date of Expiry: NIL	
Date	14/11/2021		Date	14/11.		/2021	
	ted Medical Leave 01 Degree						
Passenger			32 (A.C. (A.C. (A.		vil vil vil		
Name	LEE PHECK NGOH		ID No.		S1407941F		
Related Vehicle	SDV1235U (Car)			Contact No.		96169811	
Hospital/Clinic	SINGAPORE GENERAL HOSPITAL			Class of Driving Licence & Expiry		Class: 3 Date of Expiry: NIL	
Date	14/11/2021		Date		14/11	/2021	
No. of Days gran	ted Medical Leave	07	Degree of	:	Slight		





Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000 3 of 4 Report No. T/20211114/7008

CONTINUATION OF REPORT

Brief Details.

I was driving along North Bridge Road heading towards the CBD area at about 815am today. While almost completing the crossing of the junction between North Bridge Road and High Street, I suddenly felt a huge bang/crash and all my airbags were deployed. It was only then I realised that I have collided with another vehicle. I would like to state that I am very certain that I have the right of way as it was a 'Green Light' and the collision was unexpected. The other vehicle (registered SLV2057R), seem to have beat the red light on his end which resulted in this collision. This happened very quickly and I had no time to react or respond. I am also travelling below the speed limit.

I do not have a in-car camera in my car however, the traffic police officers which attended to the scene had assure me that the CCTV facing the accident site from buildings nearby will aid in this investigation. The other vehicle has an in-car camera and the SD card was seized by the officers on site. There were several witnesses in the vicinity and they had also left their details with the officers on site.





Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000 4 of 4 Report No. T/20211114/7008

CONTINUATION OF REPORT

Sketch Plan					
Informant is	not	able	to	provide	sketc

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.					
Signature Of Interpreter: Not applicable	Date/Time: 14/11/2021 13:42					
Officer In Charge Of Case: TP / TPIB / SYED MUHAMMAD ISA BIN OMAR ALHABSHEE Contact No.: 65476214	Classification Of Case:					



MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way, #21-01, SGX Centre 2, Singapore 068807 Tel +65 6827 7888, Fax +65 6827 7800 Co.Reg No. 200412212G GST Reg. No. 20-0412212G

A Member of MSSAD INSURANCE GROUP

SIME MOTOR PRIVATE

RENEWAL CERTIFICATE

POLICYHOLDER INFORMATION

Name : Tok Hock Seng Date of Issue

: 27/08/2021

Address

Policy No. Account No. : B 300349440 SMP

: 5001 Beach Road

: 137

#12-35 Golden Mile Complex Singapore 199588

Scheme Code

: 212165 Period of Insurance: 01/09/2021 to 31/08/2022

Premium

: SGD1,316.77

(inclusive of GST)

RISK NUMBER 1

Insured Details

Registration No.

: SDV1235U

Year of Registration : 2012

Make/Model

: BMW 520I 2.0L AT

Capacity

: 1997 C.C.

Engine No.

: A1390162N20B20B

Seating Capacity

: 05 (Incl. Driver)

Chassis No.

: WBAXG12050DX48911

Off-peak Car

: No

Financial Interest

: United Overseas Bank Limited as Hire

Purchase Owners

Coverage Details

Type of Cover

: Comprehensive

Sum Insured

: Market Value at the Time of Loss

Windscreen

: Unlimited

NCD Protector

: Covered

No Claim Discount

: 50%

Good Driver Discount: 5%

Annual Premium

: SGD1,230.63

Excess

: SGD750 (Own Damage Excess)

Authorized Driver(s): Tok Hock Seng, Lee Phek Ngoh, Shaun Tok Weiyang, Darren Tok Weile

Any other person provided he is driving on the Policyholder's order or with the Policyholder's

permission.

Limitations As To Use: Use only for social domestic and pleasure purposes and for the Policyholder's business. The Policy does not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in

connection with the Motor Trade.

Clauses/Endorsements applicable to the above Risk

This Policy extends to include the following endorsements and clauses subject otherwise to the terms conditions and exceptions/exclusions of this Policy:

Gap Cover

In the event of a total loss of the Insured Vehicle covered under Section I of the Policy, and the market value for the Insured Vehicle payable under this Policy is below the outstanding bank loan (at the time of loss) secured by the Insured for the purchase of the Insured Vehicle, we will pay for the difference between the said market value and the outstanding bank loan, subject to the maximum of \$100,000.

Hire Purchase

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. \$2593354J





TOK HOCK SENG

鍁



Race CHINESE

MALAYSIA

Date of birth 18-10-1962

Country/Place of birth

\$2593354.1





th number of cent Licence Number: S 2 5 9 3 3 5 4 J

Name:

TOK HOCK SENG

Firth Date: 18 Oct 1962 fusue Date: 30 Jun 2003



9502376



MALAYSIAN Date of Issue 04-10-2018

5001 BEACH ROAD #12-35 SINGAPORE 199588 YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(I

PASS DATE

Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms Class 3

11 Dec 1989

Licence No: S2593354J

NP 428A