

Re: SJX5914K / OD / CHINA

Denise Tay (LKKAuto) <denisetay@lkkauto.com>

Mon 22/11/2021 3:12 PM

To: carcity@singnet.com.sg <carcity@singnet.com.sg>

Cc: SUR <sur@lkkauto.com>

Dear Mr Ho,
Resent

As instructed by our client , please proceed to repair the **insured vehicle SJX 5914K, (Excess \$0). LUMP SUM REPAIR**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: [6256-3561](tel:6256-3561) | email: denisetay@lkkauto.com | fax: [6256-4315](tel:6256-4315)

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAuto) <denisetay@lkkauto.com>**Sent:** Monday, 22 November 2021 2:50 pm**To:** carcity@singnet.com.sg <carcity@singnet.com.sg>**Cc:** SUR <sur@lkkauto.com>**Subject:** SJX5914K / OD / CHINA

Dear Edwin,

As instructed by our client , please proceed to repair the **insured vehicle SJX 5914K, (Excess \$0). LUMP SUM REPAIR**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: [6256-3561](tel:6256-3561) | email: denisetay@lkkauto.com | fax: [6256-4315](tel:6256-4315)

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)