

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 3042/11/21

Your Ref: _____

Date: 23rd NOV 2021

M/S MITSUBISHI HC CAPITAL ASIA PACIFIC PTE. LTD.
111, Somerset Rd, #14-05
Singapore 238164

SUPPLEMENTARY BILL For TOYOTA HARRIER SUV 2.0 (A) - SLS 6773 X

1 pc floor board panel spare tyre cushion sponge damper	285.20
1 pc rear n/s fender airscoop grille	172.90
1 pc rear n/s fender stopper	26.20

*for
twi
rel*

~~85~~ 100.58

Less 25%

\$ 484.30
\$ 121.08

\$ 363.22

=====

Dollars : Three Hundred Sixty Three And Cents Twenty Two Only.

HUP MOTOR TRADING & SERVICE

