



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
6 Benoi Place Singapore 629927
Tel: 6861 0908 Fax: 6515 2948

Date: 19.11.2021

Strides Taxi Pte Ltd
60 Woodlands Industrial Park E4
Singapore 757705

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO VEHICLE SHD2251M HONDA SHUTTLE
HYBRID (REGISTRATION DATE: 13.03.2017)

To Supply

1) 1pc	Tailgate / <i>DD</i>	\$	1,192.00 /
2) 1pc	Tailgate "H" emblem <i>X NN</i>	\$	38.00
3) 1pc	Tailgate "Shuttle" emblem <i>- MK</i>	\$	58.00 /
4) 1pc	Tailgate "Hybrid" emblem <i>- MK</i>	\$	75.00 /

Sub total parts	\$	1,363.00
Less: 20% discount	\$	(272.60)
	\$	1,090.40

1325
-20%
1060 -

To supply S.Nett Parts

1) 1pc	"Prime Taxi" sticker / <i>MK</i>	\$	55.00
2) 1pc	"Dial A Cab 6778 0808" sticker <i>X NN</i>	\$	45.00
3) 1tube	Glass sealant / <i>MK</i>	\$	40.00 /

Sub total S.Nett Parts \$ 140.00

95 -

L/charges

1) To tuff kote rear affected portion.	\$	50.00 <i>30</i>
2) To transfer tail gate trim board, handle, mechanism parts.	\$	80.00 <i>50</i>
3) To remove & refit rear glass.	\$	120.00 /
4) To repair rear bumper. Remove & replace tailgate. Align & adjust tailgate.	\$	500.00 <i>200</i>

5) To putty, respray painting tail gate's inlet & outer and rear bumper. To \$ 500.00 200

600 ✓

Sub total L/charges	\$ 1,250.00
Estimated Grand Total	\$ 2,480.40

= 1755

Prepared by: Chrissy Teo

L/S - 1404
= 1400

Steve (LKK)
8372 8813

WAL PL
3 dgs

L/S

MJ AL Sy

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: