

FASTECH AUTO PTE LTD
 1 Kaki Bukit Ave 6 #01-48 Autobay
 Singapore 417883
 Tel No: 67452063/ 67467158 Fax No: 67458520
 Tax Reg No : 200006262D

HSIAO Tang

Not Authorized
 Made
 28/10/21
 1/s \$5800
 5 days

VEHICLE No: SLC 6845G

1PC	REAR WINDSCREEN MOULDING	nee		\$110.20	✓
1PC	TAILGATE	Body ID		\$1,099.20	✓
1PC	TAILGATE 'VEZEL' EMBLEM	nee		\$66.80	✓
1PC	TAILGATE 'H' LOGO	11		\$45.00	X
1PC	TAILGATE OUTER HANDLE GARNISH	11		\$450.00	X
2PCS	TAILGATE REFLECTORS @\$386.20	11		\$772.40	X
1PC	TAILGATE INNER LOCK	but	180.20	\$199.80	✓
1PC	TAILGATE LOCK STRIKER	11		\$66.00	X
1PC	TAILGATE INNER TRIM BOARD	de/cne	242.30	\$435.00	✓
1SET	TAILGATE INNER TRIM BOARD CLIPS	nee		\$50.00	✓
1PC	TAILGATE WEATHERSTRIP	twl	162.30	\$288.00	✓
1PC	REAR BUMPER	de	762.20	\$980.00	✓
2PCS	REAR BUMPER SIDES @\$235.10	R		\$470.20	X
2PCS	REAR BUMPER REFLECTORS @\$151.00	11		\$302.00	X
1PC	REAR BUMPER UNDER COVER	de/torn	311.30	\$541.00	✓
1SET	REAR BUMPER UNDER COVER CLIPS	nee		\$50.00	✓
1SET	REAR BUMPER CLIPS	nee		\$50.00	✓
1PC	REAR END PANEL	DD	517.30	\$665.20	✓
1PC	REAR END PANEL TOP GARNISH	twl	122.60	\$341.10	✓
2PCS	TAILLAMPS @\$650.00	ms cne d/sun	482.00	\$1,300.00	1PC
2PCS	TAILLAMP HOUSING PANELS @\$350.00	R		\$700.00	X
1PC	REAR BUZZLE SENSOR	cne		\$98.00	✓
2PCS	REAR FENDERS @\$1090.00	R		\$2,180.00	X
2PCS	REAR FENDER OUTER PROTECTORS @\$380.00	de/torn	199.10x2=398.20	\$760.00	✓
2PCS	REAR FENDER INNER TRIM BOARDS @\$395.00	ms torn d/sun	366.20	\$790.00	1PC
1PC	REAR FLOOR PANEL	R		\$1,280.00	X
1PC	REAR FLOOR PANEL TOP BOARD	weped/torn	245.80	\$522.00	✓
1PC	REAR FLOOR PANEL TOP TRAY	Torn	450.50	\$585.00	✓
1PC	REAR EXHAUST	11		\$765.00	X
1PC	REAR EXHAUST HEAT SHIELD	11		\$108.00	X
				\$16,069.90	

S.NETT

1PC	REAR WINDSCREEN SEALANT	nee		\$50.00	40
1PC	REAR WINDSCREEN INNER SEAL	nee		\$50.00	40
1PC	REAR END PANEL SEALANT	nee		\$50.00	✓
1SET	REAR BUMPER REVERSE SENSOR	shoked		\$280.00	200
1SET	REAR FLOOR PANEL INSULATOR	11		\$120.00	X

TO CEHCK WIRING	\$50.00	20
TO DISMANTLE & REPLACED REVERSE SENSOR	\$80.00	50
TO DISMANTLE & REFX REAR WINDSCREEN	\$150.00	120
TO TRANSFER TAILGATE MECHANISM	\$100.00	60
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$120.00	80
TO RESET & REPROGRAMME DIAGNOSIS SYSTEM	\$180.00	50
TO DISMANTLE & REFIX REAR EXHAUST	✓ \$100.00	X
TO SPRAY RUST PROOFING	\$100.00	80
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$1,800.00	850
TO PUTTY & SPRAY PAINTING	\$1,500.00	1000
TOTAL	\$20,799.90	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

7-5765.60
20%
7-4612.48
S.N-330
L-2310
7252.48