

SJE :

 Vehicle Nos : **SKS 3957 P**

Date of Survey :

 Model : **TOYOTA PREVIA**

Date of ReSurvey:

After-Paint:

 Year : **2018**

Contacts :

 Chassis No : **JTEGD56MX07166152**
*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount:

Working Day:

2015

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	TAILGATE	1	\$ 2,145.00	\$ 1,324.00 2,145.00
2	TAILGATE LOGO	1	\$ 68.00	\$ ✓ 68.00
3	TAILGATE EMBLEM 'TOYOTA'	1	\$ 60.00	\$ 49.70 60.00
4	TAILGATE EMBLEM 'PREVIA'	1	\$ 68.00	\$ 51.60 68.00
5	TAILGATE OUTER CHROME GARNISH	1	\$ 294.80	\$ 240.90 294.80
6	TAILGATE INNER TRIM BOARD	1	\$ 584.10	\$ 384.10 584.10
7	TAILGATE INNER TRIM BOARD SIDE	2	\$ 182.00	\$ 364.00
8	TAILGATE INNER TRIM BOARD UPPER	1	\$ 195.00	\$ 195.00
9	TAILGATE INNER HANDLE	1	\$ 84.00	\$ 53.20 84.00
10	TAILGATE LAMP	2	\$ 338.40 581.60	\$ 676.80 1,163.20
11	TAILGATE LAMP CENTRE LAMP	1	\$ 477.00	\$ 179.34 477.00
12	TAILGATE WEATHERSTRIP	1	\$ 498.45	\$ 398.50 498.45
13	TAILGATE INNER LOCK	1	\$ 381.40	\$ ✓ 381.40
14	TAILGATE INNER LOCK MOTOR	1	\$ 589.45	\$ ✓ 589.45
15	TAILGATE INNER LOCK CATCH	1	\$ 32.10	\$ 32.10
16	TAILGATE LOCK STRIKER	1	\$ 58.00	\$ 58.00
17	TAILGATE SOLENOID SWITCH	1	\$ 475.80	\$ 475.80
18	TAILGATE LOCK SENSOR	2	\$ 186.00	\$ 372.00
19	TAILGATE WINDSCREEN MOULDING	1	\$ 287.20	\$ 160.00 287.20
20	TAILGATE WIPER ARM	1	\$ 141.00	\$ 141.00
21	TAILGATE WIPER MOTOR	1	\$ 891.60	\$ 891.60
22	TAILGATE HINGE	2	\$ 95.00	\$ 190.00
23	TAILGATE NUMBER PLATE LAMP	2	\$ 83.55	\$ 167.10
24	REAR BUMPER	1	\$ 1,287.10	\$ 847.80 1,287.10
25	REAR BUMPER SIDE RETAINER	2	\$ 48.20 144.00	\$ 96.40 288.00
26	REAR BUMPER SIDE RETAINER SIDE	2	\$ 132.00	\$ ✓ 264.00
27	REAR BUMPER REFLECTOR	LH 1	\$ 97.50	\$ 97.50 195.00
28	REAR BUMPER LOWER BRACKET	2	\$ 171.45	\$ 342.90
29	REAR BUMPER TOW CAP	LH 1	\$ 61.10	\$ 48.50 122.20
30	REAR BUMPER INNER SPONGE	1	\$ 186.00	\$ ✓ 186.00
31	REAR END PANEL INNER	1	\$ 984.70	\$ 688.60 984.70
32	REAR END PANEL OUTER	1	\$ 891.40	\$ 648.10 891.40
33	REAR END PANEL TOP GARNISH	1	\$ 389.00	\$ 277.85 389.00
34	REAR END PANEL INNER GARINSH	1	\$ 361.60	\$ 280.00 361.60

DDV

NECV

BRV

BRV

NDX

JMV

BRV

BRV

TNV

JMV

SCV

NDX

NDX

NDX

NDX

NECV

NDX

NDX

NDX

NDX

NDX

BRV

NECV

BRV

NSX

MISV

BRV

DDV

DDV

BRV

BRV

35	REAR WELL PANEL	1	\$	988.85	\$	680.00	988.85	DDV		
36	REAR WELL PANEL TRIM	1	\$	561.45	\$		561.45	NSX		
37	REAR WELL PANEL TOP COVER	1	\$	242.10	\$		242.10	NDX		
38	REAR FENDER	LH 1	2	\$	1,473.00	\$	1,450.00	2,946.00	DDV	
39	REAR FENDER INNER PANEL	LH 1	2	\$	810.30	\$	810.30	1,620.60	DDV	
40	REAR FENDER INNER TRIM BOARD	2	\$	700.00	\$		✓ 1,400.00	BRV		
41	REAR FENDER INNER COWLING	LH 1	2	\$	70.00	118.00	\$	70.00	236.00	TN ✓
42	REAR FENDER SIDE GLASS MOULDING	LH 1	2	\$	125.80	\$	125.80	251.60	NECV	
43	REAR FENDER AIR VENTS	1	\$	167.00	\$		167.00	NSX		
44	TAIL LAMP	2	\$	484.50	\$		✓ 969.00	BRV		
45	TAIL LAMP LOWER BRACKET	2	\$	84.00	\$		168.00	NSX		
46	TAIL LAMP BASE PANEL	LH 1	2	\$	293.50	499.80	\$	293.50	999.60	DDV
47	EXHAUST PIPE	1	\$	682.50	\$		682.50	} NSX		
48	EXHAUST PIPE MOUNTING	2	\$	42.50	\$		85.00			
49	REAR A/C COOLING COIL	1	\$	1,405.30	\$		1,405.30			
50	REAR A/C BLOWER MOTOR	1	\$	298.60	\$		298.60			
51	REAR A/C COOLING RUBBER PIPING	1	\$	849.60	\$		849.60	} BTV		
52	REAR TOOL BRACKET	1	\$	264.00	\$		✓ 264.00			
53	REAR TOOL TRAYS COVER	1	\$	445.60	\$		445.60	NSX		

Parts Sub Total : \$ 14,053.44 29,479.90

Discount 25% : \$ 3,513.36 7,369.98

PARTS TOTAL : \$ 10,540.08 22,109.93

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$		
1	SUNDRIES	1	\$	80.00	\$	80.00 NNX
2	TAILGATE SEALANT	1	\$	100.00	\$ 30.00	100.00 NECV
3	TAILGATE OUTER CHROME GARNISH CLIPS	1	\$	50.00	\$ 10.00	50.00 NECV
4	TAILGATE INNER TRIM BOARD CLIPS	1	\$	50.00	\$ 30.00	50.00 NECV
5	TAILGATE LAMP SEAL	2	\$	60.00	\$ 60.00	120.00 NECV
6	TAILGATE LAMP CLIPS	2	\$	50.00	\$ 30.00	100.00 NEW
7	TAILGATE CENTRE LAMP SEAL	1	\$	60.00	\$	60.00 NSX
8	TAILGATE WINDSCREEN SEALANT	1	\$	120.00	\$ 60.00	120.00 NECV
9	TAILGATE WINDSCREEN INNER SEAL	1	\$	60.00	\$	60.00 }
10	TAILGATE WINDSCREEN CLIPS	1	\$	50.00	\$	50.00 NNX
11	TAILGATE WINDSCREEN PRIMER AND CLEANER	1	\$	100.00	\$	100.00 }
12	REAR BUMPER CLIPS	1	\$	50.00	\$ 30.00	50.00 NECV
13	REAR BUMPER REVERSE SENSOR	4	\$	185.00	\$ 200.00	740.00 SC ✓
14	REAR END PANEL SEALANT	1	\$	100.00	\$ 30.00	100.00 NECV
15	REAR END PANEL TOP GARNISH CLIPS	1	\$	50.00	\$ 30.00	50.00 NECV
16	REAR WELL PANEL SEALANT	1	\$	100.00	\$ 30.00	100.00 NECV
17	TAIL LAMP SEAL	2	\$	60.00	\$ 40.00	120.00 }
18	TAIL LAMP CLIPS	2	\$	50.00	\$ 20.00	100.00 NECV
19	TAIL LAMP BASE PANEL SEALANT	LH 1	2	\$ 100.00	\$ 30.00	200.00 NECV
20	REAR NUMBER PLATE W/CASING	1	\$	80.00	\$ 30.00	80.00 NECV
21	REVERSE CAMERA	1	\$	480.00	\$ 300.00	480.00 DLV
SPECIAL NETT TOTAL :				\$ 960.00	2,910.00	

Nos.	LABOUR	S\$	
1	R&R TAILGATE COMPONENT	\$ 80.00	150.00
2	R&R TAILGATE WINDSCREEN	\$ 120.00	300.00
3	R&R REVERSE SENSOR	\$ 60.00	120.00
4	R&R REAR FENDER SIDE GLASS LH 1	\$ 80.00	500.00
5	R&R FUEL TANK PIPE	\$	150.00
6	R&R EXHAUST PIPE	\$	150.00
7	R&R REAR SEAT	\$ 80.00	400.00
8	R&R REAR A/C COLING COIL	\$	150.00
9	CHECK WIRING	\$ 30.00	80.00
10	MOUNT WORK BENCH	\$	350.00
11	CHASSIS ALIGNMENT	\$	300.00
12	UPHOLSTERY	\$	300.00
13	DIAGNOSTIC & RESET FAULT CODE	\$ 120.00	300.00
14	PANEL BEATING	\$ 1400.00	1,800.00
15	RUST PROOFING	\$	200.00
16	SPRAY PAINTING	\$ 1000.00	1,800.00
LABOUR TOTAL :		\$ 2970.00	7,050.00

Survey 22/11/2021
Resurvey 25/11/2021
Trim 143 hrs
Trim 145 hrs

PARTS TOTAL : \$ 22,109.93
SPECIAL NETT TOTAL : \$ 2,910.00
LABOUR TOTAL : \$ 7,050.00
GRAND TOTAL : \$ 32,069.93

Lump sum repair
Repair days 14

Parts 10,540.08
SN 960.00
Labour 2,970.00
14,470.08
@20% 2,894.02
11,576.06

LS 11,550/2 Trim 145
13/12/2021

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: