

CONNECT 3

566 Woodlands Road (Mandai Estate) Singapore 728697
Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

cecilia

Roc: 533600611

GST: 533600611

Steve (LKK)

24/11/21, 9.00am

WHL PL
L/S
M AL by
4 dys

QT21/CB6349J /TPC

AIG Asia Pacific Insurance Pte Ltd
CHARTIS Building
78 Shenton Way
#07-16
Singapore 079120

3173.90
-25%
P- 2380.42
N- 110
L- 770
3260.42

L/S -2608.333 QUOTATION
=2600

Dear Sir,

Cost of Repair to Vehicle CB6349J

With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (S\$)	AMOUNT (S\$)
1.	Front bumper / CUT	1	601.90	568 / 601.90
2.	Front bumper clips / MC	10	2.00	20.00
3.	Front LH headlamp / BR	1	734.40	734.40
4.	Front LH door / DD	1	1,887.10	1710 / 1,887.10
5.	Front LH step panel / CUT	1	161.50	161.50
6.	Transfer door fittings	1	150.00	50 150.00
7.	School bus sticker NEC	1	15.00	15.00
8.	Check wiring	1	20.00	20.00
9.	Spray painting	1	500.00	400 500.00
10.	Labour charges	1	900.00	300 900.00
SUB-TOTAL				S\$4,989.90

- Price before 7% gst

corner panel garish RH M - CUT \$75 nett

Thank you.

Yours faithfully,

Winnie Chai

HP: 9850-9666



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Scanned with CamScanner