

WEARNES AUTOMOTIVE PTE LTD

45 LENG KEE ROAD SINGAPORE 159103

Tel: +65 64304930 Fax: +65 6474 0853 www.ducatisingapore.com

Repair Estimate

Date	8 Dec 2021
Bike Number	FBS3609B
Chassis No.	ZDM1A00AAMB001860
Customer	Wearnes Automotive Pte Ltd
Address	
Email	

Model	MTSV4S	
Mileage		6,563
Contact		
Svc. No.		
Youtech		
Technician		

No.	Labour Code	Description	Qty	Unit Price	Amount
			0	\$1,200.00	
		Sub-Total			

No.	Part Number	Description	Qty	Unit Price	Amount
1		LAMP, LICENSE PLATE Shorted	1	\$59.70	\$59.70
2		SCREW NCC	4	\$0.90	\$3.60
3		SCREW Nec	5	\$2.30	\$11.50
4		VALVE, TUBELESS TIRE nec	1	\$21.30	\$21.30
5		WHEEL RUNNER BUSH 10C	6	\$22.90	\$137.40
6		SEAL RING nec	2	\$25.10	\$50.20
7		BEARING MeC	2	\$38.50	\$77.00
8		SCREW nec	4	\$1.40	\$5.60
9		SCREW TCEIF M6X25 1 CC	1	\$2.70	\$2.70
10		NUMBER PLATE BR	1	\$30.00	\$30.00
11					
		Sub-Total			\$399.00

^{1.} This estimate is compiled with visual inspection on the above mentioned motorcycle.

•	Grand Total:	\$426.93
Signature:	GST:	\$27.93
	Total Parts:	\$399.00
	l otal Labour:	\$0.00

^{2.} During the repair process, additional parts and labour may be required to complete the repairs works. A supplementary estimate shall be created accordingly.

^{3.} The undersigned signature represents the acceptance of this estimate and the permission to proceed with repair works.