



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 1008, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise In Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre
Hilton Auto Trading
Dealing In New/Used Cars, Hire Purchase & Insurance.



TP INSURER: India International Insurance Pte Ltd (HQ)
UNKNOWN

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	13/11/2021
Vehicle Reg. No.:	SLQ9561G	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	HONDA VEZEL HYBRID, 1.5 X (A)	Vehicle Reg. Date:	27/07/2017
Vehicle Colour:	BLACK	Chassis No:	RU31251332
Engine No:	LEB5951347		
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS	Amount
Parts	872.88
Miscellaneous Items	401.00
Labour	600.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	1,873.88
+ GST 7.00% (S\$)	131.17
Nett Amount (S\$)	2,005.05

This claim is handled by: KEONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS		
Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Nov 2021)
Parts:	M1-SUV	HONDA VEZEL HYBRID 1.5 x (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLQ9561G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	20.00	0.00	*829.40 FL
2	1		*REAR BUMPER SIDE LH	20.00	0.00	*195.20 FL
3	1		*REAR BUMPER SIDE BRACKET LH	20.00	0.00	*27.50 FL
4	10		*REAR BUMPER CLIPS	20.00	0.00	*39.00 FL
Sub Total (S\$)						1,091.10
- List Item Discount on L Items (S\$)						218.22
Total Parts (S\$)						872.88

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	REAR BUMPER STEP GARNISH	390.00
2	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			401.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO REMOVE & REFIX DAMAGED PARTS, STRAGHTEN & REALIGN AFFECTED AREAS	New	200.00
2	TO SPRAY AFFECTED AREAS	New	400.00
Gross Labour Cost (S\$)			600.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >