

SERVICE ESTIMATE

- C00001
 Wealthy Link Pte. Ltd.
 Atn: Mr. Lee Yeow Seng
 38 Beach Road
 #34-11 South Beach Tower
 Singapore 189767

SL: SERVICE SALES - PC

GST Reg.No: M28920628X

Inv.No. : B&P 0 Page 1
 Inv.date : 24/11/2021
 WIP No. : 56064
 Veh.In/Out:
 *Tel.No. :
 Reg.No. : SNA101X
 Reg.date : 17/03/2021
 Mileage : 0
 Chassis No: SCFSLGAW5KGN02848

Closed by : Juan Paulo Bongon Ba
 Svc Consultant :
 Remarks : WEALTHY LINK PTE. LT

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
302	TO REPLACE BONNET, FRONT BUMPER, RADIATOR GRILLE, FRONT BUMPER, LOWER SPOILER, HEADLAMP LH/RH, PARKING SENSORS, ETC	0		8000.00	0		8,000.00	S
	1611 X 4						6400	
300	TO SPRAY BONNET, FRONT BUMPER, FRONT SPOILER, ETC	0		5500.00	0	3900	5,500.00	S
	1399 X 2							
280	TO CHECK WIRING INCLUDE RESETTNG OF ALL ELECTRICAL MODULES	0		1020.00	0		1,020.00	S
280	TO FOCUS HEADLAMP	0		340.00	0		340.00	S
R06	NUMBER PLATE & HOLDER	0		120.00	0		120.00	S
NOTES	HEADLAMP LH/RH - NEED TO BE CHECK	0		0.00	0			S
	HOOD ASSEMBLY	1.0	EA	15392.50			15,392.50	S
	LATCH SECONDARY LH	1.0	EA	228.50			228.50	S
	STRKR SECONDARY	2.0	EA	100.70			201.40	S
	LATCH SECONDARY RH	1.0	EA	228.50			228.50	S

Stev (LKK)
 24/11/21, 3:39pm

ML ML
 P/P
 M B L M
 7 dys

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Wearnes Automotive Pte. Ltd.
 45 Leng Kee Road, Singapore 159103 T 6430 4700 www.wearnes.com

Signature: _____
 Co reg no: 199501400R / GST reg no: M28920628X
 Date: _____

SERVICE ESTIMATE

- C00001 SL: SERVICE SALES - PC
 Wealthy Link Pte. Ltd.
 Atn: Mr Lee Yeow Seng
 38 Beach Road
 #34-11 South Beach Tower
 Singapore 189767

GST Reg.No:M28920628X
 Inv.No. : B&P 0 Page 2
 Inv.date. : 24/11/2021
 WIP No. : 56064
 Veh.In/Out:
 *Tel.No. :
 Reg.No. : SNA101X
 Reg.date : 17/03/2021
 Mileage : 0
 Chassis No: SCFSLGAW5KGN02848

Closed by : Juan Paulo Bongon Ba
 Svc Consultant :
 Remarks : WEALTHY LINK PTE. LT

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	STRIKER- BONNET X nn ? x nn	2.0 EA	102.10			204.20	S
	FRT CTR PED LEG FOAM ? x nn	1.0 EA	235.20			235.20	S
	INTAKE FOAM LH UPPER ? x nn	1.0 EA	124.70			124.70	S
	INTAKE FOAM RH UPPER ? x nn	1.0 EA	124.70			124.70	S
	SCRIVET-PACK OF 5 / MC	5.0 EA	2.60	11.70		13.00	S
	FRT BMPR ASSY ROW / CRA	1.0 EA	5787.30	5208.57		5,787.30	S
	FRONT SPLITTER-BLACK / CUT (Black)	1.0 EA	4158.60	3742.74		4,158.60	S
	SCR M6 x 14 HD INT / MC	9.0 EA	2.60	21.06		23.40	S
	CLIP SPG M6 PK OF 10 / MC	10.0 EA	2.40	21.60		24.00	S
	WSHR 25mm x 6.4mm-10 / MC	2.0 EA	1.30	2.34		2.60	S
	BOLT M6x35 HEX / MC	2.0 EA	1.90	3.42		3.80	S
	SCREW-M6x20 PACK 20 / MC	20.0 EA	2.70	48.60		54.00	S
	RET GRILLE BMPR(10) / MC	10.0 EA	1.20	10.80		12.00	S
	LAMP ADJUSTER ? x nn	4.0 EA	73.00			292.00	S
	RAD GRILLE BLACK ? x nn	1.0 EA	3791.10			3,791.10	S
	FRONT CAMERA BEZEL / APC	1.0 EA	15.30	13.77		15.30	S
	HLDR CMR FRT FACING / MC	1.0 EA	32.80	29.52		32.80	S

SERVICE ESTIMATE

- C000001 SL: SERVICE SALES - PC

Wealthy Link Pte. Ltd.
 Attn: Mr. Lee Yeow Seng
 38 Beach Road
 #34-11 South Beach Tower
 Singapore 189767

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 3

Inv.date. : 24/11/2021

WIP No. : 56064

Veh.In/Out:

*Tel.No. :

Reg.No. : SNA101X

Reg.date : 17/03/2021

Mileage : 0

Chassis No: SCFSLGAW5KGN02848

Closed by : Juan Paulo Bongon Ba

Svc Consultant :

Remarks : WEALTHY LINK PTE. LT

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	IN-GRL PDC HOLDER LH <i>nc</i>	1.0 EA	9.90	8.91		9.90	S
	IN-GRL PDC HOLDER RH <i>nc</i>	1.0 EA	9.90	8.91		9.90	S
	SCRIVET-PACK OF 5 <i>nc</i>	20.0 EA	2.60	46.80		52.00	S
	SENSOR PARKING AID <i>1 x nn</i>	2.0 EA	106.40			212.80	S
	SENSOR PARKING AID <i>1 x nn</i>	2.0 EA	106.40			212.80	S
	SENSOR PARKING AID <i>x nn</i>	2.0 EA	113.80			227.60	S
	DECOUPLING RING <i>1 x nn</i>	6.0 EA	39.30			235.80	S
	FRT U/TRAY <i>1 x nn</i>	1.0 EA	1098.00			1,098.00	S
	UTRAY SPPRT BAR <i>1 x nn</i>	1.0 EA	1001.10			1,001.10	S
	CLIP SPG M6 PK OF 10 <i>nc</i>	10.0 EA	2.40	<i>nc</i>	2.16	24.00	S
	SCREW-M6x20 PACK 20 <i>nc</i>	20.0 EA	2.70	48.60		54.00	S
	BADGE ASSY AML <i>nc</i>	1.0 EA	1198.00	1078.20		1,198.00	S
	PNL H/LAMP MNT LH <i>1 x nn</i>	1.0 EA	2315.20			2,315.20	S
	PNL H/LMP MNT RH <i>1 x nn</i>	1.0 EA	2315.20			2,315.20	S
	BRKT HD/LP NUT PLT <i>nc</i>	2.0 EA	22.90	41.22		45.80	S
	AUX RAD DUCT RR LH <i>1 x nn</i>	1.0 EA	943.10			943.10	S
	AUX RAD DUCT RR RH <i>1 x nn</i>	1.0 EA	943.10			943.10	S

SERVICE ESTIMATE

- C00001 SL: SERVICE SALES - PC
 Wealthy Link Pte. Ltd.
 Attn: Mr. Lee Yeow Seng
 38 Beach Road
 #34-11 South Beach Tower
 Singapore 189767

GST Reg.No:M28920628X
 Inv.No. : B&P 0 Page 4
 Inv.date. : 24/11/2021
 WIP No. : 56064
 Veh.In/Out:
 *Tel.No. :
 Reg.No. : SNA101X
 Reg.date : 17/03/2021
 Mileage : 0
 Chassis No: SCFSLGAW5KGN02848

Closed by : Juan Paulo Bongon Ba
 Svc Consultant :
 Remarks : WEALTHY LINK PTE. LT

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	BUMPER SEAL / REC	2.0 EA	147.20	264.96		294.40	/
	PNL VNT AIR CTR LWR ? X nn	1.0 EA	592.70			592.70	S
	PNL RAD GRL CTR ? X nn	1.0 EA	1351.50			1,351.50	S
	SCREW&WSHR M6x20(10) - REC	10.0 EA	1.40	12.60		14.00	/
	PNL VEN AIR CTR UPR ? X nn	1.0 EA	555.70			555.70	S
	LWR FRT SPLITTER ? X nn	1.0 EA	1589.00			1,589.00	S
	PNL VEN AIR LH ? X nn	1.0 EA	741.40			741.40	S
	PNL VEN AIR RH ? X nn	1.0 EA	741.40			741.40	S
	RAD SUPPORT LWR ? X nn	1.0 EA	946.10			946.10	S

			Gross Total.	63,654.10
Labour Total	14,980.00	Net.....	63,654.10	
Parts Total	48,674.10	GST @ 7.0%	4,455.79	
Package Total	0.00	Total.....	68,109.90	
			Paid.....	0.00
			Please Pay..	68,109.90

GST: S=StdRated; O=OutOfScope; Z=ZeroRated