



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD 146 ROBINSON ROAD #02-01 UOI BUILDINGSINGAPORE 068909			Ref: CS/UOI21011917/Eqf3e2	
			Date: 14/03/2022	
			Code: UOI2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	YQ 2231B
	Policy No.	DHOM110173862001	Coverage (\$)	0.00
	Claim No.	M11D14172112	Excess (\$)	1,000.00
	Assign From	KATIE LEE	Assign Date	23/11/2021
2. Vehicle Particulars & Condition				
	Make & Model	mitsubishi canter feb21	c.c	2998
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	FEB21EA30351	Colour	WHITE
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15	DUNLOP	5 mm
	L/H Front Tyre	195 R15	DUNLOP	5 mm
	R/H Rear Tyre	195 R15	DUNLOP	5 mm
	L/H Rear Tyre	195 R15	DUNLOP	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	18/11/2021	Inspection Date	24/11/2021
	Survey held at	GOLDBELL ENGINEERING PTE LTD 10 TUAS AVE 18 SINGAPORE 638894		
5a. Remarks				
	A)THE MARKET VALUE IS S\$84,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		20 Working Days	