



ESTIMATE

Date	: 22/11/2021	Reg No	: YQ2231B
To	: UNITED OVERSEAS INSURANCE LIMITED	Model	: FEB21ER3SDEN CBU AMT
Attn.	:	Chassis No	: FEB21EA30351
Office / Mobile	:	Engine No	: 4P10D98051
Email Address	:	Quotation No.	: 145757
		Ref. No.	:
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 18/11/2021
Attn.	: LIEWSIMING	Policy No.	: DHOM110173862001
Office / Mobile	:	Claim Type	: OD CLAIM - UOI
Email / Fax No.	: LiewSiMing@goldbell.com.sg	Workshop	: 8 TUAS AVE 18

S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price
1		GLASS,WINDSHIELD	1	1,292.49	-25	969.37	969.37
2		WEATHERSTRIP,WINDSHIELD	1	761.98	-25	571.49	571.49
3		PILLAR,FR RH	1	1,981.92	-25	1,486.44	1,486.44
4		PILLAR,FR LH	1	1,981.92	-25	1,486.44	1,486.44
5		PANEL,WINDSHIELD,UPR	1	2,058.80	-25	1,544.10	1,544.10
6		PANEL ASSY,CAB,FR	1	3,368.03	-25	2,526.02	2,526.02
7		GARNISH,FR PANEL	1	533.55	-25	400.16	400.16
8		GRILLE,RADIATOR	1	1,015.46	-25	761.60	761.60
9		BRACKET,RADIATOR GRILLE,CTR	1	36.61	-25	27.46	27.46
10		BUMPER,FR	1	1,338.81	-25	1,004.11	1,004.11
11		COVER,FR BUMPER,RH	1	472.53	-25	354.40	354.40
12		STAY,FR BUMPER,RH	1	271.38	-25	203.54	203.54
13		COVER,FR BUMPER,LH	1	472.53	-25	354.40	354.40
14		STAY,FR BUMPER,LH	1	271.38	-25	203.54	203.54
15		HORN,ELECTRIC HIGH	1	227.69	-25	170.77	170.77
16		COVER,HORN	1	45.97	-25	34.48	34.48
17		MARK,THREE-DIA	1	114.78	-25	86.09	86.09
18		MARK,FUSO	1	214.33	-25	160.75	160.75
19		MARK,DUONIC LH	1	85.28	-25	63.96	63.96
20		MARK,DUONIC RH	1	85.28	-25	63.96	63.96
21		MARK,BLUETEC	2	58.90	-25	44.18	88.35
22		HEADLAMP ASSY,RH	1	664.48	-25	498.36	498.36
23		LAMP ASSY,TURN SIGNAL,FR RH	1	301.83	-25	226.37	226.37
24		GARNISH,HEADLAMP,RH	1	189.00	-25	141.75	141.75
25		HEADLAMP ASSY,LH	1	730.93	-25	548.20	548.20
26		LAMP ASSY,TURN SIGNAL,FR LH	1	308.91	-25	231.68	231.68
27		GARNISH,HEADLAMP,LH	1	189.00	-25	141.75	141.75
28		COVER,HEADLAMP BULB BACK	2	164.59	-25	123.44	246.89
29		BEZEL,HEADLAMP,LWR	2	20.32	-25	15.24	30.48
30		ARM,WINDSHIELD WIPER	1	164.97	-25	123.73	123.73
31		BLADE ASSY,WINDSHIELD WIPER	1	73.94	-25	55.46	55.46
32		TUBE ASSY,WINDSHIELD WASHER	1	114.45	-25	85.84	85.84
33		LINK,WINDSHIELD WIPER	1	888.17	-25	666.13	666.13



ESTIMATE

Date	: 22/11/2021	Reg No	: YQ2231B
To	: UNITED OVERSEAS INSURANCE LIMITED	Model	: FEB21ER3SDEN CBU AMT
Attn.	:	Chassis No	: FEB21EA30351
Office / Mobile	:	Engine No	: 4P10D98051
Email Address	:	Quotation No.	: 145757
		Ref. No.	:
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 18/11/2021
Attn.	: LIEWSIMING	Policy No.	: DHOM110173862001
Office / Mobile	:	Claim Type	: OD CLAIM - UOI
Email / Fax No.	: LiewSiMing@goldbell.com.sg	Workshop	: 8 TUAS AVE 18

S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price
34		MOTOR,WINDSHIELD WIPER	1	919.86	-25	689.90	689.90
35		BRACKET,WINDSHIELD WIPER MOTOR	1	157.92	-25	118.44	118.44
36		TANK,WINDSHIELD WASHER	1	222.74	-25	167.06	167.06
37		PANEL ASSY,FR DOOR,RH	1	2,160.90	-25	1,620.68	1,620.68
38		HINGE,FR DOOR,UPR RH	1	224.83	-25	168.62	168.62
39		HINGE,FR DOOR,LWR RH	1	224.83	-25	168.62	168.62
40		FENDER,SIDE,FR UPR RH	1	92.88	-25	69.66	69.66
41		WEATHERSTRIP,FR DOOR,LWR RH	1	114.53	-25	85.90	85.90
42		PANEL ASSY,FR DOOR,LH	1	2,029.63	-25	1,522.22	1,522.22
43		HINGE,FR DOOR,UPR LH	1	224.83	-25	168.62	168.62
44		HINGE,FR DOOR,LWR LH	1	224.83	-25	168.62	168.62
45		FENDER,SIDE,FR UPR LH	1	92.88	-25	69.66	69.66
46		WEATHERSTRIP,FR DOOR,LWR LH	1	114.53	-25	85.90	85.90
47		PANEL,CAB FR CORNER,RH	1	704.15	-25	528.11	528.11
48		SEAL,CAB FR CORNER PANEL,RH	1	51.19	-25	38.39	38.39
49		CAP,FR CORNER PANEL,RH	1	41.28	-25	30.96	30.96
50		PANEL,CAB FR CORNER,LH	1	704.15	-25	528.11	528.11
51		SEAL,CAB FR CORNER PANEL,LH	1	51.19	-25	38.39	38.39
52		CAP,FR CORNER PANEL,LH	1	45.40	-25	34.05	34.05
53		MIRROR,RR VIEW,RH	1	147.38	-25	110.54	110.54
54		COVER,RR VIEW MIRROR RH	1	26.78	-25	20.09	20.09
55		MIRROR,RR VIEW,LH	1	147.38	-25	110.54	110.54
56		COVER,RR VIEW MIRROR LH	1	26.78	-25	20.09	20.09
57		MIRROR,FR UNDER VIEW BLINDSPOT LH	1	85.66	-25	64.25	64.25
58		COVER,FR UNDER VIEW BLINDSPOT LH	1	33.48	-25	25.11	25.11
59		COVER,RR VIEW MIRROR STAY	2	19.25	-25	14.44	28.88
60		PANEL,FR SIDE SHIELD,UPR RH	1	96.98	-25	72.74	72.74
61		SEAL,CAB SPLASH SHIELD PANEL,RH	1	62.10	-25	46.58	46.58
62		PANEL,FR SIDE SHIELD,UPR LH	1	96.98	-25	72.74	72.74
63		SEAL,CAB SPLASH SHIELD PANEL,LH	1	62.10	-25	46.58	46.58
64		SILENCER,CAB FR FLOOR	1	21.48	-25	16.11	16.11
65		SILENCER,CAB FR FLOOR,FR	1	40.47	-25	30.35	30.35
66		SILENCER,CAB FR FLOOR,FR	1	26.38	-25	19.79	19.79



ESTIMATE

Date	: 22/11/2021	Reg No	: YQ2231B
To	: UNITED OVERSEAS INSURANCE LIMITED	Model	: FEB21ER3SDEN CBU AMT
Attn.	:	Chassis No	: FEB21EA30351
Office / Mobile	:	Engine No	: 4P10D98051
Email Address	:	Quotation No.	: 145757
		Ref. No.	:
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 18/11/2021
Attn.	: LIEWSIMING	Policy No.	: DHOM110173862001
Office / Mobile	:	Claim Type	: OD CLAIM - UOI
Email / Fax No.	: LiewSiMing@goldbell.com.sg	Workshop	: 8 TUAS AVE 18

S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price
67		SCUFF PLATE,FR RH	1	134.53	-25	100.90	100.90
68		SCUFF PLATE,FR LH	1	145.14	-25	108.85	108.85
69		STEP,FR SIDE,RH	1	409.05	-25	306.79	306.79
70		STEP,FR SIDE,LH	1	409.05	-25	306.79	306.79
71		CROSSMEMBER,CHASSIS FRAME	1	1,649.54	-25	1,237.16	1,237.16
72		CROSSMEMBER,FLOOR FR END	1	2,291.80	-25	1,718.85	1,718.85
73		REINFORCEMENT,FR FLOOR	1	901.48	-25	676.11	676.11
74		CROSSMEMBER,CAB FR MOUNTING	1	661.57	-25	496.18	496.18
75		BRACKET,CAB FR MOUNTING CROSSMEMBER,RH	1	1,144.10	-25	858.07	858.07
76		BRACKET,CAB FR MOUNTING CROSSMEMBER,LH	1	1,282.55	-25	961.91	961.91
77		CUSHION,CAB FR MOUNTING	2	309.10	-25	231.83	463.65
78		BUSHING,CAB FR MOUNTING	2	25.74	-25	19.31	38.61
79		LEVER,CAB FR MOUNTING ANCHOR	1	347.56	-25	260.67	260.67
80		TORSION BAR,CAB TILT	2	833.90	-25	625.43	1,250.85
81		HEATER ASSY	1	3,342.40	-25	2,506.80	2,506.80
82		PIPE,A/C COMPRESSOR DISCHARGE	1	146.06	-25	109.55	109.55
83		HOSE,A/C PIPING,NO.3	1	635.53	-25	476.65	476.65
84		PANEL ASSY,INSTRUMENT	1	2,834.30	-25	2,125.73	2,125.73
85		DUCT,FACE HEATER,RH	1	98.25	-25	73.69	73.69
86		DUCT,FACE HEATER CTR	1	400.37	-25	300.28	300.28
87		DUCT,FACE HEATER,LH	1	98.25	-25	73.69	73.69
88		GRILLE,INSTRUMENT PANEL SIDE AIR OUTLET OUTER	2	175.18	-25	131.39	262.77
89		GRILLE,INSTRUMENT PANEL SIDE AIR OUTLET RH	1	112.89	-25	84.67	84.67
90		GRILLE,INSTRUMENT PANEL SIDE AIR OUTLET LH	1	112.89	-25	84.67	84.67
91		BRACKET,INSTRUMENT PANEL RADIO	2	91.15	-25	68.36	136.73
92		BRACKET,INSTRUMENT PANEL RADIO	2	91.15	-25	68.36	136.73
93		LID,INSTRUMENT PANEL BRAKE FLUID RESERVOIR	1	19.25	-25	14.44	14.44
94		BEZEL,COMBINATION METER	1	206.08	-25	154.56	154.56
95		PANEL,I/PNL CENTER UPPER	1	291.74	-25	218.81	218.81



ESTIMATE

Date	: 22/11/2021	Reg No	: YQ2231B
To	: UNITED OVERSEAS INSURANCE LIMITED	Model	: FEB21ER3SDEN CBU AMT
Attn.	:	Chassis No	: FEB21EA30351
Office / Mobile	:	Engine No	: 4P10D98051
Email Address	:	Quotation No.	: 145757
		Ref. No.	:
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 18/11/2021
Attn.	: LIEWSIMING	Policy No.	: DHOM110173862001
Office / Mobile	:	Claim Type	: OD CLAIM - UOI
Email / Fax No.	: LiewSiMing@goldbell.com.sg	Workshop	: 8 TUAS AVE 18

S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price
96		FRAME,I/PNL PASSENGER	1	423.91	-25	317.93	317.93
97		FRAME,I/PNL DRIVER	1	241.35	-25	181.01	181.01
98		BRACKET,INSTRUMENT PANEL SIDE,LWR LH	1	182.26	-25	136.70	136.70
99		BRACKET,INSTRUMENT PANEL SIDE,LWR RH	1	139.64	-25	104.73	104.73
100		BOX,INSTRUMENT PANEL CONSOLE	1	343.31	-25	257.48	257.48
101		HOLDER ASSY,INSTRUMENT PANEL CONSOLE CUP	1	185.99	-25	139.49	139.49
102		PARCEL TRAY	1	65.18	-25	48.89	48.89
103		GLOVEBOX ASSY	1	397.64	-25	298.23	298.23
104		PANEL ASSY,INSTRUMENT,LWR CTR	1	763.29	-25	572.47	572.47
105		PANEL & INDICATOR ASSY,GEARSHIFT LEVER	2	306.41	-25	229.81	459.62
106		PANEL,INSTRUMENT DRIVER SIDE	1	59.27	-25	44.45	44.45
107		PANEL,INSTRUMENT ASSISTANT SIDE	1	503.23	-25	377.42	377.42
108		PANEL,INSTRUMENT ASSISTANT SIDE	1	111.17	-25	83.38	83.38
109		GARNISH,INSTRUMENT PANEL	1	406.06	-25	304.55	304.55
110		MODULE,AIR BAG	1	2,885.60	-25	2,164.20	2,164.20
111		CONTROL UNIT,AIR BAG	1	2,246.51	-25	1,684.88	1,684.88
112		BRACKET,AIR BAG CONTROL UNIT	1	282.45	-25	211.84	211.84
113		SEAT BELT,FR SEAT	1	1,088.88	-25	816.66	816.66

PARTS TOTAL : 46,293.46

SPECIAL NETT ITEMS

1	FREEZER BOX AIRCON PIPE COVER	1	350.00
2	FRONT NUMBER PLATE	1	25.00
3	IU BRACKET	1	25.00

PARTS TOTAL: 400.00



ESTIMATE

Date	: 22/11/2021	Reg No	: YQ2231B
To	: UNITED OVERSEAS INSURANCE LIMITED	Model	: FEB21ER3SDEN CBU AMT
Attn.	:	Chassis No	: FEB21EA30351
Office / Mobile	:	Engine No	: 4P10D98051
Email Address	:	Quotation No.	: 145757
		Ref. No.	:
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 18/11/2021
Attn.	: LIEWSIMING	Policy No.	: DHOM110173862001
Office / Mobile	:	Claim Type	: OD CLAIM - UOI
Email / Fax No.	: LiewSiMing@goldbell.com.sg	Workshop	: 8 TUAS AVE 18

LABOUR CHARGES

1	TO REMOVE AND REFIX FRONT WINDSCREEN	200.00
2	TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN,ETC	6000.00
3	TO CHECK FOR AND RECTIFY WIRING FAULTS, TO CONDUCT DIAGNOSTICS CHECK	200.00
4	TO TRANSFER DOOR COMPARTMENT / WINDOW GLASS / REGULATOR / LOCK / MECHANISM,ETC	400.00
5	REFIX AIRCON SYSTEM AND TOP UP GAS. TO CHECK FUNCTION	700.00
6	TO REMOVE AND TO REMOVE AND REFIX FRONT DASHBOARD	700.00
7	TO REMOVE & REFIX BRAKE PIPE ASSY / POWER STEERING TANK AND TO CHECK FUNCTION	400.00
8	TO REMOVE AND INSTALL MOBILEYE	400.00
9	TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC	3150.00

LABOUR TOTAL :	12,150.00
DISCOUNT AMOUNT :	-15278.83
SUB-TOTAL :	43,564.63
GST @ 7% for \$ 43,564.63	3,049.52
GRAND TOTAL (S\$) :	46,614.15



ESTIMATE

Date	: 22/11/2021	Reg No	: YQ2231B
To	: UNITED OVERSEAS INSURANCE LIMITED	Model	: FEB21ER3SDEN CBU AMT
Attn.	:	Chassis No	: FEB21EA30351
Office / Mobile	:	Engine No	: 4P10D98051
Email Address	:	Quotation No.	: 145757
		Ref. No.	:
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 18/11/2021
Attn.	: LIEWSIMING	Policy No.	: DHOM110173862001
Office / Mobile	:	Claim Type	: OD CLAIM - UOI
Email / Fax No.	: LiewSiMing@goldbell.com.sg	Workshop	: 8 TUAS AVE 18

PREPARED BY : LIEWSIMING

DATE / TIME : _____

SURVEYOR : _____

MOBILE NO : _____

OFFICE FAX NO : _____

EMAIL ADDRESS : _____

EXCESS AMOUNT : _____

REPAIR TYPE : PART-BY-PART / LUMPSUM

AUTHORISATION : AUTHORISED / NOT AUTHORISED

RE-SURVEY : BEFORE PAINT / AFTER PAINT

NO. OF DAYS : _____

REMARKS : _____