



UNITED OVERSEAS INSURANCE LIMITED
3 ANSON ROAD #28-01 SPRINGLEAF TOWER
SINGAPORE 079909
Attn: JANET XTN:375

TAX INVOICE

GST Reg No. : M9-0002514-E
Invoice No. : EXI00315966
Invoice Date. : 28-02-2022
Account No. : C00000427
Quotation No. : 145757
Work Order No. : 1191246
Service Centre. : 8 TUAS AVE 18

PARTICULARS

AMOUNT SGD

Reg No : YQ2231B
Chassis No : FEB21EA30351
Engine No : 4P10D98051
Model No : FEB21ER3SDEN CBU AMT
Mileage : 0
SRR No :

ACCIDENT REPAIR: GBE/SVC/SALES-HQ/03-2211
DATE OF ACCIDENT: 18/11/2021
POLICY NO: DHOM110173862001

*** OD CLAIM - UOI***

ITEM 1: TO REMOVE AND REFIX FRONT WINDSCREEN
ITEM 2: TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC
ITEM 3: TO CHECK FOR AND RECTIFY WIRING FAULTS, TO CONDUCT DIAGNOSTICS CHECK
ITEM 4: REFIX AIRCON SYSTEM AND TOP UP GAS. TO CHECK FUNCTION
ITEM 5: TO REMOVE AND TO REMOVE AND REFIX FRONT DASHBOARD
ITEM 6: TO REMOVE & REFIX BRAKE PIPE ASSY / POWER STEERING TANK AND TO CHECK FUNCTION
ITEM 7: TO REMOVE AND INSTALL MOBILEYE
ITEM 8: TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC
ITEM 9: TO SUPPLY MATERIAL & REALIGN FREEZER BOX

Parts/Materials:	Description	QTY	U/Price	%	Net Price	Ext Price
	PANEL ASSY,CAB,FR	1	3368.03	-25	2526.02	2526.02
	GARNISH,FR PANEL	1	533.55	-25	400.16	400.16
	HEADLAMP ASSY,RH	1	664.48	-25	498.36	498.36
	LAMP ASSY,TURN SIGNAL,FR RH	1	301.83	-25	226.37	226.37
	GARNISH,HEADLAMP,RH	1	189.00	-25	141.75	141.75
	LAMP ASSY,TURN SIGNAL,FR LH	1	308.91	-25	231.68	231.68
	GARNISH,HEADLAMP,LH	1	189.00	-25	141.75	141.75
	PANEL,CAB FR CORNER,RH	1	704.15	-25	528.11	528.11
	SEAL,CAB FR CORNER PANEL,RH	1	51.19	-25	38.39	38.39
	CAP,FR CORNER PANEL,RH	1	41.28	-25	30.96	30.96
	PANEL,CAB FR CORNER,LH	1	704.15	-25	528.11	528.11
	SEAL,CAB FR CORNER PANEL,LH	1	51.19	-25	38.39	38.39



Industrial Vehicles. Financial Services.
41,000 Served. And Counting.

Page 2 / 4

<u>Parts/Materials:</u>	<u>Description</u>	<u>QTY</u>	<u>U/Price</u>	<u>%</u>	<u>Net Price</u>	<u>Ext Price</u>
	CAP,FR CORNER PANEL,LH	1	45.40	-25	34.05	34.05
	COVER,FR UNDER VIEW BLINDSPOT LH	1	33.48	-25	25.11	25.11
	BRACKET,CAB FR MOUNTING CROSSMEMBER,RH	1	1144.09	-25	858.07	858.07
	BRACKET,CAB FR MOUNTING CROSSMEMBER,LH	1	1282.55	-25	961.91	961.91
	PANEL,INSTRUMENT DRIVER SIDE	1	59.27	-25	44.45	44.45
	PANEL,INSTRUMENT ASSISTANT SIDE	1	503.23	-25	377.42	377.42
	MODULE,AIR BAG	1	2885.60	-25	2164.20	2164.20
	CONTROL UNIT,AIR BAG	1	2246.51	-25	1684.88	1684.88
	SEAT BELT,FR SEAT	1	1088.88	-25	816.66	816.66
	GLASS,WINDSHIELD	1	1292.48	-25	969.36	969.36
	WEATHERSTRIP,WINDSHIELD	1	761.97	-25	571.48	571.48
	PANEL,WINDSHIELD,UPR	1	2058.80	-25	1544.10	1544.10
	GRILLE,RADIATOR	1	1015.45	-25	761.59	761.59
	BRACKET,RADIATOR GRILLE,CTR	1	36.60	-25	27.45	27.45
	BUMPER,FR	1	1338.80	-25	1004.10	1004.10
	COVER,FR BUMPER,RH	1	472.52	-25	354.39	354.39
	STAY,FR BUMPER,RH	1	271.37	-25	203.53	203.53
	COVER,FR BUMPER,LH	1	472.52	-25	354.39	354.39
	STAY,FR BUMPER,LH	1	271.37	-25	203.53	203.53
	MARK,THREE-DIA	1	114.77	-25	86.08	86.08
	MARK,FUSO	1	214.32	-25	160.74	160.74
	HEADLAMP ASSY,LH	1	730.92	-25	548.19	548.19
	ARM,WINDSHIELD WIPER	1	164.96	-25	123.72	123.72
	BLADE ASSY,WINDSHIELD WIPER	1	73.93	-25	55.45	55.45
	COVER,RR VIEW MIRROR RH	1	26.77	-25	20.08	20.08
	MIRROR,FR UNDER VIEW BLINDSPOT LH	1	85.65	-25	64.24	64.24
	CROSSMEMBER,CAB FR MOUNTING	1	661.56	-25	496.17	496.17
	CUSHION,CAB FR MOUNTING	2	309.09	-25	463.64	463.64
	BUSHING,CAB FR MOUNTING	2	25.73	-25	38.60	38.60
	TORSION BAR,CAB TILT	1	833.89	-25	625.42	625.42
	HEATER ASSY	1	3342.40	-25	2506.80	2506.80
	PANEL ASSY,INSTRUMENT	1	2834.29	-25	2125.72	2125.72
	LID,INSTRUMENT PANEL BRAKE FLUID RESERVOIR	1	19.24	-25	14.43	14.43
	PANEL ASSY,INSTRUMENT,LWR CTR	1	763.28	-25	572.46	572.46
	GARNISH,INSTRUMENT PANEL	1	406.05	-25	304.54	304.54



Industrial Vehicles. Financial Services.
41,000 Served. And Counting.

Page 3 / 4

<u>Parts/Materials:</u>	<u>Description</u>	<u>QTY</u>	<u>U/Price</u>	<u>%</u>	<u>Net Price</u>	<u>Ext Price</u>
	BRACKET,AIG BAG CONTROL UNIT	1	282.44	-25	211.83	211.83
	SENSOR,RR BRAKE PICKUP - LH	1	345.16	-25	258.87	258.87
	SENSOR,RR BRAKE PICKUP - RH	1	345.16	-25	258.87	258.87
	SPACER	2	32.52	-25	48.78	48.78
	SWITCH ASSY,COMBINATION	1	1330.87	-25	998.15	998.15
	HOSE,HEATER PIPING	1	32.24	-25	24.18	24.18
	HOSE,HEATER PIPING	1	29.28	-25	21.96	21.96
	PIPE,HEATER WATER	1	102.59	-25	76.94	76.94
	SHROUD,COOLING FAN	1	510.03	-25	382.52	382.52
	TANK,RADIATOR SURGE	1	276.08	-25	207.06	207.06
	HOSE,RADIATOR CONDENSER TANK	1	32.08	-25	24.06	24.06
	RESERVOIR ASSY,P/S OIL	1	774.32	-25	580.74	580.74
	LINK ASSY,CAB TILT STAY	1	397.24	-25	297.93	297.93
	LESS EXCESS: BORNE BY OWNER	-1	1000.00	0	-1000.00	-1000.00
	FRAME,I/PNL PASSENGER	1	423.91	-25	317.93	317.93
	BOOSTER ASSY, BRAKE	1	1800.89	-25	1350.67	1350.67
	Parts Charges :					30557.49
<u>SPECIAL NETT ITEMS</u>						
	FREEZER BOX AIRCON PIPE COVER	1				350.00
	FRONT NUMBER PLATE	1				25.00
	IU BRACKET	1				25.00
	Parts Charges :					400.00
<u>LABOUR CHARGES</u>						
	LABOUR CHARGES (REFER ITEM 1)					120.00
	LABOUR CHARGES (REFER ITEM 2)					4800.00
	LABOUR CHARGES (REFER ITEM 3)					180.00
	LABOUR CHARGES (REFER ITEM 4)					600.00
	LABOUR CHARGES (REFER ITEM 5)					600.00
	LABOUR CHARGES (REFER ITEM 6)					350.00
	LABOUR CHARGES (REFER ITEM 7)					350.00
	LABOUR CHARGES (REFER ITEM 8)					2450.00
	LABOUR CHARGES (REFER ITEM 9)					800.00



LABOUR CHARGES

Labour Charges : 10250.00

Sub Total : 41207.49

GST @ 7.00% for \$ 41207.49 2884.52

GRAND TOTAL (S\$) : 44092.01

Please make all cheques payable to GOLDBELL ENGINEERING PTE LTD.

When making payment, please quote our invoice numbers.

No receipts will be issued for Cheque Payments.

Terms and conditions of sales

Interest at 1.5% per month will be charged on overdue account

This is a computer generated document. No signature is required.