

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21011920/KRS3Q2**Date:** 15/02/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100442878
<b>Claimant Vehicle No :</b>	GBF1457D	<b>Insured Vehicle No :</b>	SKZ8899D
Date of Loss:	19/11/2021	Nature of Claim:	TP
		Claim No:	7256852049SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>GBF1457D</b>	Engine No:	K9KC400D055716
Make & Model:	NISSAN NV200, 1.5 (A)	Chassis No:	VSKYBAM20Z0129824
Reg. Date:	18/07/2016 (Man. Year: 2016)	Odometer:	71132 km
Colour:	Black		
Engine Capacity:	1461 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/70 R14	Rear Tyre Size:	175/70 R14
Front Left Side:	RACINGMAX 8 mm	Rear Left Side:	APLUS 9 mm
Front Right Side:	RACINGMAX 8 mm	Rear Right Side:	APLUS 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,156.00	2,072.56	2,083.44	50.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,220.00	970.00	1,250.00	56.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,376.00</b>	<b>3,042.56</b>	<b>3,333.44</b>	<b>52.28</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,400.00</b>		
<b>Nett Amount (S\$)</b>	<b>6,376.00</b>	<b>2,400.00</b>	<b>3,976.00</b>	<b>62.36</b>
<b>+ Car Rental (2.0 x S\$100.00/day) (S\$)</b>		200.00		
	<b>Nett Liability (S\$)</b>	<b>2,600.00</b>		

INSPECTION

Date of Assignment:	23/11/2021	
Date Inspected:	25/11/2021 Inspected At:	Ja Autocare Pte Ltd 8 KAKI BUKIT AVE 4, #02-37 PREMIER@KAKI BUKIT Singapore 415875
Estimated Period of Repair:	4.0 days	

**Adjuster:** KENNETH KONG**Manager:** Jaslin Kok Chin Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH DOOR	Bent	1,350.00 FL	*1,093.90 FL
2	1		*REAR RH DOOR HINGE	Dented	65.00 FL	*65.00 FL
3	1		*REAR BUMPER	Buckled	650.00 FL	*650.00 FL
4	1		*REAR BUMPER BRACKET RH	Serviceable	65.00 FL	*- FL
5	1		*REAR BUMPER RETAINER RH	Distorted	50.00 FL	*50.00 FL
6	1		*REAR BUMPER REINFORCEMENT	Repair	450.00 FL	*- FL
7	1		*REAR BUMPER CLIPS	Necessary	60.00 FL	*60.00 FL
8	1		*REAR FENDER RH	Repair	950.00 FL	*- FL
9	1		*TAIL LAMP ASSY	Cracked	550.00 FN	*289.50 FN
10	1		*DCI EMBLEM	Necessary	50.00 FN	*50.00 FN
11	1		*REVERSE SENSOR	Serviceable	280.00 FS	*- FS
12	1		*REAR WINDSCREEN SEALANT & CLIPS	Necessary	60.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

<b>Sub Total (\$)</b>	<b>4,580.00</b>	<b>2,298.40</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	364.00	191.89
<b>- Nett Item Discount on N Items 10.00/10.00% (\$)</b>	60.00	33.95
<b>Total Parts (\$)</b>	<b>4,156.00</b>	<b>2,072.56</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING	New	120.00	20.00
2	TO DISMANTLE & REFIX REAR RH WINDSCREEN GLASS	New	100.00	50.00
3	TO KNOCU OUT DENTS ON AFFECTED AREAS & RENEW PARTS	New	800.00	500.00
4	TO PUTTY & RESPRAY PAINTING	New	1,200.00	400.00
			<b>Gross Labour Cost (\$\$)</b>	<b>2,220.00</b>
				<b>970.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >