

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMX6857A

*Not Authorized
Respray B4 paint*

LAD2111-004

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration:

22 NOV 2021

SMX6857A

JTDKB3FU703091426

TOYOTA

PRIUS GEN 4

03/11/2021

CHINA

26/01/2021

PART	LIST	
1 COVER, REAR BUMPER	Bu	485.60 ✓
1 REINFORCEMENT SUB-ASSY, REAR BUMPER	BENT	332.70 ✓
1 COVER, REAR BUMPER, LOWER	su	22.00 X
1 GUARD, REAR BUMPER, CENTER	su	374.50 X
1 RETAINER, REAR BUMPER SIDE, LH	su	132.60 X
1 RETAINER, REAR BUMPER SIDE, RH	su	132.60 X
1 COVER, DECK TRIM, REAR	su	126.70 X
1 PANEL SUB-ASSY, BODY LOWER BACK	R	651.00 X
1 COVER, FRONT BUMPER	Bu	521.00 ✓
1 UNIT ASSY, HEADLAMP, LH	su	2,637.60 X
1 UNIT ASSY, HEADLAMP, RH	my cm	2,637.60 ✓
1 HOOD SUB-ASSY	Bu	983.10 ✓
1 HINGE ASSY, HOOD, LH	R	58.90 X
1 HINGE ASSY, HOOD, RH	R	58.90 X
1 LOCK ASSY, HOOD	R	135.00 X
1 BRACKET, FRONT BUMPER EXTENSION MOUNTING	R	110.50 X
1 REINFORCEMENT SUB-ASSY, FRONT BUMPER	R	716.60 ✓
1 ABSORBER, FRONT BUMPER ENERGY	R	80.20 ✓
1 GRILLE SUB-ASSY, RADIATOR	Red/CM	422.50 ✓
1 GRILLE, RADIATOR, LOWER NO.1	su	178.60 X
1 EMBLEM ASSY, RADIATOR GRILLE	mi	105.80 ✓
TOTAL	\$	10,904.00
25%	\$	2,726.00
	\$	8,178.00

Special Nett

1SET PARKING AID	\$	su 700.00 X
1 REAR SPOILER CLIP	\$	su 70.00 X

Trans-cab Auto Services Pte Ltd

LAD2111-004

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMX6857A

1SET REAR BUMPER CLIP	\$	Na	95.00	50SA
1 REAR BUMPER PROTECTOR	\$	na	180.00	X
1SET REAR BUMPER RETAINER CLIP	\$	na	85.00	X
1 END PANEL TRIM CLIP	\$	na	65.00	X
1SET BUMPER CLIP FRT	\$	na	95.00	50SA
1 FRONT NUMBER PLATE WITH MOULDING	\$	By	200.00	45SA
1 REAR NUMBER PLATE WITH MOULDING	\$	sn	200.00	X
1SET FRNT BUMPER RETAINER CLIP	\$	na	85.00	X
TOTAL	\$		1,775.00	

TOTAL PARTS \$ 9,953.00

LABOUR

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$	na	300.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	na	380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		2,200.00	6001
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	na	380.00	X
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	na	180.00	X
To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$	na	480.00	X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	na	480.00	X
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	na	380.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMX6857A

LAD2111-004

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i>	380.00	X
To check steering geometry and computer wheel alignment	\$	<i>nn</i>	220.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	<i>n</i>	250.00	<i>301</i>
Towing Fees	\$	<i>nn</i>	150.00	X
Putty And Spray Painting Of The Affected Portion.	\$		2,200.00	<i>6601</i>
To reinstall rear bumper parking sensor.	\$		170.00	<i>501</i>
To Check Electrical Lighting Concerned.	\$		170.00	<i>301</i>
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	<i>nn</i>	380.00	X
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i>	220.00	X
To replace, refix and top up coolant for radiator	\$	<i>nn</i>	170.00	X
To lift-up / out engine with gear box and refit.	\$	<i>nn</i>	440.00	X
To remove and refit radiator support cross-member and other necessary items to enable bodywork repair.	\$	<i>nn</i>	380.00	X
To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.	\$	<i>nn</i>	380.00	X
TOTAL	\$		10,290.00	

Over All Total \$ **20,243.00**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

(PART BY-PART) Repair Days

25 DAYS

9/2/21