

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 23 Nov 2021)**Parts:** 143 HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SH9249Z/23/11/2021 15:43**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BOOTLID COVER	20.00	0.00 Def	2,609.80 FL
2	1		*BOOTLID HINGE LH	20.00	0.00 SUC X ?	*142.30 FL
3	1		*BOOTLID HINGE RH	20.00	0.00 SUC X ?	*142.30 FL
4	1		*BOOTLID EMBLEM - I40	20.00	0.00 nec	*85.00 FL
5	1		*BOOTLID EMBLEM - CRDI	20.00	0.00 nec	*52.40 FL
6	1		*BOOTLID EMBLEM - H	20.00	0.00 nec	*63.10 FL
7	1		*BOOTLID COMFORTDELGRO LOGO	0.00	0.00 nec	*30.00 F
8	1		*BOOTLID TEL. NOS STICKER	0.00	0.00 nec	*30.00 F
9	1		*BOOTLID APPS LOGO	0.00	0.00 nec	*40.00 F
10	1		*REAR BUMPER ASSY	20.00	0.00 cut	*553.00 FL
11	10		*REAR BUMPER CLIPS	20.00	0.00 nec	*22.00 FL
12	1		*REAR BUMPER UNDER COVER	20.00	0.00 DIS	*228.00 FL
13	1		*REAR BUMPER SPONGE	20.00	0.00 cut	*119.50 FL
14	1		*REAR BUMPER REINFORCEMENT	20.00	0.00 cut	*428.40 FL
15	1		*REAR BUMPER MAT	0.00	0.00 nec	*50.00 F
16	1		*REAR BUMPER REFLECTOR RH	20.00	0.00 mis	*32.00 FL
17	1		*REVERSE SENSOR	0.00	0.00 cut	*135.70 F
18	1		*BOOTLID LAMP RH	20.00	0.00 SUC X ?	*622.20 FL
19	1		*BOOTLID LAMP LH	20.00	0.00 SUC X ?	*622.20 FL
20	1		*REAR BUMPER ADVERTISEMENT LOGO	20.00	0.00 nec	*50.00 FL
21	2		*REAR FENDER ADVERTISEMENT LOGO	20.00	0.00 nec	*200.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	6,257.90
- List Item Discount on L Items (\$\$)	1,194.44
Total Parts (\$\$)	5,063.46

ComfortDelGro Engineering Pte Ltd/SH9249Z/23/11/2021 15:43. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 1 OD/TP Case (Insurer)

11.00

Sub Total (S\$)

✓ 11.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1 PANEL BEATING

New

560 900.00

2 SPRAYPAINT

New

300 600.00

3 CHECK WIRING

New

20 50.00

4 TUFF KOTE

New

30 50.00

5 REMOVE/REFIX REVERSE SENSOR

New

30 80.00

Gross Labour Cost (S\$)

1,680.00

ComfortDelGro Engineering Pte Ltd/SH9249Z/23/11/2021 15:43. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Thuan@Lkh auto.com

82235769

24/11/21 1500

L/s after repair photo
3 days wp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: