

Our Job Ref No 305495531

Date : 26/11/2021

ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : THEVAN

: SH 9249Z

DOA: 23/11/2021

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO --- GBH9199K

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

Total for Part-By-Part Repair Cost

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20%

Final Lumpsum Repair cost


\$ 4050.00

3. Estimated normal period for repairs: 3 working days

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : JUMANI

Tel : 6214 8315

Fax : 65468156

Signature : 

Name : THEVAN

Date : 26/11/21

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	7.49 / 2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

(SUPPLEMENTARY)

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
KINIK INDUSTRIES PTE LTD

Singapore

Claimant Insurer: AXA Insurance Pte Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:	MS009843	Date of Loss:	23/11/2021
Vehicle Reg. No.:	SH9249Z	Driveable?	YES
Party At Fault:	UNKNOWN		
Driver (TP):	GOH PENG SOON	Driver (Insured):	DAI CHENGNA
Make/Model:	HYUNDAI I40, 1.7 D CRDI (A)	Vehicle Reg. Date:	20/12/2017
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	1KD2820059	Chassis No:	JTFAT35Y20K211398
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Description of Accident/Loss	ACCIDENT INVOLVING GBH9199K, SH9249Z & YP5014Y AT PIE TOWARDS TUAS AFTER ADAM EXIT		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	256.96
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	256.96
+ GST 7.00% (S\$)	17.99
Nett Amount (S\$)	274.95
+ Previous Estimates (S\$)	7,227.27
Claim Total (S\$)	7,502.22

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 26 Nov 2021)
Parts: 143 HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: ComfortDelGro Engineering Pte Ltd/SH9249Z/26/11/2021 16:22
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER REINFORCEMENT BRACKET RH	20.00	0.00	DT *160.60 FL ✓
2	1		*REAR BUMPER REINFORCEMENT BRACKET LH	20.00	0.00	DT *160.60 FL ✓
F=Franchise part. L=ListItemDisc.						
Sub Total (\$\$)						321.20
- List Item Discount on L Items (\$\$)						64.24
Total Parts (\$\$)						256.96

ComfortDelGro Engineering Pte Ltd/SH9249Z/26/11/2021 16:22. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

ComfortDelGro Engineering Pte Ltd/SH9249Z/26/11/2021 16:22. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Nov 2021)

Parts: 143 HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: **ComfortDelGro Engineering Pte Ltd/SH9249Z/23/11/2021 15:43**

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BOOTLID COVER	20.00	0.00 Def	2,609.80 FL
2	1		*BOOTLID HINGE LH	20.00	0.00 sec	*142.30 FL
3	1		*BOOTLID HINGE RH	20.00	0.00 sec	*142.30 FL
4	1		*BOOTLID EMBLEM - I40	20.00	0.00 nec	*85.00 FL
5	1		*BOOTLID EMBLEM - CRDI	20.00	0.00 nec	*52.40 FL
6	1		*BOOTLID EMBLEM - H	20.00	0.00 nec	*63.10 FL
7	1		*BOOTLID COMFORTDELGRO LOGO	0.00	0.00 nec	*30.00 F
8	1		*BOOTLID TEL. NOS STICKER	0.00	0.00 nec	*30.00 F
9	1		*BOOTLID APPS LOGO	0.00	0.00 nec	*40.00 F
10	1		*REAR BUMPER ASSY	20.00	0.00 cut	*553.00 FL
11	10		*REAR BUMPER CLIPS	20.00	0.00 nec	*22.00 FL
12	1		*REAR BUMPER UNDER COVER	20.00	0.00 DIS	*228.00 FL
13	1		*REAR BUMPER SPONGE	20.00	0.00 cut	*119.50 FL
14	1		*REAR BUMPER REINFORCEMENT	20.00	0.00 cut	*428.40 FL
15	1		*REAR BUMPER MAT	0.00	0.00 nec	*50.00 F
16	1		*REAR BUMPER REFLECTOR RH	20.00	0.00 mis	*32.00 FL
17	1		*REVERSE SENSOR	0.00	0.00 cut	*135.70 F
18	1		*BOOTLID LAMP RH	20.00	0.00 sec	*622.20 FL
19	1		*BOOTLID LAMP LH	20.00	0.00 sec	*622.20 FL
20	1		*REAR BUMPER ADVERTISEMENT LOGO	20.00	0.00 nec	*50.00 FL
21	2		*REAR FENDER ADVERTISEMENT LOGO	20.00	0.00 nec	*200.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	6,257.90
- List Item Discount on L Items (\$\$)	1,194.44
Total Parts (\$\$)	5,063.46

ComfortDelGro Engineering Pte Ltd/SH9249Z/23/11/2021 15:43. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 1 OD/TP Case (Insurer)

11.00

Sub Total (S\$)

✓ 11.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1 PANEL BEATING

New

560

900.00

2 SPRAYPAINT

New

500

600.00

3 CHECK WIRING

New

20

50.00

4 TUFF KOTE

New

30

50.00

5 REMOVE/REFIX REVERSE SENSOR

New

30

80.00

Gross Labour Cost (S\$)

1,680.00

ComfortDelGro Engineering Pte Ltd/SH9249Z/23/11/2021 15:43. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Thuan@LKH auto.com

82235769

24/11/21 1500

L/s after repair photo
3 days wp

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: