

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Neg. No. 13300713010 GG1 Neg. No. 13 300713010					
	Affiliated to Federation Internationale Des Experts En Automobile				
	AUTO & GENERA	L INSURANCE (S) PL	Ref:	CS/AGI21011928/Ktf3n2	
	(BUDGET DIRECT 190 CLEMENCEA SINGAPORE SHO 239924	TINSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Date	e: 15/12/2021	
			Cod	e: AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLN 1245M	Veh. Inspected	SKR 4343J	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10012583/EE	Excess (\$)	0.00	
	Assign From	IVY RATILLA	Assign Date	24/11/2021	
2.	2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA ALTIS (A)	c.c	1598	
	Engine No.	HIDDEN	Year of Reg.	2015	
	Chassis No.	MR053REH104526572	Colour	METALLIC GREY	
	Odometer	75697 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	205/55 R16	MICHELIN	8 mm	
	L/H Front Tyre	205/55 R16	MICHELIN	8 mm	
	R/H Rear Tyre	205/55 R16	MICHELIN	8 mm	
	L/H Rear Tyre	205/55 R16	MICHELIN	8 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	21/11/2021	Inspection Date	24/11/2021	
	Survey held at ALAN'S UNITED AUTO PTE LTD				
		BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.		Estimate Days of Repair			

6 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: