



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE KIA PTE LTD

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

### ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
HOE KEE KOK	Cust No/Name	LCV14625/HOE KEE KOK
106 GERALD DRIVE	Reg No/Reg Date	SDV7000R / 12/10/202
#01-11	Date In/Mileage	/ 0
SINGAPORE 798595	Chassis No	KNAD6817VN6617641
Contact No	Engine No	G3LEMP192652
	Make/Model	KIA/STONIC 1.0 A PE E02R
	Colour/Trim	URG URBAN GREEN / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LCV14625	CRDVCH	24/11/2021/ 11:16	BLC	442 / CocoLu	42850			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								1200.00
RENEW FRT BUMPER, BONNET,								
E PNT98000								700.00
SPRAY PAINT FOR FRT BUMPER, BONNET								
A 90000001								30.00
CHECK WIRING & ELECTRICAL SYSTEM								
A 10028901								120.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								
M SUNDRY								50.00
FRT NUMBER PLATE WITH FRAME								
M SUNDRY								20.00
Sundry								
M SUNDRY								
EMBLEM-KIA -- 86300H8400								
M SUNDRY								
PANEL ASSY-HOOD -- 66400H8430								
M COVER-FR BUMPER UPR					1.00	476.00	00.00	476.00
M COVER-FR BUMPER,LWR					1.00	367.00	00.00	367.00
M GRILLE-FRONT BUMPER					1.00	247.00	00.00	247.00
M AIR DUCT-FR BUMPER,RH					1.00	38.00	00.00	38.00
M GRILLE ASSY-RADIATOR					1.00	324.00	00.00	324.00
M CAP-FRONT HOOK					1.00	5.00	00.00	5.00
M SKID PLATE-FR BUMPER					1.00	55.00	00.00	55.00
M LIP-FR BUMPER					1.00	42.00	00.00	42.00
M STRIP-FR BUMPER					1.00	27.00	00.00	27.00
M COVER-RADIATOR GRILLE UPR					1.00	46.00	00.00	46.00
M MOULDING-FRONT BUMPER A/INTAKE					1.00	61.00	00.00	61.00
M ABSORBER-FRONT BUMPER ENERGY					1.00	98.00	00.00	98.00
M COVER-BLANKING FRT FOG,RH					1.00	28.00	00.00	28.00
M STIFFNER-FR BPR LWR					1.00	123.00	00.00	123.00
M BRACKET-FR BUMPER SIDE,RH					1.00	13.00	00.00	13.00
M BEAM COMPLETE-FR BUMPER					1.00	544.00	00.00	544.00
M LATCH ASSY-HOOD					1.00	101.00	00.00	101.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

## ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
HOE KEE KOK  106 GERALD DRIVE #01-11 SINGAPORE 798595  Contact No	Cust No/Name	LCV14625/HOE KEE KOK
	Reg No/Reg Date	SDV7000R / 12/10/202
	Date In/Mileage	/ 0
	Chassis No	KNAD6817VN6617641
	Engine No	G3LEMP192652
	Make/Model	KIA/STONIC 1.0 A PE E02R
	Colour/Trim	URG URBAN GREEN / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LCV14625	CRDVCH	24/11/2021/ 11:16	BLC	442 / CocoLu	42850		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
M	GARNISH ASSY-FNDR SIDE,RH			1.00	45.00	00.00	45.00
M	GUARD ASSY-FRONT WHEEL,RH			1.00	56.00	00.00	56.00
M	LAMP ASSY-HEAD,RH			1.00	1845.00	00.00	1845.00
M	HORN ASSY-LOW PITCH			1.00	64.00	00.00	64.00
M	RESERVOIR & PUMP ASSY-WASHER			1.00	152.00	00.00	152.00
M	GUARD-AIR			1.00	23.00	00.00	23.00
Estimate							

Confirm & accepted by

	Nett	6,900.00
7% GST on	6900.00	483.00
Total Payable		7,383.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.