

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

24-Nov-21

Our ref : TP/5057/21

Teo Soon Seng

TP Budget Direct
Veron.

RE : estimate cost for vehicle no :SMG 7878Y

1 pc	frt bumper	Red	\$	1,970.00	✓
4 pcs	frt bumper parking sensor	2 pieces damaged		1,272.00	636.
1 pc	frt bumper sponge	Red		115.00	✓
1 pc	frt no plate holder	Red		113.00	✓
1 pc	frt grille	Red		880.00	✓
2 pcs	headlamp	LH 2x Red		4,456.00	2228.
1 pc	frt bumper reinforcement	new		1,685.00	+
1 pc	frt bumper centre grille	lit	8069	120.00	✓
1 pc	rear bumper	Red		2,007.00	✓
4 pcs	rear bumper reverse sensor	new	7262.10	1,272.00	+
1 pc	frt bumper reinforcement	new		835.00	x.
				14,725.00	
			less 10%	1,472.50	
				13,252.50	
1 pc	frt no plate	Red 40		40.00	snett -
Panel beating.				1,000.00	500
Spray painting.			1130	1,000.00	600
Wiring.				30.00	✓
				15,322.50	
			Plus 7% GST	1,072.58	
				16,395.08	

SD : Sixteen thousand three hundred ninety-five & cents eight only.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Adrian Lj
h/s 24/11/21.

05 Pays.

blnd : 8432.10

L/S : 67K