

# AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047  
TEL: 6483 1244 ( 4 lines ) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg  
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : ABDUL RAHMAN BIN SALLEH  
BLK 192 PUNGGOL CENTRAL #06-311  
  
SINGAPORE 820192

Estimate No: MC1902300  
Date: 23 Nov 2021  
Policy No: P10470571R00  
Veh Reg No: SLV2355E  
Make/Model: TOYOTA C-HR TURBO  
1.2 S-T CVT

ATTN:

Your Ref No: -  
Claim Type: Third Party  
Accident Date: 21/11/2021  
TP Veh Reg No: SMH5901X

## Estimate Repair Cost to Vehicle No :SLV2355E

Description	Quantity	List Price S\$	Amount S\$
<b>SPARE PARTS</b>			
1 REAR WINDSCREEN MOULDING SIDE LH & RH	2 PC	91.60	
2 REAR WINDSCREEN MOULDING LOWER	1 PC	68.20	
3 TAILGATE	1 PC	1,020.30	
4 TAILGATE EMBLEM	1 PC	66.20	
5 TAILGATE CHR LOGO	1 PC	45.60	
6 REAR BUMPER	1 PC	568.20	
7 REAR BUMPER SIDE RETAINER LH & RH	2 PC	204.40	
8 REAR BUMPER CLIPS	10 PC	45.00	
9 REAR BUMPER LOWER GARNISH	1 PC	411.90	
10 REAR BUMPER REFLECTOR COVER RH	1 PC	95.80	
11 REAR BUMPER TOW COVER	1 PC	23.70	
12 REAR BUMPER REINFORCEMENT	1 PC	332.70	
		2,973.60	
	Less 25%	743.40	2,230.20
<b>Special Nett</b>			
13 SEALANT	1 PC	40.00	
14 REAR BUMPER CHROME MOULDING LH & RH -CHECK PRICE	2 PC	0.0000	
15 REAR BUMPER REVERSE SENSOR	2 PC	200.00	
		240.00	240.00
<b>LABOUR</b>			
16 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	
17 TO REMOVE & REFIT REAR WINDSCREEN	1 EA	120.00	
18 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	80.00	
19 TO DISMANTLE ALL DAMAGED PARTS. TO KNOCK & REPAIR END PANEL, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	600.00	
20 TO SPRAY TAILGATE, REAR BUMPER, END PANEL	1 PC	600.00	
		1,440.00	1,440.00

# AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047  
TEL: 6483 1244 ( 4 lines ) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg  
GST:M9-0009639-E RCB NO:06470300B

M/S : ABDUL RAHMAN BIN SALLEH  
BLK 192 PUNGGOL CENTRAL #06-311  
  
SINGAPORE 820192

ATTN:

Your Ref No: -  
Claim Type: Third Party  
Accident Date: 21/11/2021  
TP Veh Reg No: SMH5901X

Estimate No: MC1902300  
Date: 23 Nov 2021  
Policy No: P10470571R00  
Veh Reg No: SLV2355E  
Make/Model: TOYOTA C-HR TURBO  
1.2 S-T CVT


## Estimate Repair Cost to Vehicle No :SLV2355E

Description	Quantity	List Price S\$	Amount S\$
		Total	S\$ 3,910.20
		Add GST @ 7%	273.71
		Total Amount Payable	S\$ 4,183.91

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND ONE HUNDRED EIGHTY THREE AND CENTS NINETY ONE ONLY

Please arrange this vehicle to be surveyed soonest possible.  
Thank You

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE