

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

*26/11/21
10am
Vale*

SURVEYOR COPY

M/S : ABDUL RAHMAN BIN SALLEH
 BLK 192 PUNGGOL CENTRAL #06-311

Estimate No: MC1902300
 Date: 23 Nov 2021
 Policy No: P10470571R00
 Veh Reg No: SLV2355E
 Make/Model: TOYOTA C-HR TURBO
 1.2 S-T CVT

SINGAPORE 820192 *Not Authorise*

ATTN:

*Repair B&Pain
3 days*

Your Ref No: -
 Claim Type: Third Party
 Accident Date: 21/11/2021
 TP Veh Reg No: SMH5901X

82123.35

Estimate Repair Cost to Vehicle No :SLV2355E

Description	Quantity	List Price	Amount
		S\$	S\$
SPARE PARTS			
1 REAR WINDSCREEN MOULDING SIDE LH & RH	2 PC	<i>Sm</i> 91.60	<i>X</i>
2 REAR WINDSCREEN MOULDING LOWER	1 PC	<i>Sm</i> 68.20	<i>X</i>
3 TAILGATE	1 PC	<i>R</i> 1,020.30	<i>X</i>
4 TAILGATE EMBLEM	1 PC	<i>nn</i> 66.20	<i>X</i>
5 TAILGATE CHR LOGO	1 PC	<i>nn</i> 45.60	<i>X</i>
6 REAR BUMPER	1 PC	<i>Buc Mod</i> 568.20	<i>✓</i>
7 REAR BUMPER SIDE RETAINER LH & RH	2 PC	<i>Sm</i> 204.40	<i>X</i>
8 REAR BUMPER CLIPS	10 PC	<i>nn</i> 45.00	<i>✓</i>
9 REAR BUMPER LOWER GARNISH	1 PC	<i>nd</i> 411.90	<i>✓</i>
10 REAR BUMPER REFLECTOR COVER RH	1 PC	<i>Sm</i> 95.80	<i>X</i>
11 REAR BUMPER TOW COVER	1 PC	<i>Sm</i> 23.70	<i>X</i>
12 REAR BUMPER REINFORCEMENT	1 PC	<i>R1</i> 332.70	<i>2</i>
		2,973.60	
	Less 25%	743.40	2,230.20
Special Nett			
13 SEALANT	1 PC	<i>nn</i> 40.00	<i>X</i>
14 REAR BUMPER CHROME MOULDING LH & RH -CHECK PRICE	2 PC	<i>nn</i> 0.0000	<i>405N</i>
15 REAR BUMPER REVERSE SENSOR	2 PC	<i>Shen</i> 200.00	<i>2</i>
		240.00	240.00
LABOUR			
16 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	<i>15/</i>
17 TO REMOVE & REFIT REAR WINDSCREEN	1 EA	<i>nn</i> 120.00	<i>X</i>
18 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	80.00	<i>50/</i>
19 TO DISMANTLE ALL DAMAGED PARTS. TO KNOCK & REPAIR END PANEL, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	600.00	<i>400/</i>
20 TO SPRAY TAILGATE, REAR BUMPER, END PANEL	1 PC	600.00	<i>400/</i>
		1,440.00	1,440.00

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : ABDUL RAHMAN BIN SALLEH
BLK 192 PUNGGOL CENTRAL #06-311
SINGAPORE 820192

Estimate No: MC1902300
Date: 23 Nov 2021
Policy No: P10470571R00
Veh Reg No: SLV2355E
Make/Model: TOYOTA C-HR TURBO
1.2 S-T CVT

ATTN:

Your Ref No: -
Claim Type: Third Party
Accident Date: 21/11/2021
TP Veh Reg No: SMH5901X

Estimate Repair Cost to Vehicle No :SLV2355E

Description	Quantity	List Price	Amount
		S\$	S\$
		Total	S\$ 3,910.20
		Add GST @ 7%	273.71
		Total Amount Payable	S\$ 4,183.91

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND ONE HUNDRED EIGHTY THREE AND CENTS NINETY ONE ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: