

INDIA INTERNATIONAL INSURANCE PTE LTD

SMV6771Z
 Mercedes Benz GLA180
 WDC1569422J668592 *Lester*
 64 Cecil Street
 IOB Building
 #04-02
 Singapore 049711
 Attn: Meena (6347 6073)

Work Order

Job No.: WJ2111768
 Date: 23/11/2021
 Current 0 KM
 Mileage:
 Time In: 23/11/2021 14:01
 Time out:

T	Job Description	Quantity	UOM	Unit Price	Amt
	Ad hoc				
S	L/H Door Mirror <i>/ CUT</i>	1.00		920.00	920.00 <i>/ P</i>
S	L/H Front door <i>/ 00</i>	1.00		1,598.00	1,598.00 <i>/ P</i>
S	L/H Rear door <i>/ 00</i>	1.00		1,730.00	1,730.00 <i>/ P</i>
S	L/H Rear Wheel Arch Garnish <i>/ CUT</i>	1.00		200.00	200.00 <i>/ P</i>
S	L/H Rear Wheel Sport Rim <i>/ CUT</i>	1.00		830.00	830.00 <i>/ P</i>
S	L/H Rear Knuckle Arm <i>? / BT</i>	1.00		1,200.00	1,200.00 <i>/ P</i>
S	L/H Rear Knuckle Arm Bearing <i>? / nec</i>	1.00		344.00	344.00 <i>/ P</i>
S	L/H Rear Upper Arm <i>? x nn</i>	1.00		140.00	140.00
S	L/H Rear Lower Arm <i>? x nn</i>	1.00		185.00	185.00
S	L/H Rear Shock Absorber <i>? x nn</i>	1.00		467.00	467.00
S	L/H Rear Control Arm <i>? x nn</i>	1.00		150.00	150.00
S	Labour charge to Replace/Repair damaged parts	1.00	<i>900 /</i>	1,600.00	1,600.00 <i>L</i>
S	Labour to transfer both doors glass, regulator & lock mechanism to new replace doors.	1.00	<i>160 /</i>	400.00	400.00 <i>L</i>
S	To spray painting on the affected parts & areas	1.00	<i>660 /</i>	1,200.00	1,200.00 <i>L</i>
S	Labour charge to remove & replace L/H rear undercarriage damaged parts	1.00	<i>200 /</i>	600.00	600.00 <i>L</i>
S	To check/adjust wheel alignment	1.00	<i>60 /</i>	120.00	120.00 <i>L</i>
S	Labour charge to reconnect wire hardness on replace parts	1.00		50.00	50.00 <i>/</i>
S	L/H Rear Door Rubber <i>/ nec</i>	1.00		265.00	265.00 <i>/ P</i>
S	L/H Lower Side Skirting <i>/ CUT</i>	1.00		1,189.00	1,189.00 <i>/ P</i>

Continue on next page...

L-2000 P-8276
-10%
7448.40

= 9448.40

9478.40

INDIA INTERNATIONAL INSURANCE PTE LTD

SMV6771Z
Mercedes Benz GLA180
WDC1569422J668592
64 Cecil Street
IOB Building
#04-02
Singapore 049711

Attn: Meena (6347 6073)

Work Order

Job No. : WJ2111768

Date : 23/11/2021

Current 0 KM

Mileage :

Time In : 23/11/2021 14:01

Time out :

T	Job Description	Quantity	UOM	Unit Price	Amt
S	Sundries	xnn 1.00	70	60.00	60.00

Steve (LKK)
8399 8813

OD - M HL
EXCESS - ?
P/P
My Ref Sy
5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after survey painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Remarks:

Accident Repair Estimate All Nett Items

Subtotal	13,248.00
GST 7.0%	927.36
Total	14,175.36

SIGNATURE & COMPANY'S STAMP



(Authorised Signature)