

ICOMOCO MOTORS PTE. LTD.

72 Amerika kodeliki Francis (1986) I. SHATTER TARREST TO THE TRANSPORT

(GST REGISTRATION NO: MR-8500364-4)

Date: 23 NOV 2021

Steve (LKK) 30/11/21

W/P
P/P
3 days
Resurvey Before Spray

Attn: Motor Claims Department

Vehicle number : SMP 8316 Z

Make and model: I30 1.4 5DR DCT TURBO

Registration Date: 18/10/2019

Chassis number : TMAH3513VLJ115227

Engine number : G4LDKD073685

Job No. :-

Owner name: Asri Hamid Date of Acc: 20/11/2021

Policy number : -

Claim Type: 3rd Party Claim

Items:

1	EPONT PLINADED CLID MAD	Estimate		
2	FRONT BUMPER CLIP X10 UPR GRILLER COVER CLIP X6	\$ 12.00 -		
3	LAMP ASSY-HEAD,RH	\$ 3.60 /		
	Less 20% Discount Material total	\$ 3,217.50		
		\$ 643.50		

Body, Paint & Labour Items:

1	To carry out accident body repair		
	(TO RENEW HEAD LAMP & RE-ALIGN FRT BLIMPER)		

2 Complete putty and spray paint all affected areas (TO RESPRAY FRT BUMPER)

> Total Excess Add GST 7%

Estimate

\$

\$ 320.00 -

2,574.00

\$ 280.00 -

\$ 3,174.00

Grand Total

Estimation are base on visual inspection, should there be furthur damages found during process of repair, you will be inform prior before carry out***

> LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- · To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

