

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672



Date Generated : 08/12/2021

User ID PohSuan

Section A - Accident Details

Registration Number	SHB1126J
Case Reference Number	TAX/11/21/2038
Registration Date	30/8/2021
Company Type	Strides Taxi Pte Ltd
Make	MORRISGARAGES
Model	MG5
Name of Driver	LIM HONG SIANG
Type of Accident	Head to Rear
Accident Date and Time	22/11/2021 5:05 PM
Accident Reported Date and Time	23/11/2021 9:01 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24113100
Special Instruction to ARC, if any	REAR PORTION
Prepared Date and Time	24/11/2021 11:17 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates
Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$3,600.00	\$250.00
Total Spray Cost	\$1,118.00	\$220.00
Total Spare Part Cost	\$3,794.13	\$293.57
Total Other Cost	\$1,350.00	\$360.00
TOTAL COST	\$9,862.13	\$1,123.57 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	6.0	3.0
Prepared / Adjusted By	Tuck Foo Kok	RASUL (LKK) / NTUC
ARC / Surveyor Sign Off Date	24/11/2021 11:39 AM	24/11/2021 2:38 PM
Signature		
Remarks		PART BY PART REPAIR / RESURVEY BEFORE PAINT PHOTO

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2112-0138	Invoice Number	
Quotation Date	08.12.2021	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$3,600.00	\$250.00
Total Labour	\$3,600.00	\$250.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$428.00	\$220.00
TO RESPRAY BUMPER BEAM	\$230.00	\$0.00
TO RESPRAY REAR PANEL	\$230.00	\$0.00
TO RESPRAY REAR SPARE TYRE PANEL	\$230.00	\$0.00
Total Spray Painting & Panel Beating	\$1,118.00	\$220.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$60.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	\$120.00	\$0.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	\$120.00	\$0.00
TO CHECK & RESET SYSTEM FUNCTION	\$350.00	\$150.00
TO REMOVE AND REFIT WIRE HARDESS	\$250.00	\$0.00
ISOLATED OF (EV) (NET)	\$150.00	\$150.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$1,350.00	\$360.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		10369261-SPRP	FASCIA-RR BPR	1.00	\$568.86	100.00	\$0.00	Replace	Repair
		10751490	FASCIA-RR BPR LWR	1.00	\$173.01	10.00	\$155.71	Replace	Replace
		10359003	FINISHER-RR BPR - RH	0.00	\$35.56	0.00	\$0.00	Replace	Check
		10359002	FINISHER-RR BPR - LH	0.00	\$35.56	0.00	\$0.00	Replace	Not Given
		10465727	BRACKET ASM-RR BPR FASCIA SI - RH	0.00	\$22.38	0.00	\$0.00	Replace	Not Given
		10465723	BRACKET ASM-RR BPR FASCIA SI - LH	0.00	\$22.38	0.00	\$0.00	Replace	Not Given
		10326371	BRACKET-RR BPR FASCIA SI MTG - RH	0.00	\$34.56	0.00	\$0.00	Replace	Not Given
		10326369	BRACKET-RR BPR FASCIA SI MTG - LH	0.00	\$34.56	0.00	\$0.00	Replace	Not Given
		10371766	BRACKET-PARK DIST CONT SEN(BRACKET-PARK DIST	0.00	\$9.90	0.00	\$0.00	Replace	Check
		10371768	BRACKET-PARK DIST CONT SEN(BRACKET-PARK DIST	0.00	\$9.67	0.00	\$0.00	Replace	Check
		10371790	BRACKET-PARK DIST CONT SEN(BRACKET-PARK DIST	0.00	\$9.67	0.00	\$0.00	Replace	Check

√
X
X
X
X
X
X
X
X
X
X
X

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 08/12/2021

User ID PohSuan

		10449056	BRACKET-RR BPR FASCIA LWR MTG - RH	0.00	\$9.60	0.00	\$0.00	Replace	Not Given	X
		10449047	BRACKET-RR BPR FASCIA LWR MTG - LH	0.00	\$9.60	0.00	\$0.00	Replace	Not Given	X
		90003417	SCRIVET-RR BPR FASCIA	10.00	\$0.63	10.00	\$5.67	Replace	Replace	√
		90003410	BOLT/SCREW-RR BPR FASCIA BRKT	0.00	\$0.39	0.00	\$0.00	Replace	Not Given	X
		50012569	NUT-RR BPR FASCIA BRKT	0.00	\$0.70	0.00	\$0.00	Replace	Not Given	X
		90003410	BOLT/SCREW-RR BPR FASCIA	0.00	\$0.39	0.00	\$0.00	Replace	Not Given	X
		90003375	NUT-RR BPR FASCIA	0.00	\$0.39	0.00	\$0.00	Replace	Not Given	X
		90004065	CLIP-RR BPR FASCIA	0.00	\$0.93	0.00	\$0.00	Replace	Not Given	X
		10327894	BAR ASM-RR BPR IMP	0.00	\$254.82	0.00	\$0.00	Replace	Check	X
		10450132	COVER-RR TOW HOOK OPG	1.00	\$5.07	10.00	\$4.56	Replace	Replace	√
		10726677	LAMP ASM-RR FOG - RH	1.00	\$141.81	10.00	\$127.63	Replace	Replace	√
		10726676	LAMP ASM-RR FOG - LH	0.00	\$27.22	0.00	\$0.00	Replace	Not Given	X
		10376550- WSD	SENSOR-RR PARK DIST CONT	0.00	\$48.75	0.00	\$0.00	Replace	Check	X
		10395721- SEPP	PANEL ASM-RR END	0.00	\$531.49	0.00	\$0.00	Replace	Not Given	X
		11031505- SEPP	PANEL ASM-R/FLR R/SEAT	0.00	\$2,110.50	0.00	\$0.00	Replace	Not Given	X
Total					\$4,098.40		\$293.57			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

293.57
 + 250.00
 + 580.00

 1,123.57