

## Hui Zhen (LKK Auto)

---

**From:** Bryan Ang (LKKAuto)  
**Sent:** Thursday, 23 December 2021 1:34 pm  
**To:** Hui Zhen (LKK Auto)  
**Subject:** RE: SLM 8051P Surveyed by Mr Lim (CS3/LPC21007040/Buf3-1)

Hi

Adjustment is ok. But in our survey report, the COR recommended to indicate LS 10,100/-

The MV and NV has to be indicated in the remark column also.

Thereafter submit.

Best Regards,

**Bryan Ang**

**LKK Auto Consultants Pte Ltd**

phone: 6256-3561 | email: [bryanang@lkkauto.com](mailto:bryanang@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Hui Zhen (LKK Auto) <[huizhen@lkkauto.com](mailto:huizhen@lkkauto.com)>  
**Sent:** Thursday, 23 December 2021 1:23 PM  
**To:** Bryan Ang (LKKAuto) <[bryanang@lkkauto.com](mailto:bryanang@lkkauto.com)>  
**Subject:** SLM 8051P Surveyed by Mr Lim (CS3/LPC21007040/Buf3-1)

Dear Bryan,

For your audit - above \$10K.

Best Regards,

**Hui Zhen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [huizhen@lkkauto.com](mailto:huizhen@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)