

Veron Chen (LKKAUTO)

From: Simon Ho (LKKAUTO)
Sent: Thursday, 2 December 2021 2:30 PM
To: Veron Chen (LKKAUTO)
Subject: RE: SLQ 7220D ---CS3/AIG21008746/T1vf3-1

Dear Veron,

AUDIT CHECK DONE FOR SLQ7220D, FOUND PB LABOUR TOO HIGH & SURVEYOR MARKING NEED TO REVIEW.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Veron Chen (LKKAUTO)
Sent: Thursday, 2 December, 2021 12:38 PM
To: Simon Ho (LKKAUTO)
Subject: SLQ 7220D ---CS3/AIG21008746/T1vf3-1

Dear Simon

File for audit check.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)