



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21012046/Avf3n2	
			Date: 28/01/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YL 1183P	Veh. Inspected	SFY 148E	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2103505/MYE	Excess (\$)	0.00	
Assign From	MELVIN YE YONG KANG	Assign Date	29/11/2021	
2. Vehicle Particulars & Condition				
Make & Model	AUDI A6	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	WAUZZZ4G4JN047199	Colour	BLACK	
Odometer	43453 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/40 R18	MICHELIN	6 mm	
L/H Front Tyre	245/40 R18	MICHELIN	6 mm	
R/H Rear Tyre	245/40 R18	MICHELIN	6 mm	
L/H Rear Tyre	245/40 R18	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/11/2021	Inspection Date	30/11/2021	
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 . SINGAPORE 408699			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	