

2 Kaki Bukit Ave 2, #02 19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

SUPPLEMENTARY ESTIMATE OF REPAIR

Veh# SMV6409X

Model: LEXUS NX300

Accident Date : 26/11/2021

(13/10/2020)

ERV: S\$107.510

Location : CTE Tunnel (SLE)

3P: SHC4860Y (First Cap)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1pc	Rear under cover <i>torn</i>	452.60	✓	
2		To do re-setting		350.00	180
		Sub Total:	452.60	350.00	0.00
			10%	0%	10%
		After Less %:	407.34	350.00	0.00
		Total:		757.34	

Chan
Chan San Choon
Director
DipEng, AAE MIMI, MSAE(Aust)



AL 8778 1999
24 hr accident call



191
171.90

S.N: 180

Adnan Lj
02/12/21.

Supplementary: 351.90.