

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	17/09/2021 15:32 (SGT)
Date of Accident	16/09/2021 20:10 (SGT)
Exact Location of Accident	33 Hyderabad Rd, HortPark, Singapore 119578
Additional Location Information	Before 11511, Alexandra Rd & exit to AYE
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SBS8347Z
-----------------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	SBS TRANSIT LTD
Company Reg No	XXXXXXXXXXXXTE01
Email Address	seahhh@sbstransit.com.sg
Mobile Phone No	(Phone) +65-62444534
Alternative Phone No	(Office) +65-62444534

VEHICLE PARTICULARS

Manufacturer	Scania
Model	KUB4X2, SD, AC, 2 Axle
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Bus
Transmission	Auto
CC	8867

INSURANCE COMPANY

Name of Insurance Company	MS First Capital Insurance Ltd
Type of Coverage	ActLiability
Fleet Policy	No
Policy Number	D-21097501MFBP
Cover Note Number	-

DRIVER

Name of Driver	Pang Kwok Keong
NRIC No	SXXXX619Z

Date Of Birth	03/11/1967		
Occupation	Outdoor		
Date Of Driving Pass	26/03/2011		
Driving experience	10 YEARS AND 6 MONTHS		
Gender	Male		
Mobile Number	(Phone) +65-97924386		
Alt. Phone Number	-		
Email Address	seahhh@sbstransit.com.sg		
Address	12, Bedok North Drive		
Address complement	Blk 142 Bedok Reservoir Rd	#06-1555	Postal Code :
	470142		
Postcode	Singapore 465492		
Is the driver the policyholder?	No		
If No, Relationship of the Driver with the Insured	Employee		
Does Driver Own Other Vehicles?	No		
Vehicle Registration Number of Other Vehicle Owned by Driver	-		
Insurance Company of Other Vehicle Owned by Driver	-		

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Major/Minor Rd
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	No
Number of Passengers (Including Driver)	15
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	UNKNOWN
Gender	Male

PASSENGER 2

Name	UNKNOWN
Gender	Female

PASSENGER 3

Name	UNKNOWN
Gender	Male

PASSENGER 4

Name	UNKNOWN
Gender	Female

PASSENGER 5

Name	UNKNOWN
Gender	Male

PASSENGER 6

Name	UNKNOWN
Gender	Female

PASSENGER 7

Name	UNKNOWN
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police? No
 Was notice of intended Prosecution given? No
 If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

When I was going straight in the left lane; passing by the exit to AYE, I saw the private car SMT5037C just given the right signal & straightway started to swerve to my bus RHS center. I then immediately honked at it. As a result, it started swerved back into its lane. But I saw its LH view mirror had sprung inwards. Then I stopped to take photo of each other vehicle plate no. As I did not see any real damage to my bus RHS center. I resumed my service. No injury. That's all.

ATTACHMENT(S)

Are accident photos available for attachment? No
 Was there any video captured by Car Camera? No
 Was there any audio recorded? No

