



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

Ref: CS/INC21012105/Bqy3e2

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

Date: 10/03/2023

ATTN: CYNDIE YONG

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBN 857Y	Veh. Inspected	SMC 9096U
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1152662-001	Excess (\$)	0.00
Assign From	LIM CHAN HENG	Assign Date	30/11/2021

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI ELANTRA 1.6	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	KMHD841CMJU727784	Colour	SILVER
Odometer	86486 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	POOR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	YOKOHAMA	5 mm
L/H Front Tyre	195/65 R15	YOKOHAMA	5 mm
R/H Rear Tyre	195/65 R15	YOKOHAMA	5 mm
L/H Rear Tyre	195/65 R15	YOKOHAMA	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND O/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	28/11/2021	Inspect Date / Time	30/11/2021 (02:43 PM)
Survey held at	BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 12 Working Days