



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD
73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556
ATTN: FIONA SHEN

Ref: CS/INC21012106/Btf3e2

Date: 20/12/2021

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XD 8343C	Veh. Inspected	YP 7494G
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1152088-002	Excess (\$)	0.00
Assign From	LIM CHAN HENG	Assign Date	30/11/2021

2. Vehicle Particulars & Condition

Make & Model	ISUZU NQR75UK5A	c.c	5193
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JAAN1R75KH7100293	Colour	WHITE
Odometer	240176 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/75 R17.5	FIRENZA	6 mm
L/H Front Tyre	215/75 R17.5	FIRENZA	6 mm
R/H Rear Tyre	215/75 R17.5	SUMITOMO	6 mm
L/H Rear Tyre	215/75 R17.5	SUMITOMO	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	23/11/2021	Inspect Date / Time	01/12/2021 (04:13 PM)
Survey held at	BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days