

1	of 2 ?	100%	Find Next
---	--------	------	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
NTUC INCOME INSURANCE CO-OPERATIVE LTD		Ref: CS3/INC21012107/Gvf3		
73 BRAS BASAH ROAD		Date: 30/11/2021		
#05-01 NTUC TRADE UNION HOUSESINGAPORE				
189556		Code: INC		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SNA 2260G	Veh. Inspected	SLG 7000A	
Policy No.	MT/1152798-001	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From	LIM CHAN HENG	Assign Date	30/11/2021	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	26/11/2021	Inspection Date	30/11/2021	
Survey held at	GARAGE 13 PTE LTD 8 KAKI BUKIT AVE 4 #03-46 PREMIER 415875 SINGAPORE.			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				