Hui Zhen (LKK Auto)

From: Hui Zhen (LKK Auto)

Sent: Friday, 3 December 2021 1:53 PM hupmotor@gmail.com; SUR

Subject: OD / GBK 6215B / DOA: 28/11/2021

Dear Sir/Mdm,

As instructed by our client, please proceed to repair the insured vehicle GBK 6215B (Excess TBA).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserves their rights not to pay if there is no valid approval obtained before repair.

Best Regards,

Hui Zhen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>huizhen@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)