

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21012130/UGA3Q2**Date:** 18/04/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210039862
Claimant Vehicle No :	JSR1578	Insured Vehicle No :	SJL8991E
Date of Loss:	12/10/2021	Nature of Claim:	TP
		Claim No:	0127035659SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	JSR1578	Engine No:	KF20E8100765
Make & Model:	HONDA RS150R MANUAL, 149cc	Chassis No:	PMKKF2170JB100723
Reg. Date:	01/01/2017 (Man. Year: 2017)	Odometer:	54961 km
Colour:	Black		
Engine Capacity:	149 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	90-90-14	Rear Tyre Size:	100-90-14
Front Left Side:	Maxxis 6 mm	Rear Left Side:	Maxxis 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,183.00	3,041.00	3,142.00	50.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,050.00	720.00	330.00	31.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,233.00	3,761.00	3,472.00	48.00
Approved Total (Overridden) (\$\$)		3,000.00		
Nett Amount (\$\$)	7,233.00	3,000.00	4,233.00	58.52
+ Loss of Use (6.0 x S\$20.00/day) (\$\$)		120.00		
Nett Liability (\$\$)		3,120.00		

INSPECTION

Date of Assignment:	30/11/2021	
Date Inspected:	01/12/2021	Inspected At: Erofia Motor Trading Pte Ltd (KAKI BUKIT) 1 KAKI BUKIT AVE 6 #02-62 Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FORK ASSY	Repair	980.00 FL	*- FL
2	1		*FRONT RIM	Serviceable	355.00 FL	*- FL
3	1		*FRONT BRAKE DISC	Not Necessary	198.00 FL	*- FL
4	1		*FRONT RIM SHAFT	Not Necessary	58.00 FL	*- FL
5	1		*FRONT RIM BEARING	Not Necessary	280.00 FL	*- FL
6	1		*HEALAMP (LED)	Cracked	960.00 FL	*960.00 FL
7	1		*METER COVER	Cut	135.00 FL	*135.00 FL
8	1		*SIDE MIRROR (N/S)	Cut	180.00 FL	*180.00 FL
9	1		*HANDLE BAR	Bent	135.00 FL	*135.00 FL
10	1		*SET HANDLE BAR BALANCER	Cut	80.00 FL	*80.00 FL
11	1		*SET HAND GRIP	Not Necessary	60.00 FL	*- FL
12	1		*BRAKE LEVER	N/S Cut / O/S Not Necessary	104.00 FL	*50.00 FL
13	2		*FOOTSTEP PANEL	Cut	310.00 FL	*310.00 FL
14	1		*MAIN STAND	Repair	175.00 FL	*- FL
15	1		*SIDE STAND	Cut	105.00 FL	*105.00 FL
16	1		*EXHAUST ASSY	Not Necessary	680.00 FL	*- FL
17	1		*EXHAUST PROTECTOR	Torn	185.00 FL	*185.00 FL
18	1		*SET FAIRING COVER	Cracked	1,150.00 FL	*1,150.00 FL
19	1		*REAR LAMP ASSY	Not Necessary	380.00 FL	*- FL
20	2		*FORK OILS	Not Necessary	30.00 FS	*- FS
21	2		*FORK OIL SEAL	Not Necessary	56.00 FS	*- FS
22	1		*SET STEERING CONE	Not Necessary	120.00 FS	*- FS
23	1		*SET NUMBER PLATE	Not Necessary	38.00 FS	*- FS
24	1		*PCX EMBLEM	Necessary	80.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,834.00	3,370.00
- List Item Discount on L Items 10.00/10.00% (S\$)	651.00	329.00
Total Parts (S\$)	6,183.00	3,041.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PROVIDE TOWING SERVICE (LOD)	New	40.00	40.00
2	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
3	TO SPRAY PAINTING	New	450.00	380.00
4	TO PROVIDE LABOUR	New	480.00	300.00
Gross Labour Cost (\$\$)			1,050.00	720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >