

# ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A  
 #03-11 AMK Autopoint Singapore 568047  
 Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

*Not Authorized* ESTIMATE

Sompo Insurance Singapore Pte Ltd  
 50 Raffles Place  
 #05-01/06, Singapore Land Tower,  
 Singapore 048623  
 Attn: Accident Claims Department

*Mrsing Afa Kainp*  
*Ex ??*  
*82954-10*

Date: 29/11/2021  
 Vehicle No: SJZ1138A  
 Veh Make/Model: Honda City 1.5  
 YOM: 2009  
 Chassis No: MRHGM26709P020421  
 Date of Accident: 27/11/2021

No	Qty	Description	Amount S
<b>Cost Items:-</b>			
1	1	LH Headlamp ✓	\$ CM 210.00 ✓
2	1	LH Headlamp Lower Bracket ✓	\$ Pn 15.00 X
3	1	RH Headlamp ✓	\$ CM 210.00 ✓
4	1	RH Headlamp Lower Bracket ✓	\$ Pn 15.00 X
5	1	Front Bumper ✓	\$ Bn 160.00 ✓
6	2	Front Bumper Side Retainer ✓	\$ Hd 70.00 X
7	1	Front Grille Base ✓	\$ M 80.00 ✓
8	2	Front Grille Outer ✓	\$ CM 100.00 ✓
9	1	Front Emblem "H" ✓	\$ M 16.00 ✓
10	1	Front Foglamp Garnish LH ✓	\$ Sn 20.00 X
11	1	Front Foglamp LH ✓	\$ Sn 120.00 X
12	1	Front Foglamp Garnish RH ✓	\$ Sn 20.00 X
13	1	Front Foglamp RH ✓	\$ Sn 120.00 X
14	1	Front Reinforcement Bar ✓	\$ R 75.00 ✓
15	1	Front Radiator Top Rubber / Seal ✓	\$ Sn 10.00 X
16	1	Front Support Panel ✓	\$ R 180.00 X
17	1	Front Bonnet ✓	\$ R 260.00 ✓
18	1	Bonnet Hinge ✓	\$ R 22.00 X
19	1	Bonnet Lock ✓	\$ D.T 80.00 ✓
20	1	Bonnet Stand ✓	\$ R 90.00 X
21	1	Bonnet Clip ✓	\$ M 5.00 ✓
22	1	Towing Cover ✓	\$ Sn 10.00 X
23	1	Front RH Fender ✓	\$ R 95.00 X
24	1	Front RH Fender Shield ✓	\$ Sn 30.00 X
25	1	condensot ✓	270.00 ✓
26	1	front bumper beam ✓	D.T 15.00 ✓
27			
28			
29			
30			
31			
32			
<b>Total - List Item</b>			\$ 2,013.00
<b>Cost + 10%</b>			\$ 201.30
<b>Total</b>			\$ 2,214.30

# ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A  
 #03-11 AMK Autopoint Singapore 568047  
 Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

## ESTIMATE

Sompo Insurance Singapore Pte Ltd  
 50 Raffles Place  
 #05-01/06, Singapore Land Tower,  
 Singapore 048623  
 Attn: Accident Claims Department

Date : 29/11/2021  
 Vehicle No : SJZ1138A  
 Veh Make/Model : Honda City 1.5  
 YOM : 2009  
 Chassis No : MRHGM26709P020421  
 Date of Accident : 27/11/2021

No	Qty	Description	Amount \$
----	-----	-------------	-----------

Page 1/2

		Balance c/f	
		<b>Special Nett Items:-</b>	
1	1 Set	Front Car Plate Number With Holder	\$ 45.00
2	1 Set	Front Bumper Clips	\$ 30.00
3	1 Set	Front Radiator Top Garnish Clips	\$ 30.00
4	2 Set	Front LH & RH Side Fender Shield Clips	\$ 50.00
5			
		<b>Total - SN Item</b>	\$ 155.00
		<b>Labour Charges:-</b>	
1		Spray painting on all affected area.	\$ 800.00
2		Labour remove/refix accident damages parts to knock, jack, cut weld and realign accident affected area.	\$ 800.00
3		To check wiring system & light.	\$ 80.00
4		Top remove/refix aircon condenser, radiator & etc (top up aircon gas & coolant for replace support panel)	\$ 180.00
6			
7			
8			
		<b>Total - L/C</b>	\$ 1,860.00

✓  
 ✓  
 ✓  
 X  
  
 800  
 500  
 20  
 100

Sub-Total	\$ 4,229.30	4542.80
7% GST	\$ 296.05	
<b>Total</b>	<b>\$ 4,525.35</b>	

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: