

ASS. REC. BY:

REF:

C12/2102754/KK

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MY

To Inspect Vehicle No: _____

at Workshop m/s S Three

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 831k

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 09 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: 05/06 Person Contacted: _____ Vehicle: IN / OUT

Veh No: SUB 86544 Yr Regn: 05, 06

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or (A) MAV

Make: Toy wish c.c. 1794

Colour: M. Silver A/C: Insured / Std / NI / NA

Sp. Reading: 305728 T/Radio: Insured / Std / NI / NA

Eng/No: _____
C/No: ZNE10 0301333

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / SRIm / STD A/RIm or

Tyre Size: F: 205/55R16
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front R/Bal. 5 mm Rear R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 28/11/21 D.O.I. 1/12/2021

Survey held at ✓

Des. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or

& FT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 Mat about 810k

LUMP SUM \$10,000. 9DAYS
RED:34,481.76;77%

Date/Time, File Pass to?

: Prell. Report

Days Of Repair: 9

1) Date/Time, File Return to?

: Final Report

Resurvey No. of Trip: _____

Survey Fee:

2) _____

Add Fee: : Site Insp (\$ _____)

Transportation:

: Interview (\$ _____)

_____ S - RS. SI

: Tech Invs (\$ _____)

_____ Fines

: Weekend (\$ _____)

_____ Others

Report Format :

Lump Sum / I.B.I: (\$ _____)

TOTAL

Not Authorized
 L1 Day &
 Recovery After Paint
 9 days



S THREE AUTOMOTIVE RECOVERY PTE LTD

TO :
 ATTN :

T/P VEH. NO. :

ESTIMATE REPORT 1st QUOTATION

JOB NO. : _____

OWNER'S PARTICULAR

NAME : HO SIONG SWEE
 ADDRESS :
 LICENSE NO SLB8654H TRANS.
 MAKE / MODEL : TOYOTA WISH
 OWNER'S INSURER
 JOB-CODE : TP S/A : JOEY

CONTACT : 98187903

CHASSIS NO :
 ENGINE NO :

ACCIDENT DATE : 28-Nov-21

CLAIM DETAIL

MATERIALS

	QTY	QUO-PRICE	DISC. %	DISC-PRICE	SUR. DISP	REV. PRICE
1 FRONT BUMPER	1.00	\$ 1,485.00	25.00	\$ 1,113.75	Y	✓
2 FRONT BUMPER RETAINER LH	1.00	\$ 48.00	25.00	\$ 36.00	Y	X
3 FRONT BUMPER RETAINER RH	1.00	\$ 48.00	25.00	\$ 36.00	Y	✓
4 FRONT BUMPER BRACKET LH	1.00	\$ 50.90	25.00	\$ 38.18	Y	X
5 FRONT BUMPER BRACKET RH	1.00	\$ 50.90	25.00	\$ 38.18	Y	X
6 FRONT BUMPER FOG LAMP LH	1.00	\$ 328.50	25.00	\$ 246.38	Y	X
7 FRONT BUMPER FOG LAMP RH	1.00	\$ 328.50	25.00	\$ 246.38	Y	X
8 FRONT BUMPER LOWER SPOILER	1.00	\$ 688.00	25.00	\$ 516.00	Y	X
9 FRONT BUMPER REINFORCEMENT	1.00	\$ 355.90	25.00	\$ 266.93	Y	X
10 FRONT BUMPER SPONGE	1.00	\$ 110.50	25.00	\$ 82.88	Y	?
11 FRONT BONNET	1.00	\$ 928.90	25.00	\$ 696.68	Y	✓
12 FRONT BONNET CHROME	1.00	\$ 275.00	25.00	\$ 206.25	Y	?
13 BONNET LOCK	1.00	\$ 225.30	25.00	\$ 168.98	Y	X
14 BONNET SEAL	1.00	\$ 48.50	25.00	\$ 36.38	Y	X
15 FRONT BONNET HINGE LH	1.00	\$ 98.00	25.00	\$ 73.50	Y	X
16 FRONT BONNET HINGE RH	1.00	\$ 98.00	25.00	\$ 73.50	Y	X
17 FRONT BONNET INSULATOR	1.00	\$ 298.50	25.00	\$ 223.88	Y	X
18 BONNET LOGO	1.00	\$ 69.50	25.00	\$ 52.13	Y	?
19 BONNET SEAL HOLDER	1.00	\$ 26.70	25.00	\$ 20.03	Y	X
20 BONNET CABLE LOCK	1.00	\$ 68.50	25.00	\$ 51.38	Y	X
21 HEADLAMP LH HID	1.00	\$ 2,400.00	25.00	\$ 1,800.00	Y	?
22 HEADLAMP RH HID	1.00	\$ 2,400.00	25.00	\$ 1,800.00	Y	✓
23 HEADLAMP BRACKET RH	1.00	\$ 80.00	25.00	\$ 60.00	Y	X
24 HEADLAMP BRACKET LH	1.00	\$ 80.00	25.00	\$ 60.00	Y	X
25 SUPPORT PANEL	1.00	\$ 1,020.00	25.00	\$ 765.00	Y	X
26 SUPPORT PANEL TOP COVER	1.00	\$ 264.80	25.00	\$ 198.60	Y	X

27	WIPER TANK	P ₂	1.00	\$ 230.00	25.00	\$ 172.50	Y	X
28	RADIATOR	S ₂	1.00	\$ 1,637.32	25.00	\$ 1,227.99	Y	X
29	RADIATOR FAN	S ₂	1.00	\$ 904.75	25.00	\$ 678.56	Y	X
30	RADIATOR FAN COWLING	S ₂	1.00	\$ 498.80	25.00	\$ 374.10	Y	X
31	AIRCON FAN ASSY	S ₂	1.00	\$ 904.80	25.00	\$ 678.60	Y	X
32	RADIATOR TOP MOUNTING LH	S ₂	1.00	\$ 40.00	25.00	\$ 30.00	Y	X
33	RADIATOR TOP MOUNTING RH	S ₂	1.00	\$ 40.00	25.00	\$ 30.00	Y	X
34	RADIATOR TOP MOUNTING BRACKET LH	N	1.00	\$ 40.00	25.00	\$ 30.00	Y	X
35	RADIATOR TOP MOUNTING BRACKET RH	N	1.00	\$ 40.00	25.00	\$ 30.00	Y	X
36	FRONT GRILLE ASSY		1.00	\$ 280.00	25.00	\$ 210.00	Y	?
37	BRACE PANEL	B ₂	1.00	\$ 110.10	25.00	\$ 82.58	Y	✓
38	AIRCON CONDENSOR SIDE GARNISH LH	S ₂	1.00	\$ 80.00	25.00	\$ 60.00	Y	X
39	AIRCON CONDENSOR SIDE GARNISH RH	S ₂	1.00	\$ 80.00	25.00	\$ 60.00	Y	X
40	AIRCON PIPE - CONDENSOR TO COMPRESSOR	P ₂	1.00	\$ 289.50	25.00	\$ 217.13	Y	X
41	AIRCON PIPE - CONDENSOR TO COOLING COIL	S ₂	1.00	\$ 489.50	25.00	\$ 367.13	Y	X
42	AIRCON PIPE - COMPRESSOR TO CONDENSOR	P ₂	1.00	\$ 267.30	25.00	\$ 200.48	Y	X
43	AIRCON CONDENSOR		1.00	\$ 1,428.97	25.00	\$ 1,071.73	Y	?
44	RADIATOR TOP HOSE	S ₂	1.00	\$ 148.50	25.00	\$ 111.38	Y	X
45	RADIATOR BOTTOM HOSE	S ₂	1.00	\$ 198.50	25.00	\$ 148.88	Y	X
46	RADIATOR BYPASS HOSE	P ₂	1.00	\$ 98.50	25.00	\$ 73.88	Y	X
47	HORN 2PCS	S ₂	2.00	\$ 288.20	25.00	\$ 216.15	Y	X
48	TAILGATE SPOILER TOP	P ₂	1.00	\$ 987.60	25.00	\$ 740.70	Y	X
49	REAR WINDSCREEN GLASS MOULDING	N ₂	1.00	\$ 229.50	25.00	\$ 172.13	Y	✓
50	REAR WINDSCREEN GLASS SIDE MOULDING LH	N ₂	1.00	\$ 80.00	25.00	\$ 60.00	Y	X
51	REAR WINDSCREEN GLASS SIDE MOULDING RH	N ₂	1.00	\$ 80.00	25.00	\$ 60.00	Y	X
52	TAILGATE	B ₂	1.00	\$ 1,460.80	25.00	\$ 1,095.60	Y	✓
53	TAILGATE LOGO	N ₂	1.00	\$ 68.50	25.00	\$ 51.38	Y	✓
54	TAILGATE EMBLEM	N ₂	1.00	\$ 49.30	25.00	\$ 36.98	Y	✓
55	TAILGATE OUTER CHROME MOULDING	CM	1.00	\$ 383.85	25.00	\$ 287.89	Y	✓
56	TAILGATE INNER LOCK	T ₂	1.00	\$ 497.37	25.00	\$ 373.03	Y	✓
57	TAILGATE INNER LOCK CATCH	D ₂	1.00	\$ 180.00	25.00	\$ 135.00	Y	✓
58	TAILGATE INNER TRIM BOARD		1.00	\$ 612.50	25.00	\$ 459.38	Y	?
59	TAILGATE INNER TRIM LH	P ₂	1.00	\$ 396.50	25.00	\$ 297.38	Y	X
60	TAILGATE INNER TRIM RH		1.00	\$ 396.50	25.00	\$ 297.38	Y	?
61	TAILGATE INNER TRIM TOP		1.00	\$ 410.90	25.00	\$ 308.18	Y	?
62	TAILGATE INNER HANDLE		1.00	\$ 82.50	25.00	\$ 61.88	Y	?

63	TAILGATE RUBBER	<i>OdPlw</i>	1.00	\$	370.54	25.00	\$	277.91	Y	<i>506W</i>
64	TAILGATE DAMPER LH	<i>Sm</i>	1.00	\$	361.60	25.00	\$	271.20	Y	<i>X</i>
65	TAILGATE DAMPER RH		1.00	\$	361.60	25.00	\$	271.20	Y	<i>?</i>
66	TAILGATE HINGE LH	<i>R</i>	1.00	\$	59.70	25.00	\$	44.78	Y	<i>✓</i>
67	TAILGATE HINGE RH	<i>R</i>	1.00	\$	59.70	25.00	\$	44.78	Y	<i>X</i>
68	TAILGATE WIRE HARDNESS	<i>Plw</i>	1.00	\$	480.00	25.00	\$	360.00	Y	<i>X</i>
69	REAR WIPER MOTOR		1.00	\$	719.60	25.00	\$	539.70	Y	<i>?</i>
70	REAR WIPER BLADE	<i>Sm</i>	1.00	\$	38.00	25.00	\$	28.50	Y	<i>X</i>
71	REAR WIPER NOZZLE	<i>Sm</i>	1.00	\$	120.00	25.00	\$	90.00	Y	<i>X</i>
72	REAR WIPER ARM	<i>Sm</i>	1.00	\$	175.60	25.00	\$	131.70	Y	<i>X</i>
73	REAR TAILLAMP RH	<i>CM</i>	1.00	\$	688.90	25.00	\$	516.68	Y	<i>✓</i>
74	REAR TAILLAMP LH	<i>Sm</i>	1.00	\$	688.90	25.00	\$	516.68	Y	<i>X</i>
75	TAILGATE LAMP LH	<i>NSP</i>	1.00	\$	619.60	25.00	\$	464.70	Y	<i>X</i>
76	TAILGATE LAMP RH	<i>NSP</i>	1.00	\$	64.00	25.00	\$	48.00	Y	<i>X</i>
77	TAILGATE OPEN SWITCH		1.00	\$	328.50	25.00	\$	246.38	Y	<i>?</i>
78	REAR TAILLAMP PANEL LH	<i>R</i>	1.00	\$	297.00	25.00	\$	222.75	Y	<i>X</i>
79	REAR TAILLAMP PANEL RH		1.00	\$	297.00	25.00	\$	222.75	Y	<i>?</i>
80	REAR BUMPER - SPORT	<i>Bu</i>	1.00	\$	1,559.60	25.00	\$	1,169.70	Y	<i>✓</i>
81	REAR BUMPER REFLECTOR LH	<i>Sm</i>	1.00	\$	68.50	25.00	\$	51.38	Y	<i>X</i>
82	REAR BUMPER REFLECTOR RH	<i>Sm</i>	1.00	\$	68.50	25.00	\$	51.38	Y	<i>X</i>
83	REAR BUMPER BRACKET LH	<i>R</i>	1.00	\$	98.10	25.00	\$	73.58	Y	<i>X</i>
84	REAR BUMPER RBACKET RH	<i>R</i>	1.00	\$	98.10	25.00	\$	73.58	Y	<i>X</i>
85	REAR BUMPER SIDE RETAINER LH	<i>Sm</i>	1.00	\$	68.60	25.00	\$	51.45	Y	<i>X</i>
86	REAR BUMPER SIDE RETAINER RH	<i>D.Y</i>	1.00	\$	68.60	25.00	\$	51.45	Y	<i>✓</i>
87	REAR NUMBER PLATE LAMP LH	<i>Sm</i>	1.00	\$	60.00	25.00	\$	45.00	Y	<i>X</i>
88	REAR NUMBER PLATE LAMP RH	<i>Sm</i>	1.00	\$	60.00	25.00	\$	45.00	Y	<i>X</i>
89	REAR END PANEL	<i>Ry</i>	1.00	\$	655.20	25.00	\$	491.40	Y	<i>✓</i>
90	REAR END PANEL INNER GARNISH		1.00	\$	296.50	25.00	\$	222.38	Y	<i>?</i>
91	REAR END PANEL INNER CROSSMEMBER		1.00	\$	489.50	25.00	\$	367.13	Y	<i>?</i>
92	REAR FENDER INNER TRIM BOARD LH	<i>Sm</i>	1.00	\$	899.20	25.00	\$	674.40	Y	<i>X</i>
93	REAR FENDER INNER TRIM BOARD RH		1.00	\$	899.20	25.00	\$	674.40	Y	<i>?</i>
94	REAR FENDER INNER HOUSING LH	<i>R</i>	1.00	\$	938.50	25.00	\$	703.88	Y	<i>X</i>
95	REAR FENDER INNER HOUSING RH		1.00	\$	938.50	25.00	\$	703.88	Y	<i>?</i>
96	REAR FENDER INNER SHIELD LH	<i>Sm</i>	1.00	\$	115.20	25.00	\$	86.40	Y	<i>X</i>
97	REAR FENDER INNER SHIELD RH	<i>Sm</i>	1.00	\$	115.20	25.00	\$	86.40	Y	<i>X</i>
98	REAR FENDER TRIM BOARD TOP LH	<i>Plw</i>	1.00	\$	280.00	25.00	\$	210.00	Y	<i>X</i>

99	REAR FENDER TRIM BOARD TOP RH	<i>Sm</i>	1.00	\$	280.00	25.00	\$	210.00	Y	<u>X</u>
100	REAR FENDER INNER PANEL LH	<i>N</i>	1.00	\$	550.00	25.00	\$	412.50	Y	<u>X</u>
101	REAR FENDER INNER PANEL RH	<i>N</i>	1.00	\$	550.00	25.00	\$	412.50	Y	<u>X</u>
102	REAR FENDER OUTER PANEL LH	<i>N</i>	1.00	\$	550.00	25.00	\$	412.50	Y	<u>X</u>
103	REAR FENDER OUTER PANEL RH	<i>N</i>	1.00	\$	550.00	25.00	\$	412.50	Y	<u>X</u>
104	REAR FENDER AIRVENT LH	<i>Sm</i>	1.00	\$	181.95	25.00	\$	136.46	Y	<u>X</u>
105	REAR FENDER AIRVENT RH	<i>Sm</i>	1.00	\$	181.95	25.00	\$	136.46	Y	<u>X</u>
106	REAR SPARE TYRE BOARD		1.00	\$	591.60	25.00	\$	443.70	Y	<u>?</u>
107	REAR SPARE TYRE PANEL		1.00	\$	699.80	25.00	\$	524.85	Y	<u>?</u>
108	REAR SPARETYRE CARRIER		1.00	\$	497.35	25.00	\$	373.01	Y	<u>?</u>
109	REAR 1/4 GLASS LH WITH MLDG	<i>nn</i>	1.00	\$	788.00	25.00	\$	591.00	Y	<u>X</u>
110	REAR 1/4 GLASS RH WITH MLDG	<i>nn</i>	1.00	\$	788.00	25.00	\$	591.00	Y	<u>X</u>
111	REAR KEYLESS CONTROL		1.00	\$	480.00	25.00	\$	360.00	Y	<u>?</u>

TOTAL (PARTS) :

46082.35

34561.76

SPECIAL NETT ITEM

1	REAR WINDSCREEN GLASS SEALANT	<i>nn</i>	1.00		50.00	0.00		50.00	Y	<u>40.50</u>
2	REAR WINDSCREEN GLASS INNER SEAL	<i>nn</i>	1.00		50.00	0.00		50.00	Y	<u>30.50</u>
3	REAR WINDSCREEN GLASS CLEANER & PRIMER	<i>nn</i>	1.00		50.00	0.00		50.00	Y	<u>20.50</u>
4	REAR NUMBER PLATE	<i>nd</i>	1.00		50.00	0.00		50.00	Y	<u>45.50</u>
5	REAR FENDER INNER SHIED CLIPS	<i>nn</i>	1.00		100.00	0.00		100.00	Y	<u>X</u>
6	REAR END PANEL SEALANT		1.00		80.00	0.00		80.00	Y	<u>30.50</u>
7	REAR END PANEL INNER GARNISH CLIPS 1SET	<i>nn</i>	1.00		50.00	0.00		50.00	Y	<u>X</u>
8	REAR BUMPER CLIPS 1SET	<i>nn</i>	1.00		50.00	0.00		50.00	Y	<u>✓</u>
9	REAR SPARETYRE INSULATOR PAD		1.00		180.00	0.00		180.00	Y	<u>?</u>
10	REAR REVERSE SENSOR		1.00		280.00	0.00		280.00	Y	<u>?</u>
11	REAR CAMERA	<i>Sm</i>	1.00		680.00	0.00		680.00	Y	<u>X</u>
12	REAR CAMERA RECORDER	<i>Sm</i>	1.00		680.00	0.00		680.00	Y	<u>X</u>
13	FRONT CAMERA RECORDER	<i>Sm</i>	1.00		680.00	0.00		680.00	Y	<u>X</u>
14	FRONT FENDER INNER SHIELD CLIPS RH	<i>nn</i>	1.00		50.00	0.00		50.00	Y	<u>X</u>
15	FRONT FENDER INNER SHIELD CLIPS LH	<i>nn</i>	1.00		50.00	0.00		50.00	Y	<u>X</u>
16	FRONT BUMPER CLIPS 1SET	<i>nn</i>	1.00		50.00	0.00		50.00	Y	<u>✓</u>
17	FRONT BUMPER LOWER COVER CLIPS	<i>nn</i>	1.00		80.00	0.00		80.00	Y	<u>X</u>
18	FRONT SUPPORT PANEL TOP COVER CLIPS	<i>nn</i>	1.00		50.00	0.00		50.00	Y	<u>X</u>
19	BONNET INSULATOR CLIPS	<i>nn</i>	1.00		80.00	0.00		80.00	Y	<u>X</u>

20	RADIATOR COOLANT	nm 1.00	80.00	0.00	80.00	Y	X
21	FRONT NO. PLATE	PD 1.00	50.00	0.00	50.00	Y	45m
TOTAL (PARTS) :			3470.00		3470.00		

LABOUR

1	STRAIGHTEN & PANEL BEAT ACCIDENT AREAS - FRT	1.00	1200.00	0.00	1200.00	Y	400l
2	STRAIGHTEN & PANEL BEAT ACCIDENT AREAS - REAR	1.00	1600.00	0.00	1600.00	Y	800l
3	SPRAY PAINTING ON AFFECTED AREA - FRT	1.00	1200.00	0.00	1200.00	Y	600l
4	SPRAY PAINTING ON AFFECTED AREA - REAR	1.00	1400.00	0.00	1400.00	Y	1000l
5	CHECK & REPAIR WIRING SYSTEM	1.00	80.00	0.00	80.00	Y	40l
6	R&R INNER TRIM, INNER GARNISH TO ASSIST REPAIR	1.00	120.00	0.00	120.00	Y	100l
7	R&R AND RESET REAR BUMPER SENSOR	1.00	120.00	0.00	120.00	Y	50l
8	R&R REAR WINDSCREEN GLASS	1.00	150.00	0.00	150.00	Y	120l
9	RESPRAY TUFF KOTE ON ACCIDENT AREAS	1.00	280.00	0.00	280.00	Y	90l
10	R&R TAILGATE COMPONENTS	1.00	120.00	0.00	120.00	Y	60l
11	R&R AIRCON CONDENSOR & CHARGE UP GAS	1.00	180.00	0.00	180.00	Y	?
TOTAL (LABOUR) :			6450.00		6450.00		

TOTAL PARTS & LABOUR \$ 56,002.35 \$ 44,481.76

EXCESS : : S\$ _____

NO. OF DAY : _____

RE-SURVEY : BEFORE / AFTER PAINTING

PART-BY-PART OR LUMP-SUM : S\$ _____

DATE OF SURVEY : ___ / ___ / ___

SURVEY BY : _____

CONTACT N: _____

FAX NO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policy holder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 29/11/2021 11:31 (SGT)
 Date of Accident 28/11/2021 11:55 (SGT)
 Exact Location of Accident 57 Pasir Ris Dr 1, Singapore 519531
 Additional Location Information OUTSIDE BELYSA CONDO
 Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLB8654H

INSURED/POLICYHOLDER

Is company? No
 Name Of Registered Owner HO SIONG SWEE
 NRIC No S1225138F
 Email Address HENRYHOSW1957@GMAIL.COM
 Mobile Phone No (Phone) +65-98187903
 Alternative Phone No +65-98187903

VEHICLE PARTICULARS

Manufacturer Toyota
 Model Wish
 Variant -
 Exact purpose for which vehicle was being used at time of accident Private use
 Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
 Vehicle Category Private car
 Transmission Auto
 CC 1794

INSURANCE COMPANY


Name of Insurance Company Auto & General Insurance (Singapore) Pte. Limited.
 Type of Coverage Comprehensive
 Fleet Policy No
 Policy Number P10155543R02
 Cover Note Number -

DRIVER

Name of Driver HO SIONG SWEE
 NRIC No S1225138F

SKETCH PLAN

Pasir Ris Dr 1



Belysa
Cond'n

- A - SLB 8654H
- B - SDL 555E
- C - SK2 5632B

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

while driving along Pasir Ris Dr 1, vehicle C in front of me suddenly jammed brake. I followed suite and did not hit onto the front car. Suddenly vehicle B came from behind and hit the rear portion of my vehicle. Due to the great impact, my vehicle was being pushed forward to hit vehicle C.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time

Driver's Signature
 (if driver is not the policyholder)
 Date & Time

Reporting Centre Personnel's Signature
 Name
 NRIC/FIN No

> Back to OneMotoring

Require PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	138F
Vehicle Details	
Vehicle No.:	SLB8654H
Vehicle to be Exported:	Yes
Intended Deregistration Date:	01 Dec 2021
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8A
Primary Colour:	Silver
Manufacturing Year:	2006
Engine No.:	1ZZ2542489
Chassis No.:	ZNE100301333
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$20,562.00
Original Registration Date:	02 May 2006
First Registration Date:	02 May 2006
Transfer Count:	1
Actual ARF Paid:	\$22,619.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	01 May 2026
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$46,048.00
COE Rebate Amount:	\$20,337.00
Total Rebate Amount:	\$20,337.00

Information contained herein is correct as at 01 Dec 2021

OK