## FINAL COST OF REPAIR

(To be completed for only one type of item)

To:				From:	Ref SAF 122		SAF 122	2 - BB72/PLC/D/014/21.
HD TPT CENTRE EAST, TPTHUBWEST  SELETAR NODE  HD TPT RESOURCE, TPTHUBWEST  RESOURCE SUP IC, TPTHUBWEST  Unit				MOS/33FMD				
Description of Item:	MAN TGM 18.280 4X4				SAF 1222: BB72/PLC/D/014/21.			
Part/Reg No:	MID21720 Original Value:			-	Date:			21.07.2021
Quantity:	01 CE/Non CE:				MO/MR:		D/MR:	8202630002/19385740
Quantity.					Date:			28 July 2021
Description of Damages and Costs of Repairs:					Accident Job No:		No:	8202630002/19385740
					Date:			28 July 2021
S/N Accident Repair  1) Man hour					Man-hours 70.00			
<u>S/N</u> 1)	<u>Materials</u> As on quotation			<u>Unit Price</u> \$581.51	Oty 1		<u>COST</u> \$581.51	
<u>S/N</u> 1)	Assessment fee				COST \$635.81			
<u>S/N</u> 1)	General service				<u>COST</u> \$548.06			
Base/LEO Area Office's Assessment of Damages								
	Labour Charges @ \$79.48 per hour X 70.00  Total Cost of Parts / Materials Used  Sub-contractor  Assessment Fee  Towing Service			_ hrs	= = = =		\$5,563.60 \$581.51 - \$635.81 \$548.06	
Total							\$7,328.98	-
Estimated Time for Repair:							70 Hr	

\*Delete whichever is not applicable FINAL COST OF REPAIR.

ME3 VINCENT TAN

VANCONT