

STRIDES AUTOMOTIVE SERVICES PTE LTD

CRN: 199004280Z

GST Reg No.: MR-8500001-7

2 Tanjong Katong Road #08-01 Tower 3 Paya Lebar Quarter Singapore 437161

Tel: 65 6331 1000

Date: 08 Dec 2021

RE: Breakdown Cost for Invoice No EV211100103

To Whom It May Concern,

Please refer to below table for the breakdown repair cost for Invoice No EV211100103. This repair cost is for MID 41573 accident repair.

Parts Cost

S/N	Part Number	Parts Description	Qty	Unit Price	Qty Total Price	Mark-Up Price	Total Price
1	N/A	Paint material	0.5	\$ 140.00	\$ 70.00	\$ 7.00	\$ 77.00
		Tot	al Spare	Price (Withou	ıt Mark-Up)	\$70.00	
	Mark Up Price				ark Up Price	\$7.00	
	Max Allowable Mark Up Total Spare Price including allowable Mark Up Price					\$100.00	
						\$77.00	

Labour Cost

S/N	Parts Description	Man Hour	Man Hour Rate
Remove & install, weld & panel beat LH rear door dented & punctured areas		8 \$22/4-	
2	To putty & respray on LH rear door	\$32/Hr	
	T	otal Man Hour	12
	Tot	\$384.00	

Towing Cost

S/N	Parts Description	Towing Rate		
1	To provide towing service for above vehicle from Clementi Camp to SMRT Workshop.		\$57.50	
2	To provide towing service for above vehicle from SMRT Workshop to Clementi Camp		\$57.50	
	Tot	al Towing Cost	\$115.00	

Total Repair Cost: \$576.00

Tan Yuwei Manager Fleet Maintenance

Authorised Signature

for STRIDES Automotive Service Pte Ltd