



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

SOMPO INSURANCE SINGAPORE PL	INV No.	AC2108464
50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWER	INV Date	08/12/2021
SINGAPORE 048623	Reference	CS3/SMO21012194/Uuf3e2
	Code	SMO

PROFESSIONAL SERVICE FEE

Vehicle No.	SMN 5165Y
Insured Veh.	FBM 5500Z
Claim No.	CMTD2103538/SYH
Policy No.	D21MTMC01003575
Accident Date	29/11/2021
Inspection Date	01/12/2021

Description	Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	100.00
Parts dismantled before repair as per NIMA Protocol (Photo taking + Transport on 02.12.2021)	10.00
Repaired vehicle before return to claimant as per NIMA Protocol (Photo taking + Transport on 06.12.2021)	10.00
Subtotal	120.00
GST (7%)	8.40
Grand Total	128.40

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

KHM