



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

GREAT AMERICAN INSURANCE COMPANY
3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER
SINGAPORE 039190

Ref: CS/GAI21012199/Utf3e2

Date: 20/12/2021

Code: GAI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBB 7002P	Veh. Inspected	FBJ 8002R
Policy No.		Coverage (\$)	0.00
Claim No.	CLMOMVC000004083	Excess (\$)	0.00
Assign From	SHERY WONG	Assign Date	01/12/2021

2. Vehicle Particulars & Condition

Make & Model	HONDA PCX150	c.c	153
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	MLHKF1280D5130737	Colour	BROWN
Odometer	79037 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	90/90-14	MAXXIS	6 mm
L/H Front Tyre			mm
R/H Rear Tyre	100/90-14	MAXXIS	6 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND N/S FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	27/11/2021	Inspection Date	01/12/2021
Survey held at	EROFIA MOTOR TRADING PTE LTD 1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**