

國際汽車維修 KT MOTORWERK

Blk 3012 Bedok Ind. Park E #01-2020 Singapore 489978.
(Bedok North Ave. 4) Tel: 98287487 Fax: 6448 5177
Email: ktmotorwerk@hotmail.com
Reg. No.: 53373462B

Vehicle Number : SLV9448A
Vehicle Model : KIA K3
Accident Date : 27.11.2021
Original Reg Date : 24.01.2018

Date : 29.11.2021
Chassis : KNAFX411MJ5761166
TP Ins. : AIG

ESTIMATE

1	1 pc	Rear Bumper			783.50	+
2	1 pc	Rear Bumper Side Retainers			75.30	+
3	1 set	Rear Bumper Clips			50.00	+
4	1 pc	Rear Fender RH			1,187.90	+
5	1 pc	Rear Fender Arch Sticker RH			32.00	✓
6	1 pc	Rear Fender inner cowling RH			165.20	+
7	1 pc	Rear w/screen Moulding			126.90	+
8	1 pc	Rear w/screen Inner Seal			60.00	+
9	1 pc	Tailamp RH			398.70	+
10	1 pc	Tailamp inner sealer RH			38.00	+
11	1 pc	Rear Absorber RH			298.60	+
12	1 pc	Rear Wheel Bearing RH			385.20	✓
13	1 pc	Rear Axle			1,126.80	+
14	1 pc	Rear Door RH			876.90	✓
15	2 pcs	Rear Door Black Sticker RH		65.20	130.40	✓
16	1 pc	Rear Door Outer Chrome Moulding RH			129.00	+
17	2 pcs	Rear Door Hinge RH		59.70	119.40	+
18	1 pc	Rear Door Checker RH			75.20	+
19	1 pc	Rear Door Inner Lock RH			356.90	+
20	1 pc	Rear Door w/strip RH			168.90	+
21	1 pc	Rear Door Side Rubber RH			52.00	+
22	1 pc	Rear Door Regulator Motor RH			209.80	+
23	1 pc	Rear Door Regulator Gear RH			467.00	+
24	1 pc	Rear Door Outer Handle RH			185.00	+
25	1 pc	Rear Door Outer Handle cover Rh			65.90	+
26	1 pc	Rear Door Inner Trim RH			658.90	✓
27	1 set	Rear Door Inner Trim Clip			40.00	30
28	1 pc	Rear Door Speaker RH			195.00	+
29	1 pc	Side rocker panel RH			798.60	✓
30	1 pc	Front Door RH			925.00	+
31	1 pc	Front Door Black Sticker RH			53.00	+

2912

2620.80

C/F 10,235.00
less 10% 9,211.50

Special Nett

1	1 pc	Rear w/screen Sealant <i>new</i>	60.00	+
2	1 set	Door Sun Visor <i>new</i>	280.00	60.
3	1 pc	Sport Rim LH <i>cut</i>	750.00	600
4	1 pc	Sport Rim Tyre LH <i>torn</i>	280.00	200.
5	1 set	Body sealant <i>Nec</i>	60.00	✓
6	1 pc	tailamp clips <i>new</i>	30.00	+
7	1 pc	Front No. Plate w/cover <i>new</i>	70.00	+

920

Labour charge

Panel Beating	2,000.00	800.
Spray painting	1,800.00	600.
Check Wiring on tailamp	50.00	+
Anti rust	120.00	60.
Remove and install w/screen	120.00	+
Remove and install Front and Rear Door Part	200.00	80.
Remove and install interior upholstery	150.00	+
Remove and install Rear Under Carriage	350.00	80.
To Check Four Wheel Alignment	120.00	80

\$ 15,651.50

1700

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian King.
L/s 30/11/21.

06 Days.

total: \$240.80

L/s: A.2K.

A.2K.