Our Ref: YP1270A211101	Date: 13/12/2021
Your Ref:	
China Taiping Insurance (Singapore) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Department	
Dear Sir / Madam	
Traffic Accident Along Coast Road Involving YP1270A and XD6460K On 01/11/2021	
We/I, Goldbell Leasing Pte Ltd (NRIC / ROC No: 199001196N), the YP1270A at all material times of the above accident. Ou China Taiping authorized appraiser and we / I based our / my c S\$ 2,800-00 being the repair for 04 Days (Strictly on a With	ur/my vehicle was surveyed by " laims on his recommendation for
We/I have ascertained that you were the insurers of the driver of m/same was involved in the aforesaid accident with our/my m/vehicle	vehicle XD6460K when the YP1270A.
We/I whereby you are the insurers of m/vehicle <u>XD6460K</u> and the by the negligence of your insured and as a result there of our / my m suffered loss and damage as follows:	driver/owner was caused solely /vehicle - <u>YP1270A</u> has
Cost of repairs LOU for pre-repair notice 02 days @ S\$ 140-00 [Box 7545 cc] LOU Fee for04 days @S\$ 140-00 [Box 7545 cc] Rental Fee Invoice No: GIA / LTA search fee Towing Fee (Cash Sale No) Survey Fee	5\$ 1,500.00 280-00 560-00
Total Amount	2,347.45
We/I enclose herewith copies of the supporting documents for vehicl (i) Motor Accident Report & Documents; (ii) Repair Invoices;	e no. YP1270A as follows:-
Kindly look into the matter and let us/me hear from you on the settle as possible.	ement of our/my claims as soon
Please remit us/me your settlement sum in favor of M/s Liu's Broth Forward the cheque to No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @	ner Auto Engineering Workshop. Kaki Bukit Singapore 417883.
Thank you.	
Yours faithfully,	
The owner of m/vehicle YP1270A	

Messers Goldbell Leasing Pte Ltd

cc. Liu's Bro Auto Engineering Workshop



LIU'S BROTHER AUTO ENGINEERING WORKSHOP No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883 ROB No: 53291793. Tel: 67/41-1730 / 731 Email: liusbro@ymail

Invoice/Ref No: YP1270A211101

100 No. 332317930 . 1el. 6741-17307 731 . Email: husbro@ymail.com		1.com	Final Bill			
Customer						
Name: Ch	ina Taiping Insuran	ce (Singapore) Pte Ltd	Date:	13-12-21		
Address Mo	otor Claims Departm	ent	Vehicle No:	YP1270A		
3 A	anson Road #16-00		Model/Make:	Mitsubishi Fuso		
Spi	ringleaf Tower	Singapore 079909	FK62FMZ1	IZ1RDEB		

Item No.	Descriptions Of Parts		Original Quotation / Estimation		Revised Quotation / Cost Of Repair	
1	Rear Lh Powergate Pump 02 pcs (@ S\$1,400-00)	\$	2,800.00		\$	-
2	Powergate Pump Cover 02 pcs (@ S\$260-00)	\$	520.00		\$	-
3	Powergate Panel Support	\$	600.00		\$	
4	Powergate Fluid	\$	120.00		\$	-
	Labor for Replacing Parts Etcs	\$	800.00		\$	-
	To putty & spray painting & including touch up paint on accident affected areas	\$	500.00		\$	-

Total Parts & Labour of estimate for damaged vehicle

Total amount in Lump Sum Basis for repaired vehicle

SDLS: One Thousand Five Hundred Only

\$ 1,500.00

M/s Liu's Bro Auto Engrg Wks



Land Transport Authority 10 Sin Ming Drive Singapore 575701

GST Registration No.: M4-0006529-2

Print Date/Time:

01 Dec 2021 / 08:52:57

Receipt Date/Time:

01 Dec 2021 / 08:52:28

Tax Invoice/Receipt

Receipt No.: ITNET-00000-211201-000407

Previous Receipt No.:

S/N Item Description/ Business Transaction Reference No.		Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - XD6460K As at 01 Nov 2021/13:35:00 Insurance Co: CHINA TAIPING INSURANCE (1 Insurance Enquiry - XD6460K Enquiry Fee 20211201085031657627	SINGAPORE) PTE LTD	7.00	0.49	7.49
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
	Paid By			
	426588XXXXXX1485	eNETS	Credit Card	7.45
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.