



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBH 7071H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	HANDLE BAR	SERVICEABLE	110.00	-
1	HEADLIGHT ASSY	BROKEN	295.00	295.00
1	PAIR HEADLIGHT SIDE COVER	N/S BROKEN	156.00	78.00
1	PAIR FRONT SIGNAL LIGHT	BROKEN	90.00	45.00
1	FRONT STAY	SERVICEABLE	85.00	-
2	FORK ASSY @\$380.00	TO REPAIR SEE LABOUR	760.00	-
1	FORK UNDER BRACKET	SERVICEABLE	185.00	-
1	FRONT FENDER	CUT	185.00	70.00
1	FRONT WHEEL	SERVICEABLE	385.00	-
1	FRONT WHEEL AXLE	SERVICEABLE	45.00	-
1	FUEL TANK COVER COMPLETE	CUT	276.00	276.00
1	AIR SHROUD COVER LH	CUT	86.00	86.00
1	BODY SIDE COVER LH	CUT	46.00	46.00
1	REAR COVER LH	SERVICEABLE	145.00	-
	LESS 10% DISCOUNT		-284.90	-89.60
			2,564.10	806.40
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN)	BENT	20.00	15.00
1	SET STEERING CONE & BEARING (SN)	NECESSARY	120.00	100.00
			140.00	115.00
	<u>LABOUR</u>			
	TOWING FEE.		80.00	50.00
	ALIGN STEERING COMPONENTS		120.00	100.00
	SPRAY PAINTING FOR DAMAGED FENDER & COVERS.		480.00	250.00
	REPAIR & STRAIGHTEN BODY FRAME NECK.	NOT NECESSARY	300.00	-
	RENEW DAMAGED PARTS & REPAIR AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF FORK ASSY.		450.00	200.00
			1,430.00	600.00
	GRAND TOTAL		4,134.10	1,521.40



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,200.00
---	--	--	----------

Report Ref No. CS3/LPC21011217/Guf3e2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.