

ASS. REC. BY:

Steve

REF:

CC4/LPC21012239/ea3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
X	X

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKS 1901 M Yr Regn: 30/3/15Type: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: Mini Cooper S Countryman 1598Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 41919 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WMWZC32010WR77526Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NI / S/Rim / STD A/Rim orTyre Size: F: 225/45R18R: 17BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. 20/11/21 D.O.I. 13/12/21Survey held at Trans EuroCarDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV-66K

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Invs (\$ _____)

☐

: Weekend (\$ _____)

S + RS. SI

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)



EUROKARS HABITAT PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
ESTIMATE COST OF REPAIRS



Lonpac Insurance Bhd 300 Beach Road, #17-04/07, The Concourse Singapore 199555 ATTN. : MOTOR CLAIMS FAX :			NAME :			WIP : 50401		
			ADDRESS :			EXCESS :		
			TEL :			DATE: 1-Dec-21		
VEH NO :	SKS1901M	DATE IN :		CONTACT PERSON :		DEREK	63310684	
CHASSIS NO :	WMWZC32010WR77526	MILEAGE :		TYPE OF CLAIM :		THIRD PARTY		
MODEL :	Cooper S Countryman RHD	DATE REG.:	30-Mar-15	POLICY NO. :				

NATURE OF WORKS								
S/NO	Parts Description			QTY	1ST	SUPP	REVISED	PRICES
1	REAR BUMPER	/	DD	1				\$ 1,067.37
2	SET OF MOUNTS FOR BUMPER	/	MC	1				\$ 61.81
3	CTR SPOILER R60 COOPER S	(chase)	/ cut	1				\$ 334.49
4	REAR BUMPER CENTER BRACKET	?	x nn	1				\$ 149.69
5	GUIDE BUMPER LH	?	x nn	1				\$ 59.87
6	GUIDE BUMPER RH	?	x nn	1				\$ 59.87
7	REAR BUMPER CENTER BRACKET REAR	?	x nn	1				\$ 179.59
8	REAR BUMPER BRACKET	?	x nn	2				\$ 57.08
9	SET OF MOUNTS FOR PDC SENSOR	/	MC	1				\$ 76.96
10	BREATHING COVER	x	nn	1				\$ 30.42
11	VENTILATION COVER	x	nn	1				\$ 47.81
12	NUT	/	MC	9				\$ 13.50
13	PLASTIC CAP	/	MC	4				\$ 4.44
14	BLIND RIVET	/	MC	12				\$ 18.00
15	RIVET	/	MC	2				\$ 1.30
16	REAR BUMPER CENTER BRACKET	?	x nn	1				\$ 451.30
17	LICENSE PLATE LIGHT	?	x nn	2				\$ 62.80
18	REP. COVER LH	x	nn	1				\$ 235.50
19	REP. COVER RH	x	nn	1				\$ 235.50
20				0				\$ -
TOTAL PARTS								\$ 3,147.30
TOTAL PARTS COST								\$ 3,147.30

SUPPLEMENTARY									
NO	DESCRIPTION			QTY	PARTS NO	1st	Supp	REVISED	PRICES
1									
2									
3									
Labour Description									

1	TO REPLACE REAR BUMPER, REINFORCEMENT, LOWER SPOILER & ALL ACCIDENT DAMAGE AREAS. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	840	2,100.00
2	TO RESPRAY REAR BUMPER.	800	1,000.00
3	TO REMOVE & REPLACE THE REAR TAILPIPE EXHAUST.	?	250.00
4	TO TRANSFER THE REVERSE SENSORS.		300.00
5	TO SUPPLY 1 PC NUMBER PLATE WITH CASING.	NETT	70.00
6	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	NETT 150	250.00
7	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	NETT 250	350.00
8	SUNDRIES.	NETT 20	50.00
		TOTAL LABOUR	\$ - \$ 4,370.00
		TOTAL PARTS	\$ - \$ 3,147.30
		TOTAL	\$ - \$ 7,517.30
		LESS EXCESS	\$ - \$ -
		TOTAL AFTER EXCESS	\$ - \$ -
		GST 7%	\$ - \$ -
		GRAND TOTAL	\$ - \$ -

Steve (LKK)
13/12/21, 10.30am

WHL NL
3 dy
PIP
My BL y

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: