

Our Job Ref No : 305496497

Date : 03/12/21

ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : Mr THEVAN

Vehicle Reg No. : SHC2787P CTPL

01/12/2021

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: AIG --- SLT9433C

2. The finalized amount shall be:

(a) Spare Parts after List discount \$758.60

(b) Labour Charges \$620.00

Total for Part-By-Part Repair Cost \$1,378.60

(c) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20%


Final Lumpsum Repair cost

3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : Ms. Loke YY

Tel : 62148355

Fax : 65468156

Signature : 

Name : Thevan

Date : 3/12/21

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHC2787P

Make : HYUNDAI

Model : IONIQ(G3)

Date: 02/12/21

Insurance: AIG

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			YX \$459.40
10	REAR BUMPER CLIPS			nec ✓ \$22.00
1	REAR BUMPER CENTRE MOULDING ASSY			scr ✓ \$451.25
1	REAR BUMPER REINFORCEMENT			SUC X 7. \$394.80 ✓
	SUB TOTAL			\$1,327.45
	LESS 20%			\$265.49
	DISCOUNTED TOTAL			\$1,061.96
1	REAR FENDER ADVERTISEMENT LOGO LH			nec ✓ \$100.00
1	REAR FENDER ADVERTISEMENT LOGO RH			nec ✓ \$100.00
1	REAR BUMPER REVERSE SENSOR			Cut ✓ \$180.00
				\$380.00 ✓
	Labour Charge			
	PANEL BEATING			350 \$400.00
	SPRAY PAINTING CHARGE			250 \$300.00
	REMOVE/REFIX REVERSE SENSOR			20 \$60.00 ✓
	TOTAL LABOUR			\$760.00
	ESTIMATE TOTAL			\$2,201.96

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thuvan@lkhauto.com

82235769

2/12/21 1530

P/P, after berpoint photo
2 days wp ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: