

QUOTATION SUMMARY PAGE 02
 CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$ 1,000.00	250	
TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	\$ 750.00	250	
TO APPLY ANTI-RUST & TUFF KOTE	\$ 95.00	X	
TO PERFORM LIGHTING & WIRING CHECK	\$ 150.00	X	
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING	\$ 120.00	60	
TO PERFORM DIAGNOSTIC CHECK & RESET MEMORY FAULT CODE TO IDENTIFICATION STANDARD	\$ 350.00	X 150	
TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	\$ 280.00	X	710

TOTAL \$ 2,745.00

Adrian Lj
 P/p 03/12/21
 03 Days

ESTIMATE REPORT

TOTAL PARTS COST	:	\$	4,023.50
TOTAL LABOUR COST	:	\$	2,745.00
TOTAL REPAIR COST	:	\$	6,768.50

APPROVED DETAILS

NO. OF REPAIR DAYS : DAYS
 REPAIR UNDER : PART BY PART OR LUMP SUM
 DATE / TIME OF SURVEY :
 SURVEYED BY / FROM :
 CONTACT NUMBER / EMAIL ADD. :
 DATE / TIME OF RE-SURVEY :
 EXCESS :

total: 2746.40
 (P/P)
 total: 2746.40
 (P/P) ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: