



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 ATTN: SALIHA SYED YUSOF		Ref: CS3/AIG21009216/Gtf3n2-1 Date: 27/12/2021 Code: AIG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBK 8166X	Veh. Inspected	SGP 3132R
Policy No.	0999993682	Coverage (\$)	0.00
Claim No.	8382613543SG	Excess (\$)	0.00
Assign From	SALIHA SYED YUSOF	Assign Date	03/12/2021
2. Vehicle Particulars & Condition			
Make & Model	SUBARU FORESTER 2.0 XT	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JF1SJGK85GG069690	Colour	GREY
Odometer	127951 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/55 R18	BRIDGESTONE	6 mm
L/H Front Tyre	225/55 R18	BRIDGESTONE	6 mm
R/H Rear Tyre	225/55 R18	BRIDGESTONE	6 mm
L/H Rear Tyre	225/55 R18	BRIDGESTONE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	30/08/2021	Inspection Date	02/09/2021
Survey held at	MERLIN MOTOR & ENGINEERING WORKS BLK 10 ANG MO KIO INDUSTRIAL PARK 2A #03-13 AMK AUTOPOINT SINGAPORE 568047		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	